LEVEL 2 REPLACEMENT RESERVE REPORT FY 2026 A SAMPLE HIGH RISE

millerdodson Capital Reserve Consultants

LEVEL 2 REPLACEMENT RESERVE REPORT FY 2026 A SAMPLE HIGH RISE



Community Management by:

A SAMPLE MANAGEMENT COMPANY

John Smith,

2661 Riva Rd #1023 Annapolis, MD 21401 555.555.5555 John@SmithMgt.com

Consultant:

millerdodson

Capital Reserve Consultants

2661 Riva Road, Suite 1042 Annapolis, MD 21401 410.268.0479 800.850.2835

MillerDodson.com

INTENTIONALLY LEFT BLANK

REPLACEMENT RESERVE REPORT

A SAMPLE HIGH RISE

ANNAPOLIS, MARYLAND November 11, 2025



Description. A Sample High-Rise is a Condominium, Residential located in Annapolis, Maryland. Constructed in 2010, the community consists of a 42 level High-rise Building containing 496 units. The survey examined the common elements of the property, including:

- Sidewalks
- Fencing, Site Lighting, and Mailbox Clusters
- Waterlines and Sanitary Lines
- Exterior Main Pool and Exterior Spa
- Building Exteriors, Interiors, and Systems

EXECUTIVE SUMMARY

This Reserve Study has been prepared for the A Sample High Rise for the Fiscal Year 2026 covering the period from January 1, 2026 to December 31, 2026. The Replacement Reserves Starting Balance as of January 1, 2026 is proposed to be \$343,247. The reported Current Annual Funding for Reserves is \$54,936. The Recommended Annual Reserve Funding level for 2026 is \$90,356.

The Board has been prudent in increasing the Annual Reserve Funding levels since the last Reserve Study. However, the increase shown above is due primarily to the higher-than-anticipated inflation has escalated costs in all facets of the construction industries.

Section A

Replacement Reserve Analysis

Financial Analysis - A1

General Information - A2

Current Funding - A3

Cash Flow Method Funding - A4 Inflation Adjusted Funding - A5

Comments - A6

Section B

Replacement Reserve Inventory

Replacement Reserve Inventory
General information - B1
Replacement Reserve Inventory
Comments - B2
Schedule of Projected Replacements
and Exclusions - B3

Section C

Projected Annual Replacements

Projected Annual Replacements General Information - C1 Calendar of Projected Annual Replacements - C2

Section D

Condition Assessment

Appendix

Overview, Standard Terms, and Definitions

Video Answers to Frequently Asked Questions MillerDodson welcomes the opportunity to answer questions or to discuss this Reserve Study in more detail should the Board so desire.

Current Funding. The Starting Balance and Current Annual Reserve Funding figures have been supplied by the managing agent and/or Board of Directors. Confirmation or audit of these figures is beyond the scope of the study. For the purposes of this study, it is assumed that the annual contribution will be deposited at the end of each month.

Level of Service. This study has been performed as a Level 2 Update with Site Visit/On-Site Review as defined by the Community Associations Institute's, National Reserve Study Standards. As such, the component inventory is based on the study that was performed by Miller Dodson in FY 2019. This inventory was adjusted to reflect changes provided by the Community Manager and/or the Board of Directors, or adjustments made based on the site visit and visual assessment performed by the Analyst. The analysis, including fund status and funding plan, is developed from the adjusted inventory.

To aid in the understanding of this report and its concepts and practices, on our website, we have developed <u>videos</u> addressing frequently asked topics. In addition, there are posted <u>links</u> covering a variety of subjects under the resources page of our website at <u>millerdodson.com</u>.

Purpose. The purpose of this Replacement Reserve Study is to provide A Sample High Rise (hereinafter called the Association) with an inventory of the common community facilities and infrastructure components that require periodic replacement. The Study includes a general view of the condition of these items and an effective financial plan to fund projected periodic replacements.

- Inventory of Items Owned by the Association. Section B lists the Projected Replacements of the commonly owned items that require periodic replacement using funding from Replacement Reserves. The Replacement Reserve Inventory also provides information about excluded items, which are items whose replacements are not scheduled for funding from Replacement Reserves.
- Condition of Items Owned by the Association. Section B includes our estimates of the normal
 economic life and the remaining economic life for the projected replacements. Section C provides a yearby-year listing of the projected replacements. Section D provides additional detail for items that are unique
 or deserving of attention because of their condition or the manner in which they have been treated in this
 study.
- Financial Plan. The Association has a fiduciary responsibility to protect the appearance, value, and safety of the property and it is therefore essential the Association have a financial plan that provides funding for the projected replacements. In conformance with American Institute of Certified Public Accountant guidelines, Section A, Replacement Reserve Analysis evaluates the current funding of Replacement Reserves as reported by the Association and recommends annual funding of Replacement Reserves by the Cash Flow Method. Section A, Replacement Reserve Analysis includes graphic and tabular presentations of the reported current funding and the recommended funding based on the Cash Flow Method. An Executive Summary of these calculations is provided on Page A1.

Basis. The data contained in this Replacement Reserve Study is based on the following:

- The Request for Proposal submitted and executed by the Association.
- MillerDodson performed a visual evaluation commencing on September 10, 2025 to determine the remaining useful life and replacement cost for the commonly owned elements of this facility.
- This study contains additional recommendations to address inflation for the Cash Flow Method only. For this recommendation, MillerDodson uses the Producers Price Index (PPI), which gauges inflation in manufacturing and construction. Please see page A5 for further details.

To-Scale Drawings. Site and building plans were not used in the development of this study. We recommend the Association assemble and maintain a library of site and building plans of the entire facility. Record drawings should be scanned into an electronic format for safe storage and ease of distribution. Upon request for a nominal fee, MillerDodson can provide scanning services.

Acknowledgment. MillerDodson Associates would like to acknowledge the assistance and input of the Community Manager who provided very helpful insight into the current operations of the property.

Mr. Peter B. Miller, RS, is a Founder and Principal of the firm MillerDodson Associates. Peter is widely recognized as a leading authority in the field of Reserve Studies and Strategic Reserve Planning for Community Associations. He is a graduate of the College of Architecture and Urban Studies at Virginia Tech. As an Architect, Peter began his work with Reserve Studies for community associations during the "condo conversion boom" of the late 1970s. A popular speaker and author on the topic of Reserve Studies, his latest article, "The Reserve Truth, Lessons from the Champlain Towers Incident," was published in the September/October 2021 issue of CAI's Common Ground Magazine. He frequently serves as an Expert Witness in matters concerning Replacement Reserve Studies and Reserve Funding. He has held the professional designation of Reserve Specialist (RS) since 1998.

Analyst's Credentials. Peter served as a Member of the CAI National Board of Trustees from 2018 through 2022. He was the 2020 Chair of CAI's Business Partners Council and is a member of the CAI Foundation for Community Association Research (FCAR). Peter has previously served in leadership positions with several CAI Chapters. He served on the CAI National Reserves Standards Committee from 1997 to 2003 and again in 2016-2017 for the review and updating of the National Standards. Peter currently serves as Co-Chair of the Reserves, Maintenance, and Building Safety Taskforce tasked with updating CAI's National Reserve Study Standards in the wake of the 2021 condominium building tragedy in Florida. He has also served as a Subject Matter consultant for legislation in Maryland, Virginia, and Delaware.

Respectfully Submitted,



Peter Willer
Peter B. Miller, RS

INTENTIONALLY LEFT BLANK


SECTION A - FINANCIAL ANALYSIS

The A Sample High Rise - General Common Elements Replacement Reserve Analysis uses the Cash Flow Method (CFM) to calculate Replacement Reserve funding for the periodic replacement of the 30 Projected Replacements identified in the Replacement Reserve Inventory.

\$90,356 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR THE STUDY YEAR, 2026 \$15.18 Per unit (average), minimum monthly funding of Replacement Reserves

We recommend the Association adopt a Replacement Reserve Funding Plan based on the annual funding recommendation above. Inflation adjusted funding for subsequent years is shown on Page A.5.

A Sample High Rise - General Common Elements reports a Starting Balance of \$343,247 and Annual Funding totaling \$54,936, which is inadequate to fund projected replacements starting in 2065. See Page A.3 for a more detailed evaluation.



The Board has been prudent in increasing the Annual Reserve Funding levels since the last Reserve Study. However, the increase shown above is due primarily to the higher-than-anticipated inflation has escalated costs in all facets of the construction industries.

REPLACEMENT RESERVE ANALYSIS - GENERAL INFORMATION

The A Sample High Rise - General Common Elements Replacement Reserve Analysis calculations of recommended funding of Replacement Reserves by the Cash Flow Method (CFM) and the evaluation of the Current Funding are based upon the same Study Year, Study Period, Beginning Balance, Replacement Reserve Inventory and Level of Service.

2026 STUDY YEAR

The Association reports that their accounting year begins on January 1, and the Study Year, the first year evaluated by the Replacement Reserve Analysis, begins on January 1, 2026.

40 Years | STUDY PERIOD

The Replacement Reserve Analysis evaluates the funding of Replacement Reserves over a 40-year Study Period

\$343,247 STARTING BALANCE


The Association reports Replacement Reserves on Deposit totaling \$343,247 at the start of the Study Year.

Level Two | LEVEL OF SERVICE

The Replacement Reserve Inventory has been developed in compliance with the National Reserve Study Standards for a Level Two Study, as defined by the Community Associations Institute (CAI).

\$3,860,495 | REPLACEMENT RESERVE INVENTORY - PROJECTED REPLACEMENTS

The A Sample High Rise - General Common Elements Replacement Reserve Inventory identifies 30 items that will require periodic replacement, that are to be funded from Replacement Reserves. We estimate the cost of these replacements will be \$3,860,495 over the 40-year Study Period. The Projected Replacements are divided into 4 major categories starting on Page B.3. Pages B.1-B.2 provide detailed information on the Replacement Reserve Inventory.



UPDATING OF THE FUNDING PLAN

The Association has a responsibility to review the Funding Plan annually. The review should include a comparison and evaluation of actual reserve funding with recommended levels shown on Page A.4 and A.5. The Projected Replacements listed on Page C.2 should be compared with any replacements accomplished and funded from Replacement Reserves. Discrepancies should be evaluated and if necessary, the Reserve Study should be updated or a new study commissioned. We recommend annual increases in replacement reserve funding to account for the impact of inflation. Inflation Adjusted Funding is discussed on Page A.5.

UPDATING OF THE REPLACEMENT RESERVE STUDY

At a minimum, the Replacement Reserve Study should be professionally updated every three to five years or after completion of a major replacement project. Updating should also be considered if during the annual review of the Funding Plan, discrepancies are noted between projected and actual reserve funding or replacement costs. Updating may also be necessary if there is a meaningful discrepancy between the actual inflation rate and the inflation rate used for the Inflation Adjusted Funding of Replacement Reserves on Page A.5.

ANNUAL EXPENDITURES AND CURRENT FUNDING

The annual expenditures that comprise the \$3,860,495 of Projected Expenditures over the 40-year Study Period and the impact of the Association continuing to fund Replacement Reserves at the current level are detailed in Table 3.

3 - Table of Annւ	ual Expend	ditures an	d Current	t Funding	Data - Ye	ears 0 thro	ough 39			
Year	2026	2027	2028	2029	2030	2031	2032	2033	2034	203
Starting Balance	\$343,247									
Projected Replacements		(\$24,600)		(\$10,945)	(\$15,500)	(\$14,600)		(\$193,093)		(\$9,600
Annual Deposit	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936
End of Year Balance	\$398,183	\$428,519	\$483,455	\$527,446	\$566,882	\$607,218	\$662,154	\$523,997	\$578,933	\$624,26
Cumulative Expenditures		(\$24,600)	(\$24,600)	(\$35,545)	(\$51,045)	(\$65,645)	(\$65,645)	(\$258,738)	(\$258,738)	(\$268,338
Cumulative Receipts	\$398,183	\$453,119	\$508,055	\$562,991	\$617,927	\$672,863	\$727,799	\$782,735	\$837,671	\$892,60
Year	2036	2037	2038	2039	2040	2041	2042	2043	2044	204
Projected Replacements	(\$15,000)	(\$9,600)	(\$436,360)	(\$27,945)	(\$500)	(\$23,600)	(\$15,000)	(\$160,515)		(\$42,600
Annual Deposit	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936
End of Year Balance	\$664,205	\$709,541	\$328,117	\$355,108	\$409,544	\$440,880	\$480,816	\$375,237	\$430,173	\$442,509
Cumulative Expenditures	(\$283,338)	(\$292,938)	(\$729,298)	(\$757,243)	(\$757,743)	(\$781,343)	(\$796,343)	(\$956,858)	(\$956,858)	(\$999,458
Cumulative Receipts	\$947,543	\$1,002,479	\$1,057,415	\$1,112,351	\$1,167,287	\$1,222,223	\$1,277,159	\$1,332,095	\$1,387,031	\$1,441,96
Year	2046	2047	2048	2049	2050	2051	2052	2053	2054	205
Projected Replacements		(\$9,600)	(\$188,493)	(\$10,945)	(\$84,500)	(\$29,600)		(\$17,100)	(\$17,000)	(\$9,600
Annual Deposit	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,93
End of Year Balance	\$497,445	\$542,781	\$409,224	\$453,215	\$423,651	\$448,987	\$503,923	\$541,759	\$579,695	\$625,03
Cumulative Expenditures	(\$999,458)	(\$1,009,058)	(\$1,197,551)	(\$1,208,496)	(\$1,292,996)	(\$1,322,596)	(\$1,322,596)	(\$1,339,696)	(\$1,356,696)	(\$1,366,296
Cumulative Receipts	\$1,496,903	\$1,551,839	\$1,606,775	\$1,661,711	\$1,716,647	\$1,771,583	\$1,826,519	\$1,881,455	\$1,936,391	\$1,991,32
Year	2056	2057	2058	2059	2060	2061	2062	2063	2064	206
Projected Replacements		(\$24,600)	(\$470,860)	(\$10,945)	(\$15,500)	(\$164,600)		(\$193,093)		(\$1,614,600
Annual Deposit	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936	\$54,936
End of Year Balance	\$679,967	\$710,303	\$294,379	\$338,370	\$377,806	\$268,142	\$323,078	\$184,920	\$239,856	(\$1,319,808
Cumulative Expenditures	(\$1,366,296)	(\$1,390,896)	(\$1,861,756)	(\$1,872,701)	(\$1,888,201)	(\$2,052,801)	(\$2,052,801)	(\$2,245,895)	(\$2,245,895)	(\$3,860,49
Cumulative Receipts	\$2,046,263	\$2,101,199	\$2,156,135	\$2,211,071	\$2,266,007	\$2,320,943	\$2,375,879	\$2,430,815	\$2,485,751	\$2,540,68

EVALUATION OF CURRENT FUNDING

The evaluation of Current Funding (Starting Balance of \$343,247 & annual funding of \$54,936), is done in today's dollars with no adjustments for inflation or interest earned on Replacement Reserves. The evaluation assumes Replacement Reserves will only be used for the 30 Projected Replacements identified in the Replacement Reserve Inventory and that the Association will continue Annual Funding of \$54,936 throughout the 40-year Study Period.

Annual Funding of \$54,936 is approximately 61 percent of the \$90,356 recommended Annual Funding calculated by the Cash Flow Method for 2026, the Study Year.

See the Executive Summary for the Current Funding Statement.


CASH FLOW METHOD FUNDING

\$90,356 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR 2026

\$15.18 Per unit (average), minimum monthly funding of Replacement Reserves

Recommended Replacement Reserve Funding has been calculated using the Cash Flow Method (also called the Straight Line or Threshold Method). This method calculates a constant annual funding between peaks in cumulative expenditures, while maintaining a Minimum Balance (threshold) in the Peak Years.

- **Peak Years.** The First Peak Year occurs in 2065 with Replacement Reserves on Deposit dropping to the Minimum Balance after the completion of \$3,860,495 of replacements from 2026 to 2065. Recommended funding is anticipated to decline in 2066. Peak Years are identified in Chart 4 and Table 5.
- Threshold (Minimum Balance). The calculations assume a Minimum Balance of \$97,000 will always be held in reserve, which is calculated by rounding the 12-month 40-year average annual expenditure of \$96,512 as shown on Graph #2.
- Cash Flow Method Study Period. Cash Flow Method calculates funding for \$3,860,495 of expenditures over the 40-year Study Period. It does not include funding for any projects beyond 2065 and in 2065, the end of year balance will always be the Minimum Balance.



INFLATION ADJUSTED FUNDING

The Cash Flow Method calculations on Page A4 have been done in today's dollars with no adjustment for inflation. At MillerDodson, we believe that long-term inflation forecasting is effective at demonstrating the power of compounding, not at calculating appropriate funding levels for Replacement Reserves. We have developed this proprietary model to estimate the short-term impact of inflation on Replacement Reserve funding.

\$90,356 2026 - CASH FLOW METHOD RECOMMENDED FUNDING

The 2026 Study Year calculations have been made using current replacement costs \$95,778 2027 - 6.0% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2027 funding based on three assumptions:

- Starting Balance totaling \$433,603 on January 1, 2027.
- 2027 Non-inflation replacement costs listed in Section C, \$24,600, will be replaced at approximately \$26,076, 6.00% compounded inflation increase to 2026 costs.
- The \$95,778 inflation-adjusted funding in 2027 is a 6.0% increase over the non-inflation-adjusted funding of \$90,356.

\$101,524 | 2028 - 6.0% INFLATION ADJUSTED FUNDING


A new analysis calculates the 2028 funding based on three assumptions:

- Starting balance of approximately \$503,305 = 2028 Starting Balance \$433,603, plus Inflation Adjusted Funding \$95,778 for 2027, minus \$26,076 2027 Inflation Adjusted Cost.
- No Expenditures from Replacement Reserves in 2028.

\$107,614 | 2029 - 6.0% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2029 funding based on three assumptions:

- Starting balance of approximately \$604,829 = 2029 Starting Balance \$503,305, plus Inflation Adjusted Funding \$101,524 for 2028, minus \$0 2028 Inflation Adjusted Cost.
- 2029 Non-inflation replacement costs listed in Section C, \$10,945, will be replaced at approximately \$13,036, 6.0% compounded inflation increase to 2026 costs.
- The \$107,614 inflation-adjusted funding in 2029 is a 6.0% increase over the non-inflation-adjusted funding of \$101,524 for 2028.



Year Four and Beyond

The inflation-adjusted funding calculations outlined above are not intended to be a substitute for periodic evaluation of common elements by an experienced Reserve Analyst. Industry Standards, lender requirements, and many state and local statutes require a Replacement Reserve Study to be professionally updated every 3 to 5 years.

Inflation Adjustment

Prior to approving a budget based upon the 2027, 2028 and 2029 inflation-adjusted funding calculations above, the 6.00 percent base rate of inflation used in our calculations should be compared to rates published by the Bureau of Labor Statistics. If there is a significant discrepancy (over 1 percentage point), contact MillerDodson Associates prior to using the Inflation Adjusted Funding.

Interest on Reserves

The recommended funding calculations do not account for interest earned on Replacement Reserves. In 2026, based on a 1.00 percent interest rate, we estimate the Association may earn \$3,884 on an average balance of \$388,425, \$4,685 on an average balance of \$468,454 in 2027, and \$5,541 on \$554,067 in 2028. The Association may elect to attribute 100 percent of the earned interest to Reserves, resulting in a reduction in the 2026 funding from \$90,356 to \$86,472 (a 4.29 percent reduction), \$95,778 to \$91,093 in 2027 (a 4.89 percent reduction), and \$101,524 to \$95,984 in 2028 (a 5.45 percent reduction).

REPLACEMENT RESERVE STUDY - SUPPLEMENTAL COMMENTS

Maryland's new Reserves and Reserve Study Law, HB-107, is intended to ensure that adequate Reserve Funding is available for capital repair and replacement projects when it is needed. This is done by funding the Reserve Fund annually. The law requires that the Recommended Annual Reserve Funding amount in the most recent Reserve Study be included in the Association's annual budgets. If this is an Association's "initial" (first) professionally conducted Reserve Study, HB-107 gives the Association up to three (3) fiscal years following the fiscal year in which the Reserve Study was completed, to attain the Annual Reserve Funding level recommended in the initial Reserve Study.

SECTION B - REPLACEMENT RESERVE INVENTORY

• **PROJECTED REPLACEMENTS.** A Sample High Rise - General Common Elements - Replacement Reserve Inventory identifies 30 items that are Projected Replacements and the periodic replacements of these items are scheduled for funding from Replacement Reserves. The Projected Replacements have an estimated one-time replacement cost of \$2,684,213. Cumulative Replacements totaling \$3,860,495 are scheduled in the Replacement Reserve Inventory over the 40-year Study Period. Cumulative Replacements include those components that are replaced more than once during the period of the study.

Projected Replacements are the replacement of commonly-owned physical assets that require periodic replacement and whose replacement is to be funded from Replacement Reserves.

- **TAX CODE.** The United States Tax Code grants favorable tax status to Replacement Reserves, conditioned on expenditures being made within certain guidelines. These guidelines typically exclude maintenance activities, minor repairs, and capital improvements.
- **EXCLUDED ITEMS.** Some of the items contained in the Replacement Reserve Inventory are 'Excluded Items'. Multiple categories of items are typically excluded from funding by Replacement Reserves, including but not limited to:

Value. Items with a replacement cost of less than \$1000 and/or a normal economic life of less than 3 years are typically excluded from funding from Replacement Reserves. This exclusion should reflect the Association policy on the administration of Replacement Reserves. If the Association has selected an alternative level, it will be noted in the Replacement Reserve Inventory - General Comments on Page B.2.

Long-lived Items. Items are excluded from the Replacement Reserve Inventory when items are properly maintained and are assumed to have a life equal to the property.

Unit Improvements. Items owned by a single unit and where the items serve a single unit are generally assumed to be the responsibility of that unit, not the Association.

Other Non-Common Improvements. Items owned by the local government, public and private utility companies, the United States Postal Service, Master Associations, state and local highway authorities, etc., may be installed on property that is owned by the Association. These types of items are generally not the responsibility of the Association and are excluded from the Replacement Reserve Inventory.

- **CATEGORIES.** The 30 items included in the A Sample High Rise General Common Elements Replacement Reserve Inventory are divided into 4 major categories. Each category is printed on a separate page, beginning on page B.3.
- **LEVEL OF SERVICE.** This Replacement Reserve Inventory has been developed in compliance with the standards established for a Level 2 Update, as defined by the National Reserve Study Standards, established in 1998 by the Community Associations Institute, which states:

This study has been performed as a Level 2 Update with Site Visit/On-Site Review as defined by the Community Associations Institute's, National Reserve Study Standards. As such, the component inventory is based on the study that was performed by Miller Dodson in FY 2019. This inventory was adjusted to reflect changes provided by the Community Manager and/or the Board of Directors, or adjustments made based on the site visit and visual assessment performed by the Analyst. The analysis, including fund status and funding plan, is developed from the adjusted inventory.

REPLACEMENT RESERVE INVENTORY - GENERAL INFORMATION (CONT'D)

 INVENTORY DATA. Each of the 30 Projected Replacements listed in the Replacement Reserve Inventory includes the following data:

Item Number. The Item Number is assigned sequentially and is intended for identification purposes only.

Item Description. We have identified each item included in the Inventory. Additional information may be included in the Comments section at the bottom of each page of the Inventory.

Units. We have used standard abbreviations to identify the number of units including SF-square feet, LF-lineal feet, SY-square yard, LS-lump sum, EA-each, and PR-pair. Non-standard abbreviations are noted in the Comments section at the bottom of the page.

Number of Units. The methods used to develop the quantities are discussed in "Level of Service" above.

Unit Replacement Cost. We use four sources to develop the unit cost data shown in the Inventory; actual replacement cost data provided by the client, information provided by local contractors and suppliers, industry standard estimating manuals, and a cost database we have developed based upon our detailed interviews with contractors and service providers who are specialists in their respective lines of work.

Normal Economic Life (Years). The number of years that a new and properly installed item should be expected to remain in service.

Remaining Economic Life (Years). The estimated number of years before an item will need to be replaced. In "normal" conditions, this could be calculated by subtracting the age of the item from the Normal Economic Life of the item, but only rarely do physical assets age "normally". Some items may have longer or shorter lives depending on many factors such as environment, initial quality of the item, maintenance, etc.

Total Replacement Cost. This is calculated by multiplying the Unit Replacement Cost by the Number of Units.

- **PARTIAL FUNDING.** Items may have been included in the Replacement Reserve Inventory at less than 100 percent of their full quantity and/or replacement cost. This is done on items that will never be replaced in their entirety, but which may require periodic replacements over an extended period of time. The assumptions that provide the basis for any partial funding are noted in the Comments section.
- **REMAINING ECONOMIC LIFE GREATER THAN 40 YEARS.** The calculations do not include funding for initial replacements beyond 40 years. These replacements are included in this Study for tracking and evaluation. They should be included for funding in future Studies, when they enter the 40-year window.
- ACCURACY OF THE ANALYSIS. The accuracy of the Replacement Reserve Analysis is dependent upon expenditures from Replacement Reserves being made ONLY for the 30 Projected Replacements specifically listed in the Replacement Reserve Inventory. The inclusion/exclusion of items from the Replacement Reserve Inventory is discussed on Page B.1.

SITE I	TEMS TED REPLACEMENTS				NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)				
ITEM I	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)		
1	Concrete sealant - entry drive (1st lvl)	sf	5,380	\$0.25	10	3	\$1,345		
	Concrete flatwork (6%)						EXCLUDED		
			Rep	lacement Costs -	Page S	ubtotal	\$1,345		

COMMENTS

- Concrete flatwork (6%) [12/28/2020] excluded per board

	ERIOR ITEMS COTED REPLACEMENTS				Economic Life (yrs) Economic Life (yrs)		
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
2	Roof, EPDM	sf	20,230	\$19.00	20	12	\$384,370
3	Glass curtainwall replacement (0.05%)	sf	116	\$50.00	2	1	\$5,800
4	Glass curtainwall replacement (1.5%)	sf	38	\$100.00	2	1	\$3,800
5	Decorative metal panels - seal replacement	sf	17,696	\$5.25	15	7	\$92,904
6	FRC panels - seal replacement	sf	6,392	\$6.35	15	7	\$40,589
7	Main entrance doors	pr	8	\$2,580.00	25	17	\$20,640
8	Exterior doors, glass and aluminum	ea	6	\$1,500.00	25	15	\$9,000
9	Exterior doors, metal, sgl	ea	96	\$900.00	25	17	\$86,400
10	Exterior doors, metal, dbl	ea	5	\$1,250.00	25	17	\$6,250
11	Overhead door with opener	ea	2	\$11,520.00	20	12	\$23,040
12	Overhead door with opener - large	ea	1	\$18,000.00	20	19	\$18,000
13	Lighting, exterior	ea	22	\$225.00	20	12	\$4,950
14	Lights, artwork, colored w/controls	ls	1	\$5,000.00	10	5	\$5,000

Replacement Costs - Page Subtotal \$700,743

COMMENTS

• Item #3: Glass curtainwall replacement (0.05%) - Model for the glass curtain wall assumes 1/2% of the window system will fail and be replaced every 5 years. Maintenanceteam should keep track of each failed window system so the actual replacements can be tracked against this model andmodel can be adjusted accordingly.

A Sample High Rise - General Common Elements

TEM	ITEM	LINUT	NUMBER	UNIT REPLACEMENT	NE	551	REPLACEME
#	DESCRIPTION	UNIT	OF UNITS	COST (\$)	NEL	REL	COST
15	Lobby tile floor tuckpoint (5%)	sf	100	\$5.00	10	4	\$50
16	Lobby tile floor replace	sf	2,000	\$42.00	30	24	\$84,000
17	Bathroom renovation, 1st floor lobby	Is	1	\$6,500.00	20	12	\$6,50
18	Lighting, general fixtures	ea	49	\$125.00	25	17	\$6,12
19	Lighting, interior	ea	40	\$250.00	20	12	\$10,00

Replacement Costs - Page Subtotal	\$107,125

COMMENTS

A Sample High Rise - General Common Elements

November 11, 2025

	DING SYSTEMS - MECHANICAL SYSTEMS CTED REPLACEMENTS				NE REL-	NEL- Normal Economic Life (yrs			
ГЕМ #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEME COST		
20	Fire pump, 250 hp	ea	1	\$31,500.00	40	32	\$31,50		
21	Fire pump controller	ls	1	\$10,500.00	40	32	\$10,50		
22	Dry sprinkler system compressor	ea	1	\$5,000.00	30	22	\$5,00		
23	Sprinkler heads	ea	6,720	\$225.00	50	39	\$1,512,00		

COMMENTS	

Replacement Costs - Page Subtotal

\$1,559,000

MillerDodson Associates, Inc.
A Sample High Rise - General Common Elements

	DING SYSTEMS - ELECTRICAL SYSTEMS CTED REPLACEMENTS						Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
24	Primary switchgear	ls	1	\$75,000.00	50	39	\$75,000
25	Fire panel	ls	1	\$31,500.00	25	17	\$31,500
26	Security system	ls	1	\$35,000.00	15	7	\$35,000
27	Video camera system	ls	1	\$15,000.00	3	1	\$15,000
28	Generator, whole building	ea	1	\$150,000.00	45	35	\$150,000
29	Electric meter, control system (billing)	ls	1	\$7,500.00	15	12	\$7,500
30	Water meter, control system (billing)	ls	1	\$2,000.00	15	13	\$2,000
			Rep	placement Costs -	Page :	Subtotal	\$316,000

COMMENTS

VALU	IATION EXCLUSIONS d Items						
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
#	Property identification signage	ONII	OF UNITS	CO31 (\$)	NEL	KEL	EXCLUDED
	Miscellaneous signage						EXCLUDED
	House bid						EXCLUDED
	Fire extinguisher cabinet						EXCLUDED
	Signage						EXCLUDED

VALUATION EXCLUSIONS

- Valuation Exclusions. For ease of administration of the Replacement Reserves and to reflect accurately how Replacement Reserves are administered, items with a dollar value less than \$1000 have not been scheduled for funding from Replacement Reserve. Examples of items excluded by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

LONG-LIFE I	EXCLUSIONS						
ITEM ITEM # DESCRIPTION	ani	JNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
	g foundation(s)	INIC	OF UNITS	CO31 (\$)	INEL	KEL	EXCLUDED
Concre	ete floor slabs (interior)						EXCLUDED
Wall, f	oor, and roof structure						EXCLUDED
	on element electrical services						EXCLUDED
	cal wiring						EXCLUDED
	piping at common facilities						EXCLUDED
	piping at common facilities						EXCLUDED
Gas se	ervices at common facilities						EXCLUDED

LONG-LIFE EXCLUSIONS

- Long Life Exclusions. Components that when properly maintained, can be assumed to have a life equal to the property as a whole, are normally excluded from the Replacement Reserve Inventory. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- Exterior masonry is generally assumed to have an unlimited economic life, but periodic repointing is required, and we have included this for funding in the Replacement Reserve Inventory.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

UNIT IMPROVEMENTS EXCLUSIONS Excluded Items						
ITEM ITEM # DESCRIPTION	LINIT	NUMBER	UNIT REPLACEMENT	NEI	BEI	REPLACEMENT
Building interior above the 1st floor Sanitary sewers serving one unit Electrical wiring serving one unit Cable TV service serving one unit Telephone service serving one unit Gas service serving one unit Unit interior	UNIT	OF UNITS	COST(\$)	NEL	REL	EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED

UNIT IMPROVEMENTS EXCLUSIONS

- Unit improvement Exclusions. We understand that the elements of the project that relate to a single unit are the responsibility of that unit owner. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

UTILITY EXCLUSIONS Excluded Items					
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL REL	REPLACEMENT COST (\$)
Cable TV systems and structures	Oltri	OI OIIIIO	σσστ (ψ)	NEL NEL	EXCLUDED
Telephone cables and structures					EXCLUDED
Gas mains and meters					EXCLUDED
Water mains and meters					EXCLUDED

UTILITY EXCLUSIONS

- Utility Exclusions. Many improvements owned by utility companies are on property owned by the Association. We have assumed that repair, maintenance, and replacements of these components will be done at the expense of the appropriate utility company. Examples of items excluded from funding Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

MAIN' Exclude	TENANCE AND REPAIR EXCLUSIONS					
ITEM			NUMBER	UNIT REPLACEMENT		REPLACEMEN'
#	ITEM DESCRIPTION	UNIT	OF UNITS	COST (\$)	NEL	REL COST (\$
	Janitorial service					EXCLUDED
	Repair services					EXCLUDED
	Partial replacements					EXCLUDED
	Capital improvements					EXCLUDED

MAINTENANCE AND REPAIR EXCLUSIONS

- Maintenance activities, one-time-only repairs, and capital improvements. These activities are NOT appropriately funded from Replacement Reserves. The inclusion of such component in the Replacement Reserve Inventory could jeopardize the special tax status of ALL Replacement Reserves, exposing the Association to significant tax liabilities. We recommend that the Board of Directors discuss these exclusions and Revenue Ruling 75-370 with a Certified Public Accountant.
- Examples of items excluded from funding by Replacement Reserves are listed above. The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

INTENTIONALLY LEFT BLANK

SECTION C - CALENDAR OF PROJECTED ANNUAL REPLACEMENTS

GENERAL STATEMENT. The 30 Projected Replacements in the A Sample High Rise - General Common Elements Replacement Reserve Inventory whose replacement is scheduled to be funded from Replacement Reserves are broken down on a year-by-year basis, beginning on Page C.2.

REPLACEMENT RESERVE ANALYSIS AND INVENTORY POLICIES, PROCEDURES, AND ADMINISTRATION

- **REVIEW OF THE REPLACEMENT RESERVE STUDY.** For this study to be effective, it should be reviewed by the Board of Directors, those responsible for the management of the items included in the Replacement Reserve Inventory, and the accounting professionals employed by the Association.
- **REVISIONS.** Revisions will be made to the Replacement Reserve Analysis and Replacement Reserve Inventory in accordance with the written instructions of the Board of Directors. No additional charge is incurred for the <u>first</u> revision if requested in writing within three months of the date of the Replacement Reserve Study. It is our policy to provide revisions in electronic (Adobe PDF) format only. We acknowledge that there are instances in which multiple revisions are necessary. However, unnecessary multiple revisions drain our time and manpower resources. Therefore, MillerDodson will exercise its sole discretion as to whether additional charges are incurred.
- TAX CODE. The United States Tax Code grants favorable tax status to a common interest development (CID) meeting certain guidelines for their Replacement Reserve. If a CID files their taxes as a 'Corporation' on Form 1120 (IRC Section 277), these guidelines typically require maintenance activities, partial replacements, minor replacements, capital improvements, and one-time-only replacements to be excluded from Reserves. A CID cannot co-mingle planning for maintenance activities with capital replacement activities in the Reserves (Revenue Ruling 75-370). Funds for maintenance activities and capital replacement activities must be held in separate accounts. If a CID files taxes as an "Exempt Homeowners Association" using Form 1120H (IRC Section 528), the CID does not have to segregate these activities. However, because the CID may elect to change their method of filing from year to year within the Study Period, we advise using the more restrictive approach. We further recommend that the CID consult with their Accountant and consider creating separate and independent accounts and reserves for large maintenance items, such as painting.
- CONFLICT OF INTEREST. Neither MillerDodson Associates nor the Reserve Analyst has any prior or existing
 relationship with this Association which would represent a real or perceived conflict of interest.
- **RELIANCE ON DATA PROVIDED BY THE CLIENT.** Information provided by an official representative of the Association regarding financial, physical conditions, quality, or historical issues is deemed reliable.
- **INTENT.** This Replacement Reserve Study is a reflection of the information provided by the Association and the visual evaluations of the Analyst. It has been prepared for the sole use of the Association and is not for the purpose of performing an audit, quality/forensic analyses, or background checks of historical records.
- **PREVIOUS REPLACEMENTS.** Information provided to MillerDodson Associates regarding prior replacements is considered to be accurate and reliable. Our visual evaluation is not a project audit or quality inspection.
- EXPERIENCE WITH FUTURE REPLACEMENTS. The Calendar of Annual Projected Replacements, lists replacements we have projected to occur over the Study Period and begins on Page C2. Actual experience in replacing the items may differ significantly from the cost estimates and time frames shown because of conditions beyond our control. These differences may be caused by maintenance practices, inflation, variations in pricing and market conditions, future technological developments, regulatory actions, acts of God, and luck. Some items may function normally during our visual evaluation and then fail without notice.

PRO	JECTED RI	EPLACEMENTS	
Item 2026 - Study Year	\$	Item 2027 - YEAR 1 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 27 Video camera system	\$ \$5,800 \$3,800 \$15,000
No Scheduled Replacements		Total Scheduled Replacements	\$24,600
Item 2028 - YEAR 2	\$	1 Concrete sealant - entry drive (1st lvl) 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%)	\$ \$1,345 \$5,800 \$3,800
No Scheduled Replacements		Total Scheduled Replacements	\$10,945
Item 2030 - YEAR 4 15 Lobby tile floor tuckpoint (5%) 27 Video camera system	\$ \$500 \$15,000	Item 2031 - YEAR 5 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 14 Lights, artwork, colored w/controls	\$ \$5,800 \$3,800 \$5,000
Total Scheduled Replacements	\$15,500	Total Scheduled Replacements	\$14,600
Item 2032 - YEAR 6	\$	Item 2033 - YEAR 7 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements	\$5,800 \$3,800 \$92,904 \$40,589 \$35,000 \$15,000

	F	PROJECTED R	EPLA	CEMENTS	
Item	2034 - YEAR 8	\$	3 4	2035 - YEAR 9 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%)	\$ \$5,800 \$3,800
No Scheduled Replaceme	nts		Total S	Scheduled Replacements	\$9,600
Item 27 Video camera sys	2036 - YEAR 10 tem	\$ \$15,000	1tem 3 4	2037 - YEAR 11 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%)	\$ \$5,800 \$3,800
Total Scheduled Replacen	nents	\$15,000	Total S	Scheduled Replacements	\$9,600
19 Lighting, interior	2038 - YEAR 12 th opener tion, 1st floor lobby ntrol system (billing)	\$ \$384,370 \$23,040 \$4,950 \$6,500 \$10,000 \$7,500	1 ttem 1 3 4 27 30	2039 - YEAR 13 Concrete sealant - entry drive (1st IvI) Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%) Video camera system Water meter, control system (billing)	\$ \$1,345 \$5,800 \$3,800 \$15,000 \$2,000
Total Scheduled Replacen		\$436,360		Scheduled Replacements	\$27,945
Item 15 Lobby tile floor tud Total Scheduled Replacen		\$ \$500 \$500	3 4 8 14 Total S	2041 - YEAR 15 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%) Exterior doors, glass and aluminum Lights, artwork, colored w/controls	\$ \$5,800 \$3,800 \$9,000 \$5,000

3 Glass cutriamwall replacement (0.05%) State State	PF	ROJECTED R	EPLACEMENTS	
Item 2044 - YEAR 18			3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 7 Main entrance doors 9 Exterior doors, metal, sgl 10 Exterior doors, metal, dbl 18 Lighting, general fixtures	\$ \$5,800 \$3,800 \$20,640 \$86,400 \$6,250 \$6,125 \$31,500
No Scheduled Replacements	Total Scheduled Replacements	\$15,000	Total Scheduled Replacements	\$160,515
Item 2046 - YEAR 20	Item 2044 - YEAR 18	\$	3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large	\$ \$5,800 \$3,800 \$18,000 \$15,000
No Scheduled Replacements Total Scheduled Replacement (1.5%)	No Scheduled Replacements		Total Scheduled Replacements	\$42,600
Item2048 - YEAR 22\$ Item2049 - YEAR 235Decorative metal panels - seal replacement\$92,9041 Concrete sealant - entry drive (1st IvI)6FRC panels - seal replacement\$40,5893 Glass curtainwall replacement (0.05%)22Dry sprinkler system compressor\$5,0004 Glass curtainwall replacement (1.5%)26Security system\$35,000	Item 2046 - YEAR 20	\$	3 Glass curtainwall replacement (0.05%)	\$ \$5,800 \$3,800
5 Decorative metal panels - seal replacement \$92,904 6 FRC panels - seal replacement \$40,589 22 Dry sprinkler system compressor \$5,000 26 Security system \$35,000	No Scheduled Replacements		Total Scheduled Replacements	\$9,600
Total Scheduled Replacements \$188,493 Total Scheduled Replacements \$	5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 22 Dry sprinkler system compressor 26 Security system 27 Video camera system	\$92,904 \$40,589 \$5,000 \$35,000 \$15,000	Concrete sealant - entry drive (1st IvI) Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%)	\$ \$1,345 \$5,800 \$3,800

	PROJECTED R	EPLA(CEMENTS	
Item 2050 - YEAR 24 15 Lobby tile floor tuckpoint (5%) 16 Lobby tile floor replace	\$ \$500 \$84,000	1tem 3 4 14 27	2051 - YEAR 25 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%) Lights, artwork, colored w/controls Video camera system	\$ \$5,800 \$3,800 \$5,000 \$15,000
Total Scheduled Replacements	\$84,500	Total S	Scheduled Replacements	\$29,600
Item 2052 - YEAR 26	\$	1tem 3 4 29	2053 - YEAR 27 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%) Electric meter, control system (billing)	\$ \$5,800 \$3,800 \$7,500
No Scheduled Replacements		Total S	Scheduled Replacements	\$17,100
Item 2054 - YEAR 28 27 Video camera system 30 Water meter, control system (billing)	\$ \$15,000 \$2,000	3 4	2055 - YEAR 29 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%)	\$ \$5,800 \$3,800
Total Scheduled Replacements	\$17,000		Scheduled Replacements	\$9,600
Item 2056 - YEAR 30 No Scheduled Replacements	\$	1tem 3 4 27	2057 - YEAR 31 Glass curtainwall replacement (0.05%) Glass curtainwall replacement (1.5%) Video camera system	\$ \$5,800 \$3,800 \$15,000

Bern				
13 Lighting, oxforce	Item 2058 - YI		Item 2059 - YEAR 33	\$
13 Lighting, exterior \$4,950 4 Glass curtainwall replacement (1,5%) \$3,800 10 Lighting, inferior \$110,000 \$15,000 21 File pump, controller \$10,500 22 File pump controller \$10,500 23 File pump controller \$10,500 24 Total Scheduled Replacements \$470,860 Total Scheduled Replacement (1,5%) \$3,800 25 Video camera system \$15,000 \$15,000 \$3,800 \$4,00			II	
17 Bathworn removaline, 1st floor totally \$10,000	The state of the s		i : : : : : : : : : : : : : : : : : : :	
19			4 Glass curtainwall replacement (1.5%)	\$3,800
20 Fire pump controller				
Total Scheduled Replacements	5 G.			
Total Scheduled Replacements	• • • • • • • • • • • • • • • • • • •			
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$	21 File pump controller	\$10,500		
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$				
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$				
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$				
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$				
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$				
Item 2060 - YEAR 34 \$ 15 Lobby tile floor tuckpoint (5%) \$ \$ \$ \$ \$ \$ \$ \$ \$		A.770.000		440.045
15	Total Scheduled Replacements	\$470,860	Total Scheduled Replacements	\$10,945
27 Video camera system	Item 2060 - Y	EAR 34 \$	Item 2061 - YEAR 35	\$
14	15 Lobby tile floor tuckpoint (5%		3 Glass curtainwall replacement (0.05%)	\$5,800
Total Scheduled Replacements	27 Video camera system	\$15,000	II ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	
Total Scheduled Replacements			1	
Item 2062 - YEAR 36			28 Generator, whole building	\$150,000
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36				
Item 2062 - YEAR 36		445.500		****
No Scheduled Replacements Total Scheduled Replacement (1.05%) \$5,800	Total Scheduled Replacements	\$15,500	Total Scheduled Replacements	\$164,600
A Glass curtainwall replacement (1.5%) \$3,800	Item 2062 - YI	EAR 36 \$		
No Scheduled Replacements \$92,904			3 Glass curtainwall replacement (0.05%)	ሲር ዐ ርር
No Scheduled Replacements			11	
26 Security system \$35,000			4 Glass curtainwall replacement (1.5%)	\$3,800
No Scheduled Replacements			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement	\$3,800 \$92,904
Total Scheduled Replacements \$193,093			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement	\$3,800 \$92,904 \$40,589
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
Item 2064 - YEAR 38			4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system	\$3,800 \$92,904 \$40,589 \$35,000
3 Glass curtainwall replacement (0.05%) \$5,800 4 Glass curtainwall replacement (1.5%) \$3,800 12 Overhead door with opener - large \$18,000 23 Sprinkler heads \$1,512,000 24 Primary switchgear \$75,000	No Cohodulad Danisaamaata		4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000
4 Glass curtainwall replacement (1.5%) \$3,800 12 Overhead door with opener - large \$18,000 23 Sprinkler heads \$1,512,000 24 Primary switchgear \$75,000	No Scheduled Replacements		4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000
12 Overhead door with opener - large \$18,000 23 Sprinkler heads \$1,512,000 24 Primary switchgear \$75,000	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000
23 Sprinkler heads \$1,512,000 24 Primary switchgear \$75,000	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%)	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$193,093
24 Primary switchgear \$75,000	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%)	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$193,093 \$ \$5,800 \$3,800
	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$15,000 \$18,000 \$18,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements Total Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
No Scheduled Replacements \$1,614,600	·	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,500 \$3,800 \$1,512,000
	Item 2064 - YI	EAR 38 \$	4 Glass curtainwall replacement (1.5%) 5 Decorative metal panels - seal replacement 6 FRC panels - seal replacement 26 Security system 27 Video camera system Total Scheduled Replacements Item 2065 - YEAR 39 3 Glass curtainwall replacement (0.05%) 4 Glass curtainwall replacement (1.5%) 12 Overhead door with opener - large 23 Sprinkler heads 24 Primary switchgear	\$3,800 \$92,904 \$40,589 \$35,000 \$15,000 \$15,000 \$1,512,000 \$1,512,000 \$75,000

SECTION D - CONDITION ASSESSMENT

General Comments. MillerDodson Associates conducted a Reserve Study at A Sample High-Rise - General Common Elements in December 2020. A Sample High-Rise - General Common Elements is in generally excellent condition for a residential condominium constructed between 2008-2010. A review of the Replacement Reserve Inventory will show that we are anticipating most of the components achieving their normal economic lives.

General Common Element (GCE) - This area picks up both the owners of residential units and the commercial properties on the first floor. Included are the entire exterior envelope, glass skin, roof, and exterior doors on the first floor. Also included are the fire suppression and detection systems, security system, and the main electrical switchgear which includes the building's back-up generator.

The following comments pertain to the larger, more significant components in the Replacement Reserve Inventory and to those items that are unique or deserving of attention because of their condition or the manner in which they have been treated in the Replacement Reserve Analysis or Inventory.

IMPORTANT NOTE: This Condition Assessment is based upon visual and apparent conditions of the common elements of the community which were observed by the Reserve Analyst at the time of the site visit. This Condition Assessment does not constitute, nor is it a substitute for, a professional Structural Evaluation of the buildings, amenities, or systems. MillerDodson strongly recommends that the Association retain the services of a Structural Engineer to conduct thorough and periodic evaluations of the buildings, balconies, and any other structural components of the buildings and amenities of the Association.

General Condition Statements.

Excellent. 100% to 90% of Normal Economic Life expected, with no appreciable wear or defects.

Good. 90% to 60% of Normal Economic Life expected, minor wear or cosmetic defects found. Normal maintenance should be expected. If performed properly, normal maintenance may increase the useful life of a component. Otherwise, the component is wearing normally.

Fair. 60% to 30% of Normal Economic Life expected moderate wear with defects found. Repair actions should be taken to extend the life of the component or to correct repairable defects and distress. Otherwise, the component is wearing normally.

Marginal. 30% to 10% of Normal Economic Life expected, with moderate to significant wear or distress found. Repair actions are expected to be cost-effective for localized issues, but normal wear and use are evident. The component is reaching the end of the Normal Economic Life.

Poor. 10% to 0% of Normal Economic Life expected, with significant distress and wear. Left unattended, additional damage to underlying structures is likely to occur. Further maintenance is unlikely to be cost-effective.

(Continued on next page)

EXTERIOR ITEMS

Building Roofing. Asphalt shingle roofs can have a useful life of 20 to 50 years, depending on the weight and quality of the shingle. Weathered, curled, and missing shingles indicate they may be nearing the end of their useful life.

Slate shingle roofing can have an extended useful life of 100 years or more. Failures with slate roofs are primarily from improper fasteners, damage from improper access to the roof, and physical damage, primarily from hail. The metalwork, including flashings and valleys, will need to be replaced, and we assume that this work will be required every 30 years.

Metal roofing can be a standing seam, rolled seam, or shingle with a normal economic life of 50 to 100 years. In some cases, recoating or repainting can extend the useful life of a metal roof.


Flat roofing systems can have a variety of configurations that will greatly affect the cost of replacement, including insulation, ballast, the height of the building, and the density of installed mechanical equipment. Flat roofing systems typically have a useful life of 15 to 25 years.

Access to the roof was not provided at the time of the site visit.

Annual inspections are recommended, with cleaning, repair, and vegetation mitigation performed as needed. Contractors and personnel should perform access, inspection, and repair work with the appropriate access equipment experienced in the roofing types used for the facility.

INTERIOR ITEMS

Tile Floors. Tile floors are found in the 1st floor and 9th-floor lobbies and in the elevator lobbies on the 1st through 9th floors. Tile flooring and walls can also be found in the common restrooms. These floors walls have an extended life but may need occasional regrouting of joints. Full replacement has been included to allow for replacement due to failure or to allow for changes in the décor.





BUILDING SYSTEMS

Fire Safety Systems. The building is fitted with a fire safety system that includes sprinklers and alarms, which are reported to operate normally. Testing and inspection of fire safety systems are not included in this study.

Depending on age, condition, and jurisdictional location, sprinkler pipe systems have various configurations and requirements. Specific county and municipal codes can make a significant difference in what your facility's specific requirements may be.

Building fire alarm systems have a service life of 15 to 25 years. While the panels may continue to operate past this point, changes in fire safety technology and building fire safety codes tend to render them obsolete. In addition, manufacturers only support their systems for a limited period, typically about 15 years. After this time, it may be increasingly difficult to obtain replacement parts and services. When upgrading the fire alarm system, changes in the technologies and new code requirements will likely require upgrades in lighting, sensors, alarms, and other systems and sub-components.

We have assumed that wet and dry pipe systems are long-life components and will not require whole-scale replacement. It is imperative, however, for these pipes to be properly drained or for the water to be properly conditioned. Other components, such as heads, gauges, and valves, are assumed normal maintenance items and are therefore excluded from the study.

We recommend having your entire fire safety system inspected and evaluated by a professional in this field who is familiar with your area of the country. In addition, a comprehensive preventative maintenance program will ensure the maximum possible useful life from these components, and a qualified professional can help set up and implement such a program.

Your local CAI chapter may have a service provider list on their website that may refer you to a local fire and life safety consultant. As an alternative, please get in touch with our office, and we will provide recommendations.

As a preliminary estimate, we have provided an allowance every 15 years for the major repair and upgrade of the fire safety systems. A detailed evaluation of the facility's fire safety system should include an estimate of reserve funding for these components, and this funding estimate should be incorporated in the next reserve study update. Inspections and annual maintenance work are not accounted for or included in this study.

Emergency Backup Generator. The property has a Cummins generator for backup of essential emergency systems. The generator is new and in excellent condition. The Facility Manager operates the generator weekly to ensure it is in operation in case of emergency.





Electrical Switchgear. There is switchgear for distribution 480v power throughout the entire building on the1st floor and there are also power distribution panels for 120/208v power to the residential floors and for 480vpower in the penthouse for mechanical equipment. The switchgear has a long life but changes in equipment technology can result in the inability of obtaining replacement parts and subsequently to switchgear must be replaced. History in this area shows that in about 30 years the distribution breakers will require power panel replacements and the switchgear will require replacement in 50 years.

Electrical Transformers. Transformers are used to reduce the 480v power throughout the building to120/208v. These transformers experience the majority of failures due to overheating, so with electrical room cooling, this failure timeframe should be extended. The study assumes the transformers will last for 30 years before replacement.





This Condition Assessment is based upon our visual survey of the property. The sole purpose of the visual survey was an evaluation of the common and limited common elements of the property to ascertain their remaining useful life and replacement cost. Our evaluation assumed that all components met building code requirements in force at the time of construction. Our visual survey was conducted with care by experienced persons, but no warranty or guarantee is expressed or implied.

End of Condition Assessment

INTENTIONALLY LEFT BLANK


SECTION A - FINANCIAL ANALYSIS

The Sample High Rise - Garage Replacement Reserve Analysis uses the Cash Flow Method (CFM) to calculate Replacement Reserve funding for the periodic replacement of the 6 Projected Replacements identified in the Replacement Reserve Inventory.

\$32,053 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR THE STUDY YEAR, 2026 \$5.39 Per unit (average), minimum monthly funding of Replacement Reserves

We recommend the Association adopt a Replacement Reserve Funding Plan based on the annual funding recommendation above. Inflation adjusted funding for subsequent years is shown on Page A1.5.

Sample High Rise - Garage reports a Starting Balance of \$138,933 and Annual Funding totaling \$22,236, which is inadequate to fund projected replacements starting in 2039. See Page A1.3 for a more detailed evaluation.



REPLACEMENT RESERVE ANALYSIS - GENERAL INFORMATION

The Sample High Rise - Garage Replacement Reserve Analysis calculations of recommended funding of Replacement Reserves by the Cash Flow Method (CFM) and the evaluation of the Current Funding are based upon the same Study Year, Study Period, Beginning Balance, Replacement Reserve Inventory and Level of Service.

2026 STUDY YEAR

The Association reports that their accounting year begins on January 1, and the Study Year, the first year evaluated by the Replacement Reserve Analysis, begins on January 1, 2026.

30 Years | STUDY PERIOD

The Replacement Reserve Analysis evaluates the funding of Replacement Reserves over a 40-year Study Period

\$138,933 STARTING BALANCE


The Association reports Replacement Reserves on Deposit totaling \$138,933 at the start of the Study Year.

Level Two LEVEL OF SERVICE

The Replacement Reserve Inventory has been developed in compliance with the National Reserve Study Standards for a Level Two Study, as defined by the Community Associations Institute (CAI).

\$819,686 | REPLACEMENT RESERVE INVENTORY - PROJECTED REPLACEMENTS

The Sample High Rise - Garage Replacement Reserve Inventory identifies 6 items that will require periodic replacement, that are to be funded from Replacement Reserves. We estimate the cost of these replacements will be \$819,686 over the 30-year Study Period. The Projected Replacements are divided into 1 major categories starting on Page B1.3. Pages B1.1-B1.2 provide detailed information on the Replacement Reserve Inventory.



UPDATING OF THE FUNDING PLAN

The Association has a responsibility to review the Funding Plan annually. The review should include a comparison and evaluation of actual reserve funding with recommended levels shown on Page A1.4 and A1.5. The Projected Replacements listed on Page C1.2 should be compared with any replacements accomplished and funded from Replacement Reserves. Discrepancies should be evaluated and if necessary, the Reserve Study should be updated or a new study commissioned. We recommend annual increases in replacement reserve funding to account for the impact of inflation. Inflation Adjusted Funding is discussed on Page A1.5.

UPDATING OF THE REPLACEMENT RESERVE STUDY

At a minimum, the Replacement Reserve Study should be professionally updated every three to five years or after completion of a major replacement project. Updating should also be considered if during the annual review of the Funding Plan, discrepancies are noted between projected and actual reserve funding or replacement costs. Updating may also be necessary if there is a meaningful discrepancy between the actual inflation rate and the inflation rate used for the Inflation Adjusted Funding of Replacement Reserves on Page A1.5.

ANNUAL EXPENDITURES AND CURRENT FUNDING

The annual expenditures that comprise the \$819,686 of Projected Expenditures over the 30-year Study Period and the impact of the Association continuing to fund Replacement Reserves at the current level are detailed in Table 3.

#3 - Table of Annu	3 - Table of Annual Expenditures and Current Funding Data - Years 0 through 39											
Year	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035		
Starting Balance	\$138,933											
Projected Replacements				(\$175,165)				(\$37,000))			
Annual Deposit	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236		
End of Year Balance	\$161,169	\$183,405	\$205,641	\$52,712	\$74,948	\$97,184	\$119,420	\$104,656	\$126,892	\$149,128		
Cumulative Expenditures				(\$175,165)	(\$175,165)	(\$175,165)	(\$175,165)	(\$212,165)	(\$212,165)	(\$212,165)		
Cumulative Receipts	\$161,169	\$183,405	\$205,641	\$227,877	\$250,113	\$272,349	\$294,585	\$316,821	\$339,057	\$361,293		
Year	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045		
Projected Replacements			(\$173,350)	(\$175,165)				(\$6,840)				
Annual Deposit	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236		
End of Year Balance	\$171,364	\$193,600	\$42,486	(\$110,444)	(\$88,208)	(\$65,972)	(\$43,736)	(\$28,340)	(\$6,104)	\$16,132		
Cumulative Expenditures	(\$212,165)	(\$212,165)	(\$385,515)	(\$560,681)	(\$560,681)	(\$560,681)	(\$560,681)	(\$567,521)	(\$567,521)	(\$567,521)		
Cumulative Receipts	\$383,529	\$405,765	\$428,001	\$450,237	\$472,473	\$494,709	\$516,945	\$539,181	\$561,417	\$583,653		
Year	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055		
Projected Replacements			(\$37,000)	(\$215,165)								
Annual Deposit	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236	\$22,236		
End of Year Balance	\$38,368	\$60,604	\$45,840	(\$147,089)	(\$124,853)	(\$102,617)	(\$80,381)	(\$58,145)	(\$35,909)	(\$13,673)		
Cumulative Expenditures	(\$567,521)	(\$567,521)	(\$604,521)	(\$819,686)	(\$819,686)	(\$819,686)	(\$819,686)	(\$819,686)	(\$819,686)	(\$819,686)		
Cumulative Receipts	\$605,889	\$628,125	\$650,361	\$672,597	\$694,833	\$717,069	\$739,305	\$761,541	\$783,777	\$806,013		
•												

EVALUATION OF CURRENT FUNDING

The evaluation of Current Funding (Starting Balance of \$138,933 & annual funding of \$22,236), is done in today's dollars with no adjustments for inflation or interest earned on Replacement Reserves. The evaluation assumes Replacement Reserves will only be used for the 6 Projected Replacements identified in the Replacement Reserve Inventory and that the Association will continue Annual Funding of \$22,236 throughout the 30-year Study Period.

Annual Funding of \$22,236 is approximately 69 percent of the \$32,053 recommended Annual Funding calculated by the Cash Flow Method for 2026, the Study Year.

See the Executive Summary for the Current Funding Statement.


CASH FLOW METHOD FUNDING

\$32,053 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR 2026

\$5.39 Per unit (average), minimum monthly funding of Replacement Reserves

Recommended Replacement Reserve Funding has been calculated using the Cash Flow Method (also called the Straight Line or Threshold Method). This method calculates a constant annual funding between peaks in cumulative expenditures, while maintaining a Minimum Balance (threshold) in the Peak Years.

- Peak Years. The First Peak Year occurs in 2039 with Replacement Reserves on Deposit dropping to the Minimum Balance after the completion of \$560,681 of replacements from 2026 to 2039. Recommended funding is projected to decline from \$32,053 in 2039 to \$25,901 in 2040. Peak Years are identified in Chart 4 and Table 5.
- Threshold (Minimum Balance). The calculations assume a Minimum Balance of \$27,000 will always be held in reserve, which is calculated by rounding the 12-month 30-year average annual expenditure of \$27,323 as shown on Graph #2.
- Cash Flow Method Study Period. Cash Flow Method calculates funding for \$819,686 of expenditures over the 30-year Study Period. It does not include funding for any projects beyond 2055 and in 2055, the end of year balance will always be the Minimum Balance.



INFLATION ADJUSTED FUNDING

The Cash Flow Method calculations on Page A4 have been done in today's dollars with no adjustment for inflation. At MillerDodson, we believe that long-term inflation forecasting is effective at demonstrating the power of compounding, not at calculating appropriate funding levels for Replacement Reserves. We have developed this proprietary model to estimate the short-term impact of inflation on Replacement Reserve funding.

\$32,053 2026 - CASH FLOW METHOD RECOMMENDED FUNDING

The 2026 Study Year calculations have been made using current replacement costs \$34,137 2027 - 6.5% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2027 funding based on three assumptions:

- Starting Balance totaling \$170,986 on January 1, 2027.
- No Expenditures from Replacement Reserves in 2027.

\$36,355 | 2028 - 6.5% INFLATION ADJUSTED FUNDING


A new analysis calculates the 2028 funding based on three assumptions:

- Starting balance of approximately \$205,123 = 2028 Starting Balance \$170,986, plus Inflation Adjusted Funding \$34,137 for 2027, minus \$0 2027 Inflation Adjusted Cost.
- No Expenditures from Replacement Reserves in 2028.

\$38,721 2029 - 6.5% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2029 funding based on three assumptions:

- Starting balance of approximately \$241,479 = 2029 Starting Balance \$205,123, plus Inflation Adjusted Funding \$36,355 for 2028, minus \$0 2028 Inflation Adjusted Cost.
- 2029 Non-inflation replacement costs listed in Section C, \$175,165, will be replaced at approximately \$211,591, 6.5% compounded inflation increase to 2026 costs.
- The \$38,721 inflation-adjusted funding in 2029 is a 6.5% increase over the non-inflation-adjusted funding of \$36,355 for 2028.



Year Four and Beyond

The inflation-adjusted funding calculations outlined above are not intended to be a substitute for periodic evaluation of common elements by an experienced Reserve Analyst. Industry Standards, lender requirements, and many state and local statutes require a Replacement Reserve Study to be professionally updated every 3 to 5 years.

Inflation Adjustment

Prior to approving a budget based upon the 2027, 2028 and 2029 inflation-adjusted funding calculations above, the 6.50 percent base rate of inflation used in our calculations should be compared to rates published by the Bureau of Labor Statistics. If there is a significant discrepancy (over 1 percentage point), contact MillerDodson Associates prior to using the Inflation Adjusted Funding.

Interest on Reserves

The recommended funding calculations do not account for interest earned on Replacement Reserves. In 2026, based on a 1.00 percent interest rate, we estimate the Association may earn \$1,550 on an average balance of \$154,960, \$1,881 on an average balance of \$188,055 in 2027, and \$2,233 on \$223,301 in 2028. The Association may elect to attribute 100 percent of the earned interest to Reserves, resulting in a reduction in the 2026 funding from \$32,053 to \$30,504 (a 4.83 percent reduction), \$34,137 to \$32,256 in 2027 (a 5.50 percent reduction), and \$36,356 to \$34,123 in 2028 (a 6.14 percent reduction).

November 11, 2025

REPLACEMENT RESERVE STUDY - SUPPLEMENTAL COMMENTS

Maryland's new Reserves and Reserve Study Law, HB-107, is intended to ensure that adequate Reserve Funding is available for capital repair and replacement projects when it is needed. This is done by funding the Reserve Fund annually. The law requires that the Recommended Annual Reserve Funding amount in the most recent Reserve Study be included in the Association's annual budgets. If this is an Association's "initial" (first) professionally conducted Reserve Study, HB-107 gives the Association up to three (3) fiscal years following the fiscal year in which the Reserve Study was completed, to attain the Annual Reserve Funding level recommended in the initial Reserve Study.

SECTION B - REPLACEMENT RESERVE INVENTORY

• PROJECTED REPLACEMENTS. Sample High Rise - Garage - Replacement Reserve Inventory identifies 6 items that are Projected Replacements and the periodic replacements of these items are scheduled for funding from Replacement Reserves. The Projected Replacements have an estimated one-time replacement cost of \$432,355. Cumulative Replacements totaling \$819,686 are scheduled in the Replacement Reserve Inventory over the 30-year Study Period. Cumulative Replacements include those components that are replaced more than once during the period of the study.

Projected Replacements are the replacement of commonly-owned physical assets that require periodic replacement and whose replacement is to be funded from Replacement Reserves.

- **TAX CODE.** The United States Tax Code grants favorable tax status to Replacement Reserves, conditioned on expenditures being made within certain guidelines. These guidelines typically exclude maintenance activities, minor repairs, and capital improvements.
- **EXCLUDED ITEMS.** Some of the items contained in the Replacement Reserve Inventory are 'Excluded Items'. Multiple categories of items are typically excluded from funding by Replacement Reserves, including but not limited to:

Value. Items with a replacement cost of less than \$1000 and/or a normal economic life of less than 3 years are typically excluded from funding from Replacement Reserves. This exclusion should reflect the Association policy on the administration of Replacement Reserves. If the Association has selected an alternative level, it will be noted in the Replacement Reserve Inventory - General Comments on Page B1.2.

Long-lived Items. Items are excluded from the Replacement Reserve Inventory when items are properly maintained and are assumed to have a life equal to the property.

Unit Improvements. Items owned by a single unit and where the items serve a single unit are generally assumed to be the responsibility of that unit, not the Association.

Other Non-Common Improvements. Items owned by the local government, public and private utility companies, the United States Postal Service, Master Associations, state and local highway authorities, etc., may be installed on property that is owned by the Association. These types of items are generally not the responsibility of the Association and are excluded from the Replacement Reserve Inventory.

- **CATEGORIES.** The 6 items included in the Sample High Rise Garage Replacement Reserve Inventory are divided into 1 major categories. Each category is printed on a separate page, beginning on page B1.3.
- **LEVEL OF SERVICE.** This Replacement Reserve Inventory has been developed in compliance with the standards established for a Level 2 Update, as defined by the National Reserve Study Standards, established in 1998 by the Community Associations Institute, which states:

This study has been performed as a Level 2 Update with Site Visit/On-Site Review as defined by the Community Associations Institute's, National Reserve Study Standards. As such, the component inventory is based on the study that was performed by . This inventory was adjusted to reflect changes provided by the Community Manager and/or the Board of Directors, or adjustments made based on the site visit and visual assessment performed by the Analyst. The analysis, including fund status and funding plan, is developed from the adjusted inventory.

REPLACEMENT RESERVE INVENTORY - GENERAL INFORMATION (CONT'D)

• **INVENTORY DATA.** Each of the 6 Projected Replacements listed in the Replacement Reserve Inventory includes the following data:

Item Number. The Item Number is assigned sequentially and is intended for identification purposes only.

Item Description. We have identified each item included in the Inventory. Additional information may be included in the Comments section at the bottom of each page of the Inventory.

Units. We have used standard abbreviations to identify the number of units including SF-square feet, LF-lineal feet, SY-square yard, LS-lump sum, EA-each, and PR-pair. Non-standard abbreviations are noted in the Comments section at the bottom of the page.

Number of Units. The methods used to develop the quantities are discussed in "Level of Service" above.

Unit Replacement Cost. We use four sources to develop the unit cost data shown in the Inventory; actual replacement cost data provided by the client, information provided by local contractors and suppliers, industry standard estimating manuals, and a cost database we have developed based upon our detailed interviews with contractors and service providers who are specialists in their respective lines of work.

Normal Economic Life (Years). The number of years that a new and properly installed item should be expected to remain in service.

Remaining Economic Life (Years). The estimated number of years before an item will need to be replaced. In "normal" conditions, this could be calculated by subtracting the age of the item from the Normal Economic Life of the item, but only rarely do physical assets age "normally". Some items may have longer or shorter lives depending on many factors such as environment, initial quality of the item, maintenance, etc.

Total Replacement Cost. This is calculated by multiplying the Unit Replacement Cost by the Number of Units.

- **PARTIAL FUNDING.** Items may have been included in the Replacement Reserve Inventory at less than 100 percent of their full quantity and/or replacement cost. This is done on items that will never be replaced in their entirety, but which may require periodic replacements over an extended period of time. The assumptions that provide the basis for any partial funding are noted in the Comments section.
- **REMAINING ECONOMIC LIFE GREATER THAN 30 YEARS.** The calculations do not include funding for initial replacements beyond 30 years. These replacements are included in this Study for tracking and evaluation. They should be included for funding in future Studies, when they enter the 30-year window.
- ACCURACY OF THE ANALYSIS. The accuracy of the Replacement Reserve Analysis is dependent upon expenditures from Replacement Reserves being made ONLY for the 6 Projected Replacements specifically listed in the Replacement Reserve Inventory. The inclusion/exclusion of items from the Replacement Reserve Inventory is discussed on Page B1.1.

COMMENTS

November 11, 2025

	KING GARAGE ECTED REPLACEMENTS				NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)		
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$
1	Concrete Sealant - garage floor	sf	206,077	\$0.85	10	3	\$175,165
2	Overhead door with opener	ea	2	\$16,000.00	15	7	\$32,000
3	Security Gate Arms, motor & controls	ea	2	\$2,500.00	15	7	\$5,000
4	Suspended Ceiling	sf	17,335	\$10.00	20	12	\$173,350
5 6	Lighting, general fixtures	ea	320	\$125.00	25	23	\$40,000
U	Exit Signage, LED	ea	72	\$95.00	25	17	\$6,840

Replacement Costs - Page Subtotal

\$432,355

November 11, 2025

uded Items			UNIT			
M ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	REPLACEMENT COST (\$)	NEL	REL	REPLACE CO
House bib						EXCLUD
Property identification signage						EXCLUD
Miscellaneous signage						EXCLUD
Fire extinguisher cabinet						EXCLUD
Signage						EXCLUD

VALUATION EXCLUSIONS

Comments

- Valuation Exclusions. For ease of administration of the Replacement Reserves and to reflect accurately how Replacement Reserves are administered, items with a dollar value less than \$1000 have not been scheduled for funding from Replacement Reserve. Examples of items excluded by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

LONG-LIFE I	EXCLUSIONS						
ITEM ITEM # DESCRIPTION	ani	JNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
	g foundation(s)	INIC	OF UNITS	CO31 (\$)	INEL	KEL	EXCLUDED
Concre	ete floor slabs (interior)						EXCLUDED
Wall, f	oor, and roof structure						EXCLUDED
	on element electrical services						EXCLUDED
	cal wiring						EXCLUDED
	piping at common facilities						EXCLUDED
	piping at common facilities						EXCLUDED
Gas se	ervices at common facilities						EXCLUDED

LONG-LIFE EXCLUSIONS

Comments

- Long Life Exclusions. Components that when properly maintained, can be assumed to have a life equal to the property as a whole, are normally excluded from the Replacement Reserve Inventory. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- Exterior masonry is generally assumed to have an unlimited economic life, but periodic repointing is required, and we have included this for funding in the Replacement Reserve Inventory.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

UNIT Exclude	IMPROVEMENTS EXCLUSIONS d Items					
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REPLACEMEN REL COST (\$
#	All areas of building outside garage	UNII	OF UNITS	COST (\$)	NEL	EXCLUDED
	IMPROVEMENTS EXCLUSIONS					
Commer	nts					
• Uni	t improvement Exclusions. We understand that the ele				unit are th	

- of that unit owner. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

AINTENANCE AND REPAIR EXCLUSIONS luded Items	\$					
EM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMI COST
Striping of parking spaces			5551 (4)			EXCLUDE
Numbering of parking spaces						EXCLUDE
Repair services						EXCLUDE
Partial replacements						EXCLUDE
Capital improvements						EXCLUDE

MAINTENANCE AND REPAIR EXCLUSIONS

Comments

- Maintenance activities, one-time-only repairs, and capital improvements. These activities are NOT appropriately funded from Replacement Reserves. The inclusion of such component in the Replacement Reserve Inventory could jeopardize the special tax status of ALL Replacement Reserves, exposing the Association to significant tax liabilities. We recommend that the Board of Directors discuss these exclusions and Revenue Ruling 75-370 with a Certified Public Accountant.
- Examples of items excluded from funding by Replacement Reserves are listed above. The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

SECTION C - CALENDAR OF PROJECTED ANNUAL REPLACEMENTS

GENERAL STATEMENT. The 6 Projected Replacements in the Sample High Rise - Garage Replacement Reserve Inventory whose replacement is scheduled to be funded from Replacement Reserves are broken down on a year-by-year basis, beginning on Page C1.2.

REPLACEMENT RESERVE ANALYSIS AND INVENTORY POLICIES, PROCEDURES, AND ADMINISTRATION

- **REVIEW OF THE REPLACEMENT RESERVE STUDY.** For this study to be effective, it should be reviewed by the Board of Directors, those responsible for the management of the items included in the Replacement Reserve Inventory, and the accounting professionals employed by the Association.
- **REVISIONS.** Revisions will be made to the Replacement Reserve Analysis and Replacement Reserve Inventory in accordance with the written instructions of the Board of Directors. No additional charge is incurred for the <u>first</u> revision if requested in writing within three months of the date of the Replacement Reserve Study. It is our policy to provide revisions in electronic (Adobe PDF) format only. We acknowledge that there are instances in which multiple revisions are necessary. However, unnecessary multiple revisions drain our time and manpower resources. Therefore, MillerDodson will exercise its sole discretion as to whether additional charges are incurred.
- TAX CODE. The United States Tax Code grants favorable tax status to a common interest development (CID) meeting certain guidelines for their Replacement Reserve. If a CID files their taxes as a 'Corporation' on Form 1120 (IRC Section 277), these guidelines typically require maintenance activities, partial replacements, minor replacements, capital improvements, and one-time-only replacements to be excluded from Reserves. A CID cannot co-mingle planning for maintenance activities with capital replacement activities in the Reserves (Revenue Ruling 75-370). Funds for maintenance activities and capital replacement activities must be held in separate accounts. If a CID files taxes as an "Exempt Homeowners Association" using Form 1120H (IRC Section 528), the CID does not have to segregate these activities. However, because the CID may elect to change their method of filing from year to year within the Study Period, we advise using the more restrictive approach. We further recommend that the CID consult with their Accountant and consider creating separate and independent accounts and reserves for large maintenance items, such as painting.
- CONFLICT OF INTEREST. Neither MillerDodson Associates nor the Reserve Analyst has any prior or existing
 relationship with this Association which would represent a real or perceived conflict of interest.
- **RELIANCE ON DATA PROVIDED BY THE CLIENT.** Information provided by an official representative of the Association regarding financial, physical conditions, quality, or historical issues is deemed reliable.
- **INTENT.** This Replacement Reserve Study is a reflection of the information provided by the Association and the visual evaluations of the Analyst. It has been prepared for the sole use of the Association and is not for the purpose of performing an audit, quality/forensic analyses, or background checks of historical records.
- **PREVIOUS REPLACEMENTS.** Information provided to MillerDodson Associates regarding prior replacements is considered to be accurate and reliable. Our visual evaluation is not a project audit or quality inspection.
- EXPERIENCE WITH FUTURE REPLACEMENTS. The Calendar of Annual Projected Replacements, lists replacements we have projected to occur over the Study Period and begins on Page C2. Actual experience in replacing the items may differ significantly from the cost estimates and time frames shown because of conditions beyond our control. These differences may be caused by maintenance practices, inflation, variations in pricing and market conditions, future technological developments, regulatory actions, acts of God, and luck. Some items may function normally during our visual evaluation and then fail without notice.

PROJECTED R	EPLACEMENTS
Item 2026 - Study Year \$	Item 2027 - YEAR 1 \$
No Scheduled Replacements	No Scheduled Replacements
Item 2028 - YEAR 2 \$	Item 2029 - YEAR 3 \$ 1 Concrete Sealant - garage floor \$175,165
No Scheduled Replacements	Total Scheduled Replacements \$175,165
Item 2030 - YEAR 4 \$	Item 2031 - YEAR 5 \$
No Scheduled Replacements	No Scheduled Replacements
Item 2032 - YEAR 6 \$	Item 2033 - YEAR 7 \$ 2 Overhead door with opener \$32,000
	3 Security Gate Arms, motor & controls \$5,000
No Scheduled Replacements	Total Scheduled Replacements \$37,000
Item 2034 - YEAR 8 \$	Item 2035 - YEAR 9 \$
No Scheduled Replacements	No Scheduled Replacements

PRO	JECTED RI	PLACEMENTS	
Item 2036 - YEAR 10	\$	Item 2037 - YEAR 11	\$
No Scheduled Replacements		No Scheduled Replacements	
Item 2038 - YEAR 12	\$	Item 2039 - YEAR 13	\$
4 Suspended Ceiling	\$173,350	Concrete Sealant - garage floor	\$175,165
Total Scheduled Replacements	\$173,350	Total Scheduled Replacements	\$175,165
Item 2040 - YEAR 14	\$	Item 2041 - YEAR 15	\$
2040 - 12/4(14	Ψ	2041 - 1274(10	Ψ
No Scheduled Replacements		No Scheduled Replacements	
Item 2042 - YEAR 16	\$	Item 2043 - YEAR 17 6 Exit Signage, LED	\$ \$6,840
No Scheduled Replacements		Total Scheduled Replacements	\$6,840
Item 2044 - YEAR 18	\$	Item 2045 - YEAR 19	\$
No Scheduled Replacements		No Scheduled Replacements	

PROJECTED REPLACEMENTS									
Item 2046 - YEAR 20	\$	Item 2047 - YEAR 21	\$						
No Scheduled Replacements		No Scheduled Replacements							
Item 2048 - YEAR 22 2 Overhead door with opener	\$ \$32,000	1 Concrete Sealant - garage floor	\$ \$175,165						
3 Security Gate Arms, motor & controls	\$5,000	5 Lighting, general fixtures	\$40,000						
Total Scheduled Replacements	\$37,000	Total Scheduled Replacements	\$215,165						
Item 2050 - YEAR 24	\$	Item 2051 - YEAR 25	\$						
No Scheduled Replacements		No Scheduled Replacements							
Item 2052 - YEAR 26	\$	Item 2053 - YEAR 27	\$						
No Scheduled Replacements		No Scheduled Replacements							
Item 2054 - YEAR 28	\$	Item 2055 - YEAR 29	\$						
No Scheduled Replacements		No Scheduled Replacements							

SECTION D - CONDITION ASSESSMENT

General Comments. MillerDodson Associates conducted a Reserve Study at Sample High Rise - Garage in December 2020. Sample High Rise - Garage is in generally excellent condition for a condominium residential garage constructed in 2010. A review of the Replacement Reserve Inventory will show that we are anticipating most of the components achieving their normal economic lives.

Garage - This area covers the first floor entry point to the garage with the security gate arms and the overhead doors with garage door openers. The concrete floor for the entry and the 8 garage levels is included for sealing the concrete surface. The lighting and exit signs for the garage levels are included.

The following comments pertain to the larger, more significant components in the Replacement Reserve Inventory and to those items that are unique or deserving of attention because of their condition or the manner in which they have been treated in the Replacement Reserve Analysis or Inventory.

IMPORTANT NOTE: This Condition Assessment is based upon visual and apparent conditions of the common elements of the community which were observed by the Reserve Analyst at the time of the site visit. This Condition Assessment does not constitute, nor is it a substitute for, a professional Structural Evaluation of the buildings, amenities, or systems. MillerDodson strongly recommends that the Association retain the services of a Structural Engineer to conduct thorough and periodic evaluations of the buildings, balconies, and any other structural components of the buildings and amenities of the Association.

General Condition Statements.

Excellent. 100% to 90% of Normal Economic Life expected, with no appreciable wear or defects.

Good. 90% to 60% of Normal Economic Life expected, minor wear or cosmetic defects found. Normal maintenance should be expected. If performed properly, normal maintenance may increase the useful life of a component. Otherwise, the component is wearing normally.

Fair. 60% to 30% of Normal Economic Life expected moderate wear with defects found. Repair actions should be taken to extend the life of the component or to correct repairable defects and distress. Otherwise, the component is wearing normally.

Marginal. 30% to 10% of Normal Economic Life expected, with moderate to significant wear or distress found. Repair actions are expected to be cost-effective for localized issues, but normal wear and use are evident. The component is reaching the end of the Normal Economic Life.

Poor. 10% to 0% of Normal Economic Life expected, with significant distress and wear. Left unattended, additional damage to underlying structures is likely to occur. Further maintenance is unlikely to be cost-effective.

(Continued on next page)

PARKING GARAGE

Concrete Flatwork. The concrete flatwork includes the garage entry at street level and the garage floor itself. The Association maintains an inventory of approximately 211,457 square feet of concrete garage floor surface. The overall condition of the concrete surface is very good.

The standards we used for recommending replacement are as follows:

- Trip hazard, 0.5 inch height difference.
- Severe cracking.
- Severe spalling

Because it is highly unlikely that all of the garage concrete floors will fail and require replacement in the period of the study, we have programmed funds for sealing the concrete garage floor which includes a small amount for some crack sealing and spall repair. There should be little to no failure due to the garage being protected from the majority of the moisture and weather.

Concrete, Sealant. The concrete drive into the parking structure and the floor of each garage level will not need to be replaced as they are not directly exposed to the weather conditions, but to protect the surfaces from deterioration due to water, mag-chloride de-icer, and vehicle fluids it is recommended the concrete be sealed. History has proven that sealing the concrete in underground or covered garages every 10 years can limit the amount of spall repair that would otherwise be required. This Sample Company is a company specializing in garage sealing work in the Annapolis area. They were very helpful in determining the type of materials that work well in the local area and the cost factors for the work.

This Condition Assessment is based upon our visual survey of the property. The sole purpose of the visual survey was an evaluation of the common and limited common elements of the property to ascertain their remaining useful life and replacement cost. Our evaluation assumed that all components met building code requirements in force at the time of construction. Our visual survey was conducted with care by experienced persons, but no warranty or guarantee is expressed or implied.

End of Condition Assessment

INTENTIONALLY LEFT BLANK


SECTION A - FINANCIAL ANALYSIS

The Sample High Rise - Residential Common Elements Replacement Reserve Analysis uses the Cash Flow Method (CFM) to calculate Replacement Reserve funding for the periodic replacement of the 164 Projected Replacements identified in the Replacement Reserve Inventory.

\$255,281 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR THE STUDY YEAR, 2026 \$42.89 Per unit (average), minimum monthly funding of Replacement Reserves

We recommend the Association adopt a Replacement Reserve Funding Plan based on the annual funding recommendation above. Inflation adjusted funding for subsequent years is shown on Page A2.5.

Sample High Rise - Residential Common Elements reports a Starting Balance of \$1,124,541 and Annual Funding totaling \$179,988, which is inadequate to fund projected replacements starting in 2043. See Page A2.3 for a more detailed evaluation.



REPLACEMENT RESERVE ANALYSIS - GENERAL INFORMATION

The Sample High Rise - Residential Common Elements Replacement Reserve Analysis calculations of recommended funding of Replacement Reserves by the Cash Flow Method (CFM) and the evaluation of the Current Funding are based upon the same Study Year, Study Period, Beginning Balance, Replacement Reserve Inventory and Level of Service.

2026 STUDY YEAR

The Association reports that their accounting year begins on January 1, and the Study Year, the first year evaluated by the Replacement Reserve Analysis, begins on January 1, 2026.

40 Years | STUDY PERIOD

The Replacement Reserve Analysis evaluates the funding of Replacement Reserves over a 40-year Study Period

\$1,124,541 STARTING BALANCE


The Association reports Replacement Reserves on Deposit totaling \$1,124,541 at the start of the Study Year.

Level Two LEVEL OF SERVICE

The Replacement Reserve Inventory has been developed in compliance with the National Reserve Study Standards for a Level Two Study, as defined by the Community Associations Institute (CAI).

\$10,372,230 REPLACEMENT RESERVE INVENTORY - PROJECTED REPLACEMENTS

The Sample High Rise - Residential Common Elements Replacement Reserve Inventory identifies 164 items that will require periodic replacement, that are to be funded from Replacement Reserves. We estimate the cost of these replacements will be \$10,372,230 over the 40-year Study Period. The Projected Replacements are divided into 4 major categories starting on Page B2.3. Pages B2.1-B2.2 provide detailed information on the Replacement Reserve Inventory.



UPDATING OF THE FUNDING PLAN

The Association has a responsibility to review the Funding Plan annually. The review should include a comparison and evaluation of actual reserve funding with recommended levels shown on Page A2.4 and A2.5. The Projected Replacements listed on Page C2.2 should be compared with any replacements accomplished and funded from Replacement Reserves. Discrepancies should be evaluated and if necessary, the Reserve Study should be updated or a new study commissioned. We recommend annual increases in replacement reserve funding to account for the impact of inflation. Inflation Adjusted Funding is discussed on Page A2.5.

UPDATING OF THE REPLACEMENT RESERVE STUDY

At a minimum, the Replacement Reserve Study should be professionally updated every three to five years or after completion of a major replacement project. Updating should also be considered if during the annual review of the Funding Plan, discrepancies are noted between projected and actual reserve funding or replacement costs. Updating may also be necessary if there is a meaningful discrepancy between the actual inflation rate and the inflation rate used for the Inflation Adjusted Funding of Replacement Reserves on Page A2.5.

ANNUAL EXPENDITURES AND CURRENT FUNDING

The annual expenditures that comprise the \$10,372,230 of Projected Expenditures over the 40-year Study Period and the impact of the Association continuing to fund Replacement Reserves at the current level are detailed in Table 3.

3 - Table of Annu	3 - Table of Annual Expenditures and Current Funding Data - Years 0 through 39											
Year	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035		
Starting Balance	\$1,124,541											
Projected Replacements	(\$18,940)	(\$3,308)	(\$6,000)	(\$187,269)	(\$76,559)	(\$374,353)	(\$110,530)	(\$53,234)	(\$342,815)	(\$11,780		
Annual Deposit	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988		
End of Year Balance	\$1,285,589	\$1,462,270	\$1,636,258	\$1,628,977	\$1,732,406	\$1,538,041	\$1,607,499	\$1,734,254	\$1,571,427	\$1,739,635		
Cumulative Expenditures	(\$18,940)	(\$22,248)	(\$28,248)	(\$215,517)	(\$292,075)	(\$666,428)	(\$776,958)	(\$830,192)	(\$1,173,007)	(\$1,184,787		
Cumulative Receipts	\$1,304,529	\$1,484,517	\$1,664,505	\$1,844,493	\$2,024,481	\$2,204,469	\$2,384,457	\$2,564,445	\$2,744,433	\$2,924,421		
Year	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045		
Projected Replacements	(\$280,983)	(\$57,750)	(\$23,424)	(\$872,025)	(\$218,579)	(\$1,136,321)	(\$185,926)	(\$801,248)	(\$397,284)	(\$33,888		
Annual Deposit	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988		
End of Year Balance	\$1,638,640	\$1,760,878	\$1,917,442	\$1,225,405	\$1,186,815	\$230,482	\$224,544	(\$396,716)	(\$614,012)	(\$467,911		
Cumulative Expenditures	(\$1,465,769)	(\$1,523,519)	(\$1,546,943)	(\$2,418,968)	(\$2,637,547)	(\$3,773,867)	(\$3,959,793)	(\$4,761,041)	(\$5,158,325)	(\$5,192,212		
Cumulative Receipts	\$3,104,409	\$3,284,397	\$3,464,385	\$3,644,373	\$3,824,361	\$4,004,349	\$4,184,337	\$4,364,325	\$4,544,313	\$4,724,301		
Year	2046	2047	2048	2049	2050	2051	2052	2053	2054	205		
Projected Replacements	(\$78,975)	(\$13,940)	(\$42,783)	(\$1,578,252)	(\$137,825)	(\$122,886)	(\$77,976)	(\$233,286)	(\$354,280)	(\$370,898		
Annual Deposit	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988		
End of Year Balance	(\$366,898)	(\$200,850)	(\$63,645)	(\$1,461,909)	(\$1,419,746)	(\$1,362,643)	(\$1,260,631)	(\$1,313,929)	(\$1,488,221)	(\$1,679,131		
Cumulative Expenditures	(\$5,271,187)	(\$5,285,127)	(\$5,327,910)	(\$6,906,162)	(\$7,043,987)	(\$7,166,872)	(\$7,244,848)	(\$7,478,134)	(\$7,832,414)	(\$8,203,312		
Cumulative Receipts	\$4,904,289	\$5,084,277	\$5,264,265	\$5,444,253	\$5,624,241	\$5,804,229	\$5,984,217	\$6,164,205	\$6,344,193	\$6,524,181		
Year	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065		
Projected Replacements	(\$327,007)	(\$108,000)	(\$120,068)	(\$785,709)	(\$99,879)	(\$208,793)	(\$98,650)	(\$53,044)	(\$350,640)	(\$17,130		
Annual Deposit	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988	\$179,988		
End of Year Balance	(\$1,826,149)	(\$1,754,161)	(\$1,694,241)	(\$2,299,962)	(\$2,219,852)	(\$2,248,657)	(\$2,167,319)	(\$2,040,375)	(\$2,211,027)	(\$2,048,169		
Cumulative Expenditures	(\$8,530,318)	(\$8,638,318)	(\$8,758,386)	(\$9,544,095)	(\$9,643,973)	(\$9,852,766)	(\$9,951,416)	(\$10,004,460)	(\$10,355,100)	(\$10,372,230		
Cumulative Receipts	\$6,704,169	\$6,884,157	\$7,064,145	\$7,244,133	\$7,424,121	\$7,604,109	\$7,784,097	\$7,964,085	\$8,144,073	\$8,324,06		

EVALUATION OF CURRENT FUNDING

The evaluation of Current Funding (Starting Balance of \$1,124,541 & annual funding of \$179,988), is done in today's dollars with no adjustments for inflation or interest earned on Replacement Reserves. The evaluation assumes Replacement Reserves will only be used for the 164 Projected Replacements identified in the Replacement Reserve Inventory and that the Association will continue Annual Funding of \$179,988 throughout the 40-year Study Period.

Annual Funding of \$179,988 is approximately 71 percent of the \$255,281 recommended Annual Funding calculated by the Cash Flow Method for 2026, the Study Year.

See the Executive Summary for the Current Funding Statement.


CASH FLOW METHOD FUNDING

\$255,281 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR 2026

\$42.89 Per unit (average), minimum monthly funding of Replacement Reserves

Recommended Replacement Reserve Funding has been calculated using the Cash Flow Method (also called the Straight Line or Threshold Method). This method calculates a constant annual funding between peaks in cumulative expenditures, while maintaining a Minimum Balance (threshold) in the Peak Years.

- **Peak Years.** The First Peak Year occurs in 2059 with Replacement Reserves on Deposit dropping to the Minimum Balance after the completion of \$9,544,095 of replacements from 2026 to 2059. Recommended funding is anticipated to decline in 2060. Peak Years are identified in Chart 4 and Table 5.
- Threshold (Minimum Balance). The calculations assume a Minimum Balance of \$260,000 will always be held in reserve, which is calculated by rounding the 12-month 40-year average annual expenditure of \$259,306 as shown on Graph #2.
- Cash Flow Method Study Period. Cash Flow Method calculates funding for \$10,372,230 of expenditures over the 40-year Study Period. It does not include funding for any projects beyond 2065 and in 2065, the end of year balance will always be the Minimum Balance.



INFLATION ADJUSTED FUNDING

The Cash Flow Method calculations on Page A4 have been done in today's dollars with no adjustment for inflation. At MillerDodson, we believe that long-term inflation forecasting is effective at demonstrating the power of compounding, not at calculating appropriate funding levels for Replacement Reserves. We have developed this proprietary model to estimate the short-term impact of inflation on Replacement Reserve funding.

\$255,281 2026 - CASH FLOW METHOD RECOMMENDED FUNDING

The 2026 Study Year calculations have been made using current replacement costs \$261,152 2027 - 2.3% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2027 funding based on three assumptions:

- Starting Balance totaling \$1,360,882 on January 1, 2027.
- 2027 Non-inflation replacement costs listed in Section C, \$3,308, will be replaced at approximately \$3,384, 2.30% compounded inflation increase to 2026 costs.
- The \$261,152 inflation-adjusted funding in 2027 is a 2.3% increase over the non-inflation-adjusted funding of \$255,281.

\$267,152 | 2028 - 2.3% INFLATION ADJUSTED FUNDING


A new analysis calculates the 2028 funding based on three assumptions:

- Starting balance of approximately \$1,618,651 = 2028 Starting Balance \$1,360,882, plus Inflation Adjusted Funding \$261,152 for 2027, minus \$3,384 2027 Inflation Adjusted Cost.
- 2028 Non-inflation replacement costs listed in Section C, \$6,000, will be replaced at approximately \$6,279, 2.3% compounded inflation increase to 2026 costs.
- The \$267,152 inflation-adjusted funding in 2028 is a 2.3% increase over the non-inflation-adjusted funding of \$261,152 for 2027.

\$273,304 | 2029 - 2.3% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2029 funding based on three assumptions:

- Starting balance of approximately \$1,879,531 = 2029 Starting Balance \$1,618,651, plus Inflation Adjusted Funding \$267,152 for 2028, minus \$6,279 2028 Inflation Adjusted Cost.
- 2029 Non-inflation replacement costs listed in Section C, \$187,269, will be replaced at approximately \$200,490, 2.3% compounded inflation increase to 2026 costs.
- The \$273,304 inflation-adjusted funding in 2029 is a 2.3% increase over the non-inflation-adjusted funding of \$267,152 for 2028.



Year Four and Beyond

The inflation-adjusted funding calculations outlined above are not intended to be a substitute for periodic evaluation of common elements by an experienced Reserve Analyst. Industry Standards, lender requirements, and many state and local statutes require a Replacement Reserve Study to be professionally updated every 3 to 5 years.

Inflation Adjustment

Prior to approving a budget based upon the 2027, 2028 and 2029 inflation-adjusted funding calculations above, the 2.30 percent base rate of inflation used in our calculations should be compared to rates published by the Bureau of Labor Statistics. If there is a significant discrepancy (over 1 percentage point), contact MillerDodson Associates prior to using the Inflation Adjusted Funding.

Interest on Reserves

The recommended funding calculations do not account for interest earned on Replacement Reserves. In 2026, based on a 1.00 percent interest rate, we estimate the Association may earn \$12,427 on an average balance of \$1,242,711, \$14,898 on an average balance of \$1,489,766 in 2027, and \$17,491 on \$1,749,092 in 2028. The Association may elect to attribute 100 percent of the earned interest to Reserves, resulting in a reduction in the 2026 funding from \$255,281 to \$242,854 (a 4.86 percent reduction), \$261,152 to \$246,255 in 2027 (a 5.70 percent reduction), and \$267,159 to \$249,668 in 2028 (a 6.54 percent reduction).

Sample High Rise - Residential Common Elements

November 11, 2025

REPLACEMENT RESERVE STUDY - SUPPLEMENTAL COMMENTS

Maryland's new Reserves and Reserve Study Law, HB-107, is intended to ensure that adequate Reserve Funding is available for capital repair and replacement projects when it is needed. This is done by funding the Reserve Fund annually. The law requires that the Recommended Annual Reserve Funding amount in the most recent Reserve Study be included in the Association's annual budgets. If this is an Association's "initial" (first) professionally conducted Reserve Study, HB-107 gives the Association up to three (3) fiscal years following the fiscal year in which the Reserve Study was completed, to attain the Annual Reserve Funding level recommended in the initial Reserve Study.

SECTION B - REPLACEMENT RESERVE INVENTORY

PROJECTED REPLACEMENTS. Sample High Rise - Residential Common Elements - Replacement Reserve
Inventory identifies 164 items that are Projected Replacements and the periodic replacements of these items are
scheduled for funding from Replacement Reserves. The Projected Replacements have an estimated one-time
replacement cost of \$5,054,805. Cumulative Replacements totaling \$10,372,230 are scheduled in the Replacement
Reserve Inventory over the 40-year Study Period. Cumulative Replacements include those components that are
replaced more than once during the period of the study.

Projected Replacements are the replacement of commonly-owned physical assets that require periodic replacement and whose replacement is to be funded from Replacement Reserves.

- **TAX CODE.** The United States Tax Code grants favorable tax status to Replacement Reserves, conditioned on expenditures being made within certain guidelines. These guidelines typically exclude maintenance activities, minor repairs, and capital improvements.
- **EXCLUDED ITEMS.** Some of the items contained in the Replacement Reserve Inventory are 'Excluded Items'. Multiple categories of items are typically excluded from funding by Replacement Reserves, including but not limited to:

Value. Items with a replacement cost of less than \$1000 and/or a normal economic life of less than 3 years are typically excluded from funding from Replacement Reserves. This exclusion should reflect the Association policy on the administration of Replacement Reserves. If the Association has selected an alternative level, it will be noted in the Replacement Reserve Inventory - General Comments on Page B2.2.

Long-lived Items. Items are excluded from the Replacement Reserve Inventory when items are properly maintained and are assumed to have a life equal to the property.

Unit Improvements. Items owned by a single unit and where the items serve a single unit are generally assumed to be the responsibility of that unit, not the Association.

Other Non-Common Improvements. Items owned by the local government, public and private utility companies, the United States Postal Service, Master Associations, state and local highway authorities, etc., may be installed on property that is owned by the Association. These types of items are generally not the responsibility of the Association and are excluded from the Replacement Reserve Inventory.

- **CATEGORIES.** The 164 items included in the Sample High Rise Residential Common Elements Replacement Reserve Inventory are divided into 4 major categories. Each category is printed on a separate page, beginning on page B2.3.
- **LEVEL OF SERVICE.** This Replacement Reserve Inventory has been developed in compliance with the standards established for a Level 2 Update, as defined by the National Reserve Study Standards, established in 1998 by the Community Associations Institute, which states:

This study has been performed as a Level 2 Update with Site Visit/On-Site Review as defined by the Community Associations Institute's, National Reserve Study Standards. As such, the component inventory is based on the study that was performed by . This inventory was adjusted to reflect changes provided by the Community Manager and/or the Board of Directors, or adjustments made based on the site visit and visual assessment performed by the Analyst. The analysis, including fund status and funding plan, is developed from the adjusted inventory.

REPLACEMENT RESERVE INVENTORY - GENERAL INFORMATION (CONT'D)

• **INVENTORY DATA.** Each of the 164 Projected Replacements listed in the Replacement Reserve Inventory includes the following data:

Item Number. The Item Number is assigned sequentially and is intended for identification purposes only.

Item Description. We have identified each item included in the Inventory. Additional information may be included in the Comments section at the bottom of each page of the Inventory.

Units. We have used standard abbreviations to identify the number of units including SF-square feet, LF-lineal feet, SY-square yard, LS-lump sum, EA-each, and PR-pair. Non-standard abbreviations are noted in the Comments section at the bottom of the page.

Number of Units. The methods used to develop the quantities are discussed in "Level of Service" above.

Unit Replacement Cost. We use four sources to develop the unit cost data shown in the Inventory; actual replacement cost data provided by the client, information provided by local contractors and suppliers, industry standard estimating manuals, and a cost database we have developed based upon our detailed interviews with contractors and service providers who are specialists in their respective lines of work.

Normal Economic Life (Years). The number of years that a new and properly installed item should be expected to remain in service.

Remaining Economic Life (Years). The estimated number of years before an item will need to be replaced. In "normal" conditions, this could be calculated by subtracting the age of the item from the Normal Economic Life of the item, but only rarely do physical assets age "normally". Some items may have longer or shorter lives depending on many factors such as environment, initial quality of the item, maintenance, etc.

Total Replacement Cost. This is calculated by multiplying the Unit Replacement Cost by the Number of Units.

- **PARTIAL FUNDING.** Items may have been included in the Replacement Reserve Inventory at less than 100 percent of their full quantity and/or replacement cost. This is done on items that will never be replaced in their entirety, but which may require periodic replacements over an extended period of time. The assumptions that provide the basis for any partial funding are noted in the Comments section.
- **REMAINING ECONOMIC LIFE GREATER THAN 40 YEARS.** The calculations do not include funding for initial replacements beyond 40 years. These replacements are included in this Study for tracking and evaluation. They should be included for funding in future Studies, when they enter the 40-year window.
- ACCURACY OF THE ANALYSIS. The accuracy of the Replacement Reserve Analysis is dependent upon expenditures from Replacement Reserves being made ONLY for the 164 Projected Replacements specifically listed in the Replacement Reserve Inventory. The inclusion/exclusion of items from the Replacement Reserve Inventory is discussed on Page B2.1.

Sample High Rise - Residential Common Elements

	ERIOR ITEMS CTED REPLACEMENTS	NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)					
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
1	Storefront Doors, 9th & 10th floors	ea	7	\$1,200.00	20	13	\$8,400
2	Sliding Glass Doors to Balconies (10%)	ea	48	\$4,655.00	5	8	\$223,440
3	Balcony railing (25%)	If	2,460	\$75.00	35	27	\$184,500

Replacement Costs - Page Subtotal	\$416.340

COMMENTS

INTERIOR ITEMS - COMMON AREA, ALL FLOORS PROJECTED REPLACEMENTS							Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
4	Hallway Carpet (20%)	sf	7,456	\$6.00	10	3	\$44,736
5	Hallway Carpet (20%)	sf	7,456	\$6.00	10	4	\$44,736
6	Hallway Carpet (20%)	sf	7,456	\$6.00	10	5	\$44,736
7	Hallway Carpet (20%)	sf	7,456	\$6.00	10	6	\$44,736
8	Hallway Carpet (20%)	sf	7,456	\$6.00	10	7	\$44,736
9	Mailroom, Carpet	sf	454	\$6.00	10	3	\$2,724
10	Tile Floor, tuckpoint, 5%	sf	264	\$7.50	10	3	\$1,980
11	Tile Floor, replace	sf	5,287	\$41.00	30	23	\$216,767
12	Hallway Wall Covering, w/base & signs (20%)	sf	20,170	\$5.25	15	13	\$105,893
13	Hallway Wall Covering, w/base & signs (20%)	sf	20,170	\$5.25	15	14	\$105,893
14	Hallway Wall Covering, w/base & signs (20%)	sf	20,170	\$5.25	15	15	\$105,893
15	Hallway Wall Covering, w/base & signs (20%)	sf	20,170	\$5.25	15	16	\$105,893
16	Hallway Wall Covering, w/base & signs (20%)	sf	20,170	\$5.25	15	17	\$105,893
17	Hallway Suspended Ceiling	sf	2,376	\$10.00	30	23	\$23,760
18	Hallway Lighting, 25%	ea	240	\$150.00	10	13	\$36,000
19	Exit Signs, LED	ea	132	\$90.00	25	18	\$11,880
20	Flat Screen TVs, wall mounted (25%)	ea	10	\$600.00	2	none	\$6,000
21	Hallway Artwork	ea	66	\$250.00	12	5	\$16,500
22	Wood Doors, with hardware, 25%	ea	134	\$825.00	10	13	\$110,550
23	HM Doors, single	ea	137	\$725.00	30	23	\$99,325
24	HM Doors, double	ea	2	\$1,200.00	30	23	\$2,400
			Rep	lacement Costs -	Page	Subtotal	\$1,281,029

COMMENTS

Sample High Rise - Residential Common Elements

November 11, 2025

INTERIOR ITEMS - COMMON AREA, ALL FLOORS - (cont.) PROJECTED REPLACEMENTS					NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)		
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
25	Lighting, elevator lobby, 1st-8th floors	ea	186	\$150.00	25	18	\$27,900
26	Mailboxes, 10 unit high, single wide	ea	2	\$1,100.00	25	18	\$2,200
27	Mailboxes, 10 unit high, double wide	ea	26	\$1,650.00	25	18	\$42,900
28	Mailboxes, 2 unit large boxes	ea	11	\$550.00	25	18	\$6,050
29	Parcel collector, 9th floor	ls	1	\$34,000.00	25	24	\$34,000
30	Stair light fixtures	ea	84	\$125.00	25	18	\$10,500
31	Chain Link Fence Storage, repair	ea	525	\$80.00	20	13	\$42,000

Replacement Costs - Page Subtotal \$165,550

COMMENTS

• Item #31: Chain Link Fence Storage, repair - Chain Link Fence Storage - The repair for each storage area would be the door hinges and lock arm, as these moving parts will fail through usage and time.

MillerDodson Associates, Inc.
Sample High Rise - Residential Common Elements

	RIOR ITEMS - 1ST FLOOR LOBBY CTED REPLACEMENTS			·	NI REL-	EL - Normal E Remaining E	Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
32	Area Rugs	ls	1	\$1,800.00	8	4	\$1,800
33	Wall Covering	sf	400	\$5.25	15	11	\$2,100
34	Wall panels,mirror	ls	1	\$1,000.00	30	26	\$1,000
35	Lounge, furniture, hard goods	Is	1	\$13,600.00	21	17	\$13,600
36	Artwork	Is	1	\$5,300.00	12	8	\$5,300
37	Bathroom Renovation, 1st, Men	ls	1	\$6,500.00	20	13	\$6,500
38	Bathroom Renovation, 1st, Women	ls	1	\$6,500.00	20	13	\$6,500
			Rep	olacement Costs -	Page S	Subtotal	\$36,800

CO	M	ME	ΞN	TS

INTERIOR ITEMS - 9TH FLOOR LOBBY & LOUNGE PROJECTED REPLACEMENTS							conomic Life (yrs) conomic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
39	Labby Oth Floor Tile	of	374	¢44.00	20	9	645 224
40	Lobby, 9th Floor, Tile Lounge, 9th Floor, Carpet	sf sf	3,448	\$41.00 \$6.00	30 10	3 3	\$15,334 \$20,688
41	Lounge, Wood Panel Wall	sı sf	3, 44 6 450	\$9.00	10 25	ა 18	\$20,000 \$4,050
				******			+ 1,555
42	Lobby Front Counter, millwork	Is	1	\$1,750.00	21	14	\$1,750
43	Lobby, Front Counter, computers	ea	3	\$1,200.00	6	5	\$3,600
44	Lobby, Front Counter, chairs	ea	2	\$525.00	12	9	\$1,050
45	Manager Office, furniture	ls	1	\$8,000.00	12	10	\$8,000
46	Bathroom Renovation, 9th, Men	ls	1	\$6,500.00	20	13	\$6,500
47	Bathroom Renovation, 9th, Women	ls	1	\$6,500.00	20	13	\$6,500
48	Bathroom Renovation, fitness	ls	1	\$6,500.00	20	13	\$6,500
49	Lounge, millwork	ls	1	\$4,500.00	24	18	\$4,500
50	Lounge, appliances	ls	1	\$2,800.00	12	6	\$2,800
51	Lounge, pool table	ea	1	\$5,500.00	21	15	\$5,500
52	Lounge, furniture, soft goods	ls	1	\$45,000.00	10	3	\$45,000
53	Lounge, furniture, hard goods	ls	1	\$20,000.00	21	14	\$20,000
54	Lounge, furniture, hard goods	ls	1	\$12,000.00	21	18	\$12,000
55	Lounge, artwork	Is	1	\$1,750.00	12	5	\$1,750
56	Lounge, flat screen TVs - (25%)	ea	1	\$900.00	2	1	\$900
57	Lounge, video projector	ea	1	\$1,400.00	8	3	\$1,400
58	Lounge, Lighting	ea	53	\$150.00	25	18	\$7,950
			Rep	lacement Costs -	Page S	Subtotal	\$175,772

COMMENTS

INTERIOR ITEMS - 9TH FLOOR FITNESS CENTER (FC) PROJECTED REPLACEMENTS							conomic Life (yrs) conomic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
59	Fitness Center, Carpet	sf	1,120	\$6.00	10	3	\$6,720
60	Fitness Center, Rubber Flooring	sf	1,250	\$12.00	15	10	\$15,000
61	Fitness Center, Rubber Flooring (top)	sf	1,000	\$12.00	15	10	\$12,000
62	FC - treadmills	ea	4	\$7,400.00	12	5	\$29,600
63	FC - ellipticals	ea	3	\$2,800.00	12	5	\$8,400
64	FC - exercise bike, upright	ea	1	\$1,200.00	12	5	\$1,200
65	FC - exercise bike, spin	ea	1	\$2,050.00	12	5	\$2,050
66	FC - exercise bike, spin	ea	1	\$2,050.00	12	9	\$2,050
67	FC - stair stepper	ea	1	\$2,400.00	12	5	\$2,400
68	FC - rowing machine	ea	1	\$1,100.00	12	9	\$1,100
69	FC - exercise equipment, resistance	Is	1	\$42,000.00	24	17	\$42,000
70	FC - smith machine	ea	2	\$3,400.00	24	17	\$6,800
71	FC - weight bench	ea	2	\$1,000.00	32	25	\$2,000
72	FC - weights	ls	1	\$4,500.00	32	25	\$4,500
73	FC Mirrors	sf	768	\$8.00	24	17	\$6,144
74	FC - Chairs, metal	ea	4	\$150.00	21	14	\$600
75	FC Light Strips	ea	4	\$750.00	25	18	\$3,000
76	FC Light fixtures	ea	4	\$150.00	25	15	\$600
			Rep	lacement Costs -	Page S	Subtotal	\$146,164

COMMENTS

• FC - exercise equipment, resistance includes (12) strength equipment items: crunch bench, assisted dip, shoulder press, bicep curl, row/rear deltoid, tricep press, fly, pulldown, chest press, leg extension, seated leg curl, and seated leg press

	RIOR ITEMS - 10TH FLOOR LOUNGE AR	EA					Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMEI COST
77	Lounge, 10th floor, carpet	sf	1	\$6.00	10	3	\$6
78	Lounge, bathroom renovation	ea	2	\$6,500.00	20	13	\$13,000
79	Lounge, kitchen millwork	ls	1	\$3,200.00	24	17	\$3,200
80	Lounge, kitchen appliances	ls	1	\$1,475.00	12	5	\$1,475
81	Lounge, millwork	ls	1	\$1,275.00	21	14	\$1,275
82	Lounge, furniture, soft goods	ls	1	\$4,400.00	10	3	\$4,400
83	Lounge, furniture, hard goods	ls	1	\$9,875.00	21	14	\$9,875
84	Lounge, computers	ea	2	\$1,400.00	6	5	\$2,800
85	Lounge, flat screen TVs (50%)	ea	1	\$1,200.00	4	1	\$1,200
86	Lounge, artwork	ls	1	\$1,600.00	12	5	\$1,600
87	Lounge, lighting	ea	24	\$150.00	25	18	\$3,600

COMMENTS

Replacement Costs - Page Subtotal

\$42,431

COMMENTS

November 11, 2025

	RIOR ITEMS - 10TH FLOOR MEDIA ROOM CTED REPLACEMENTS						Economic Life (yrs) Economic Life (yrs)
EM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMEN COST (\$
38	Media Room, 10th floor, carpet	sf	1	\$6.00	10	3	\$6
39	Media Room, millwork	ls	1	\$25.00	21	15	\$25
90	Media Room, furniture, soft goods	ls	1	\$10,750.00	10	4	\$10,750
91	Media Room, furniture, hard goods	ls	1	\$825.00	21	15	\$825
92	Media Room, video projector	ea	1	\$1,425.00	8	3	\$1,425
93	Media Room, projector screen	ea	1	\$325.00	16	11	\$325
94	Media Room, popcorn popper	ea	1	\$1,000.00	5	4	\$1,000
95	Media Room, artwork	ls	1	\$475.00	12	8	\$475
96	Media Room, lighting	ea	8	\$150.00	25	20	\$1,200

Replacement Costs - Page Subtotal

\$16,031

	DING SYSTEMS - MECHANICAL SYSTEMS CTED REPLACEMENTS						mal Economic Life (yrs) ing Economic Life (yrs)	
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)	
97	Cooling Towers, rebuild	ea	2	\$59,350.00	12	5	\$118,700	
98	Cooling Towers, replacement	ea	2	\$59,350.00	24	17	\$118,700	
99	Cooling Towers fan VFDs	ea	2	\$8,100.00	12	5	\$16,200	
100	Rooftop AHU for Corridors, repair	ea	1	\$59,000.00	15	5	\$59,000	
101	Rooftop AHU for Corridors, replace	ea	1	\$81,000.00	30	17	\$81,000	
102	Heating system heat exchangers	ea	2	\$23,000.00	24	17	\$46,000	
103	Heating water pump, 2 hp	ea	2	\$5,900.00	24	17	\$11,800	
104	Condensor water pump, 75 hp	ea	2	\$13,000.00	24	17	\$26,000	
105	Rebuild condensor water pump	ea	2	\$6,400.00	12	5	\$12,800	
106	Replace condensor pump motor, 75 hp	ea	2	\$2,800.00	6	5	\$5,600	
107	Condensor water pump VFDs	ea	2	\$8,500.00	12	5	\$17,000	
108	DHW tanks & heat exchangers	ea	2	\$11,800.00	20	13	\$23,600	
109	Cooling Water treatment system	ls	1	\$10,750.00	10	3	\$10,750	
110	Domestic water booster pumps, 75 hp	ea	2	\$19,500.00	20	13	\$39,000	
111	Rebuild domestic water booster pump	ea	2	\$6,400.00	10	3	\$12,800	
112	Replace water pump motor, 75 hp	ea	2	\$8,500.00	6	5	\$17,000	
113	Domestic water booster pump VFDs	ea	2	\$2,800.00	12	11	\$5,600	
114	Domestic water booster pump control	ls	1	\$8,100.00	20	10	\$8,100	
115	Domestic water booster pumps, 75 hp	ea	2	\$19,500.00	20	13	\$39,000	
116	Rebuild domestic water booster pump	ea	2	\$6,400.00	10	3	\$12,800	
117	Replace motor domestic pump, 75 hp	ea	2	\$2,800.00	5	3	\$5,600	
			Repl	acement Costs -	Page S	Subtotal	\$687,050	

COMMENTS

- The cost for the cooling tower replacement is reduced by the amount of the repair cost which will take place at the same time. The replacement cost considers a re-lining of the tower fan sections with all new moving parts as the size and the weight of the entire unit would need to be craned off and then the new craned on.
- The cost for the rooftop AHU replacement is reduced by the amount of the repair cost which will take place at the same time. The replacement cost considers re-skinning of any rusted exterior panels with all new moving parts as the size and the weight of the entire unit would need to be craned off and then the new craned on.
- The building's HVAC system has 14 VAV boxes. We have assumed that one will require replacement every 2 years once they are 20 years old.

	DING SYSTEMS - MECHANICAL SYSTE	MS - (con	- (cont.)			NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)		
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMEN' COST (\$	
118	Domestic water booster pump VFDs	ea	2	\$8,500.00	12	11	\$17,000	
119	Domestic water booster pump control	Is	1	\$8,100.00	20	10	\$8,100	
120	Domestic water pump, 20 hp	ea	1	\$6,200.00	24	22	\$6,200	
121	Domestic water pump, 20 hp rebuild	ea	1	\$2,200.00	12	10	\$2,200	
122	Domestic water pump, 20 hp motor	ea	1	\$2,200.00	6	4	\$2,200	
123	Domestic water pump, 20 hp VFD	ea	1	\$2,200.00	12	10	\$2,200	
124	HW recirculation pump, 9th floor	ea	1	\$3,500.00	24	22	\$3,500	
125	Elevator Equipment HVAC, 4000 cfm	ea	1	\$23,750.00	24	17	\$23,750	
126	1st Floor Lobby FCU HP	ls	1	\$3,400.00	20	13	\$3,400	
127	1st Floor Maint. Shop FCU HP	ls	1	\$2,975.00	20	13	\$2,975	
128	9th Floor FCU Heat Pumps	ls	1	\$11,850.00	20	13	\$11,850	
129	10th Floor FCU Heat Pumps	ls	1	\$8,900.00	20	13	\$8,900	
130	Exhaust Fan, 15hp, large	ea	1	\$10,200.00	30	23	\$10,200	
131	Exhaust Fans, 10hp, medium	ea	7	\$6,900.00	30	23	\$48,300	
132	Exhaust Fans, 7.5hp, small	ea	2	\$5,100.00	30	23	\$10,200	
133	Stairwell heates, electric, w/fan	ea	13	\$450.00	24	17	\$5,850	

COMMENTS

- The cost for the cooling tower replacement is reduced by the amount of the repair cost which will take place at the same time. The replacement cost considers a re-lining of the tower fan sections with all new moving parts as the size and the weight of the entire unit would need to be craned off and then the new craned on.
- The cost for the rooftop AHU replacement is reduced by the amount of the repair cost which will take place at the same time. The replacement cost considers re-skinning of any rusted exterior panels with all new moving parts as the size and the weight of the entire unit would need to be craned off and then the new craned on.
- The building's HVAC system has 14 VAV boxes. We have assumed that one will require replacement every 2 years once
 they are 20 years old.

Replacement Costs - Page Subtotal

\$166,825

Sample High Rise - Residential Common Elements

November 11, 2025

	DING SYSTEMS - ELEVATORS CTED REPLACEMENTS		NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)				
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
134	Elevator controls and component replace	ea	4	\$242,000.00	25	15	\$968,000
135	Elevator cabs & doors, remodel	ea	4	\$42,000.00	20	10	\$168,000
136	Elevator cab interiors	ea	4	\$25,500.00	15	8	\$102,000
137	Trash chute doors, set	ea	43	\$575.00	25	19	\$24,725

Replacement Costs - Page Subtotal \$1,262,725

COMMENTS

 The Association presently has a "premium elevator maintenance contract" which repairs or replaces most major components on the elevators. Recommend the Association continue to maintain the elevators with this "premium contract".
 If not, then the reserve study should add costs to relace the components covered.

	DING SYSTEMS - ELECTRICAL SYSTEMS CTED REPLACEMENTS						Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMEN' COST (\$
138	Disrtibution Switchgear repairs	ea	32	\$1,125.00	30	23	\$36,000
139	Distrubution Transformer, 480v to 208v	ea	17	\$23,250.00	30	23	\$395,250
140	FCU, heat pump, for electrical rooms	ea	17	\$2,550.00	20	23	\$43,350
141	Key Trak system	ls	1	\$31,500.00	15	10	\$31,500

			rs.

Replacement Costs - Page Subtotal

\$506,100

	REATION ITEMS - SWIMMING POOL CTED REPLACEMENTS					NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)		
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)	
142	Concrete, deck, partial repair	sf	100	\$13.50	99	none	\$1,350	
143	Concrete, seal, around pool	sf	5,300	\$0.30	10	4	\$1,590	
144	Swimming pool finish, tuckpointing	sf	1,420	\$4.50	7	none	\$6,390	
145	Swimming pool ceramic tile replace	sf	1,420	\$24.00	99	6	\$34,080	
146	Swimming white coat	sf	1,420	\$17.00	10	16	\$24,140	
147	Swimming pool waterline tile	lf	175	\$22.00	10	5	\$3,850	
148	Spa white coat	sf	190	\$17.00	10	9	\$3,230	
149	Spa waterline tile	If	36	\$22.00	10	5	\$792	
150	Swimming pool filter	ls	1	\$3,200.00	10	4	\$3,200	
151	Swimming pool valves & plumbing	sf	1,420	\$2.25	20	14	\$3,195	
152	Swimming pool pumps	ea	2	\$2,600.00	5	none	\$5,200	
153	Swimming pool heat exchanger	ea	2	\$9,300.00	30	24	\$18,600	
154	Spa, air pump	ea	1	\$1,750.00	6	4	\$1,750	
155	Recliner Lounge, outdoors	ea	54	\$135.00	12	6	\$7,290	
156	Recliner Lounge, outdoors, replace fabric	ea	54	\$106.00	6	6	\$5,724	
157	Big Wicker Sofa	ea	2	\$1,050.00	12	10	\$2,100	
158	Big Wicker Chairs	ea	9	\$825.00	12	10	\$7,425	
159	Big Wicker, re-cushion	ea	11	\$900.00	6	6	\$9,900	
160	Gas Barbeque Grills	ea	3	\$775.00	10	4	\$2,325	
			Repl	acement Costs -	Page	Subtotal	\$142,131	

COMMENTS

• The swimming pool inventory includes the spa.

REATION ITEMS - FIRE PIT & DOG PARK ECTED REPLACEMENTS				NEL- Normal Economic Life (yrs) REL- Remaining Economic Life (yrs)		
ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
Fire Pit	ea	1	\$5,000.00	20	17	\$5,000
Dog Park, 3rd Floor, carpet	sf	345	\$3.50	3	1	\$1,208
Dog Park, 3rd Floor, glass surround	lf	32	\$75.00	35	32	\$2,400
Dog Park, 3rd Floor, furniture	ls	1	\$1,250.00	12	9	\$1,250
	Fire Pit Dog Park, 3rd Floor, carpet Dog Park, 3rd Floor, glass surround	ECTED REPLACEMENTS ITEM DESCRIPTION UNIT Fire Pit ea Dog Park, 3rd Floor, carpet Dog Park, 3rd Floor, glass surround If	Fire Pit ea 1 Dog Park, 3rd Floor, carpet pog Park, 3rd Floor, glass surround lf 32	ECTED REPLACEMENTS ITEM DESCRIPTION UNIT NUMBER OF UNITS REPLACEMENT COST (\$) Fire Pit ea 1 \$5,000.00 Dog Park, 3rd Floor, carpet Dog Park, 3rd Floor, glass surround sf 345 \$3.50 Dog Park, 3rd Floor, glass surround lf 32 \$75.00	ECTED REPLACEMENTS REL-	REL- Remaining ITEM DESCRIPTION NUMBER OF UNITS NUMBER COST (\$) NEL REL Fire Pit ea 1 \$5,000.00 20 17 Dog Park, 3rd Floor, carpet Dog Park, 3rd Floor, glass surround sf 345 \$3.50 3 1 Dog Park, 3rd Floor, glass surround lf 32 \$75.00 35 32

Replacement Costs - Page Subtotal

\$9,858

COMMENTS

VALUATION EXCLUSIONS Excluded Items						
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
Property identification signage	ONIT	OI ONITS	σσστ (ψ)	INLL	NLL	EXCLUDED
Miscellaneous signage						EXCLUDED
Fire extinguisher cabinet						EXCLUDED
Signage						EXCLUDED
Interior doors						EXCLUDED

VALUATION EXCLUSIONS

- Valuation Exclusions. For ease of administration of the Replacement Reserves and to reflect accurately how Replacement Reserves are administered, items with a dollar value less than \$1000 have not been scheduled for funding from Replacement Reserve. Examples of items excluded by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

LONG-LIFE EXCLUSIONS Excluded Items					
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL REL	REPLACEMENT COST (\$)
Building foundation(s)	OHIT	OF SIMILE	σσο (ψ)	NEE NEE	EXCLUDED
Concrete floor slabs (interior)					EXCLUDED
Wall, floor, and roof structure					EXCLUDED
Common element electrical services					EXCLUDED
Electrical wiring					EXCLUDED
Water piping at common facilities					EXCLUDED
Waste piping at common facilities					EXCLUDED
Gas services at common facilities					EXCLUDED
Trash chute					EXCLUDED
Stainless steel pool fixtures					EXCLUDED

LONG-LIFE EXCLUSIONS

- Long Life Exclusions. Components that when properly maintained, can be assumed to have a life equal to the property as a whole, are normally excluded from the Replacement Reserve Inventory. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- Exterior masonry is generally assumed to have an unlimited economic life, but periodic repointing is required, and we have included this for funding in the Replacement Reserve Inventory.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

UNIT	IMPROVEMENTS EXCLUSIONS						
Exclude				LIMIT			
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
	Sanitary sewers serving one unit			5521 (4)	.,		EXCLUDED
	Electrical wiring serving one unit						EXCLUDED
	Cable TV service serving one unit						EXCLUDED
	Telephone service serving one unit						EXCLUDED
	Gas service serving one unit						EXCLUDED
	Unit interior						EXCLUDED

UNIT IMPROVEMENTS EXCLUSIONS

- Unit improvement Exclusions. We understand that the elements of the project that relate to a single unit are the responsibility of that unit owner. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

UTILITY EXCLUSIONS						
Excluded Items			UNIT			
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
Primary electric feeds						EXCLUDED
Electric transformers						EXCLUDED
Cable TV systems and structures						EXCLUDED
Telephone cables and structures						EXCLUDED
Gas mains and meters						EXCLUDED
Water mains and meters						EXCLUDED

UTILITY EXCLUSIONS

- Utility Exclusions. Many improvements owned by utility companies are on property owned by the Association. We have
 assumed that repair, maintenance, and replacements of these components will be done at the expense of the appropriate
 utility company. Examples of items excluded from funding Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

MAINTENANCE AND REPAIR EXCLUSIONS						
ITEM ITEM		NUMBER	UNIT REPLACEMENT		-	REPLACEMENT
# DESCRIPTION Striping of parking spaces	UNIT	OF UNITS	COST (\$)	NEL	REL	EXCLUDED
Numbering of parking spaces						EXCLUDED
Interior painting						EXCLUDED
Janitorial service						EXCLUDED
Repair services						EXCLUDED
Partial replacements						EXCLUDED
Capital improvements						EXCLUDED
Capital Improvement						_,,,,

MAINTENANCE AND REPAIR EXCLUSIONS

- Maintenance activities, one-time-only repairs, and capital improvements. These activities are NOT appropriately funded from Replacement Reserves. The inclusion of such component in the Replacement Reserve Inventory could jeopardize the special tax status of ALL Replacement Reserves, exposing the Association to significant tax liabilities. We recommend that the Board of Directors discuss these exclusions and Revenue Ruling 75-370 with a Certified Public Accountant.
- Examples of items excluded from funding by Replacement Reserves are listed above. The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

GOVE Exclude	ERNMENT EXCLUSIONS d Items						
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
	Government, roadways and parking						EXCLUDED
GOVE	ERNMENT EXCLUSIONS						

- Government Exclusions. We have assumed that some of the improvements installed on property owned by the Association will be maintained by the state, county, or local government, or other association or other responsible entity. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- Excluded rights-of-way, including adjacent properties and adjacent roadways.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

INTENTIONALLY LEFT BLANK

SECTION C - CALENDAR OF PROJECTED ANNUAL REPLACEMENTS

GENERAL STATEMENT. The 164 Projected Replacements in the Sample High Rise - Residential Common Elements Replacement Reserve Inventory whose replacement is scheduled to be funded from Replacement Reserves are broken down on a year-by-year basis, beginning on Page C2.2.

REPLACEMENT RESERVE ANALYSIS AND INVENTORY POLICIES, PROCEDURES, AND ADMINISTRATION

- **REVIEW OF THE REPLACEMENT RESERVE STUDY.** For this study to be effective, it should be reviewed by the Board of Directors, those responsible for the management of the items included in the Replacement Reserve Inventory, and the accounting professionals employed by the Association.
- **REVISIONS.** Revisions will be made to the Replacement Reserve Analysis and Replacement Reserve Inventory in accordance with the written instructions of the Board of Directors. No additional charge is incurred for the <u>first</u> revision if requested in writing within three months of the date of the Replacement Reserve Study. It is our policy to provide revisions in electronic (Adobe PDF) format only. We acknowledge that there are instances in which multiple revisions are necessary. However, unnecessary multiple revisions drain our time and manpower resources. Therefore, MillerDodson will exercise its sole discretion as to whether additional charges are incurred.
- TAX CODE. The United States Tax Code grants favorable tax status to a common interest development (CID) meeting certain guidelines for their Replacement Reserve. If a CID files their taxes as a 'Corporation' on Form 1120 (IRC Section 277), these guidelines typically require maintenance activities, partial replacements, minor replacements, capital improvements, and one-time-only replacements to be excluded from Reserves. A CID cannot co-mingle planning for maintenance activities with capital replacement activities in the Reserves (Revenue Ruling 75-370). Funds for maintenance activities and capital replacement activities must be held in separate accounts. If a CID files taxes as an "Exempt Homeowners Association" using Form 1120H (IRC Section 528), the CID does not have to segregate these activities. However, because the CID may elect to change their method of filing from year to year within the Study Period, we advise using the more restrictive approach. We further recommend that the CID consult with their Accountant and consider creating separate and independent accounts and reserves for large maintenance items, such as painting.
- CONFLICT OF INTEREST. Neither MillerDodson Associates nor the Reserve Analyst has any prior or existing
 relationship with this Association which would represent a real or perceived conflict of interest.
- **RELIANCE ON DATA PROVIDED BY THE CLIENT.** Information provided by an official representative of the Association regarding financial, physical conditions, quality, or historical issues is deemed reliable.
- **INTENT.** This Replacement Reserve Study is a reflection of the information provided by the Association and the visual evaluations of the Analyst. It has been prepared for the sole use of the Association and is not for the purpose of performing an audit, quality/forensic analyses, or background checks of historical records.
- **PREVIOUS REPLACEMENTS.** Information provided to MillerDodson Associates regarding prior replacements is considered to be accurate and reliable. Our visual evaluation is not a project audit or quality inspection.
- **EXPERIENCE WITH FUTURE REPLACEMENTS.** The Calendar of Annual Projected Replacements, lists replacements we have projected to occur over the Study Period and begins on Page C2. Actual experience in replacing the items may differ significantly from the cost estimates and time frames shown because of conditions beyond our control. These differences may be caused by maintenance practices, inflation, variations in pricing and market conditions, future technological developments, regulatory actions, acts of God, and luck. Some items may function normally during our visual evaluation and then fail without notice.

Item	\$
142 Concrete, deck, partial repair \$1,350 85 Lounge, flat screen TVs (50%) 144 Swimming pool finish, tuckpointing \$6,390 162 Dog Park, 3rd Floor, carpet	\$900
144 Swimming pool finish, tuckpointing \$6,390 162 Dog Park, 3rd Floor, carpet	\$1,200
152 Swimming pool pumps \$5,200	\$1,208
I	
ll ll	
Total Scheduled Replacements \$18,940 Total Scheduled Replacements	\$3,308

Item	2028 - YEAR 2	\$	Item	2029 - YEAR 3	\$
20	Flat Screen TVs, wall mounted (25%)	\$6,000	4	Hallway Carpet (20%)	\$ \$44,736
20	Tat Solden 1 vs, wall mounted (2070)	ψυ,υυυ	9	Mailroom, Carpet	\$2,724
			10	Tile Floor, tuckpoint, 5%	\$1,980
			39	Lobby, 9th Floor, Tile	\$1,980 \$15,334
			40	Lounge, 9th Floor, Carpet	\$20,688
			52	Lounge, furniture, soft goods	\$45,000
			56	Lounge, flat screen TVs - (25%)	\$900
			57	Lounge, video projector	\$1,400
			59	Fitness Center, Carpet	\$6,720
			77	Lounge, 10th floor, carpet	\$6
			82	Lounge, furniture, soft goods	\$4,400
			88	Media Room, 10th floor, carpet	\$6
			92	Media Room, video projector	\$1,425
			109	Cooling Water treatment system	\$10,750
			111	Rebuild domestic water booster pump	\$12,800
			116	Rebuild domestic water booster pump	\$12,800
			117	Replace motor domestic pump, 75 hp	\$5,600
Total S	cheduled Replacements	\$6,000	Total S	cheduled Replacements	\$187,269

Item	2030 - YEAR 4	\$	Item 2031 - YEAR 5	\$
5	Hallway Carpet (20%)	\$44,736	6 Hallway Carpet (20%)	\$44,736
20	Flat Screen TVs, wall mounted (25%)	\$6,000	21 Hallway Artwork	\$16,500
32	Area Rugs	\$1,800	43 Lobby, Front Counter, computers	\$3,600
90	Media Room, furniture, soft goods	\$10,750	55 Lounge, artwork	\$1,750
94	Media Room, popcorn popper	\$1,000	56 Lounge, flat screen TVs - (25%)	\$900
122	Domestic water pump, 20 hp motor	\$2,200	62 FC - treadmills	\$29,600
143	Concrete, seal, around pool	\$1,590	63 FC - ellipticals	\$8,400
150	Swimming pool filter	\$3,200	64 FC - exercise bike, upright	\$1,200
154	Spa, air pump	\$1,750	65 FC - exercise bike, spin	\$2,050
160	Gas Barbeque Grills	\$2,325	67 FC - stair stepper	\$2,400
	•		* *	
162	Dog Park, 3rd Floor, carpet	\$1,208	80 Lounge, kitchen appliances	\$1,475
			84 Lounge, computers	\$2,800
			85 Lounge, flat screen TVs (50%)	\$1,200
			86 Lounge, artwork	\$1,600
			97 Cooling Towers, rebuild	\$118,700
			99 Cooling Towers fan VFDs	\$16,200
			100 Rooftop AHU for Corridors, repair	\$59,000
			105 Rebuild condensor water pump	\$12,800
			106 Replace condensor pump motor, 75 hp	\$5,600
1			107 Condensor water pump VFDs	\$17,000
			112 Replace water pump motor, 75 hp	\$17,000
1			147 Swimming pool waterline tile	\$3,850
			149 Spa waterline tile	\$792
			152 Swimming pool pumps	\$5,200
Total S	cheduled Replacements	\$76,559	Total Scheduled Replacements	\$374,353

Item	2032 - YEAR 6	\$	Item	2033 - YEAR 7	\$
7	Hallway Carpet (20%)	\$44,736	8	Hallway Carpet (20%)	\$44,736
20	Flat Screen TVs, wall mounted (25%)	\$6,000	56	Lounge, flat screen TVs - (25%)	\$900
50	Lounge, appliances	\$2,800	144	Swimming pool finish, tuckpointing	\$6,390
145	Swimming pool ceramic tile replace	\$34,080	162	Dog Park, 3rd Floor, carpet	\$1,208
155	Recliner Lounge, outdoors	\$7,290		· · · · · ·	. ,
156	Recliner Lounge, outdoors, replace fabric	\$5,724			
159	Big Wicker, re-cushion	\$9,900			
	g	40,000			
T-4-1 0	School and Devices weeks	¢440 500	Tetal	Sahadulad Danlagamenta	650.004
i otal S	cheduled Replacements	\$110,530	ı otal S	Scheduled Replacements	\$53,234

Item	2034 - YEAR 8	\$	Item	2035 - YEAR 9	\$
2	Sliding Glass Doors to Balconies (10%)	\$223,440	44	Lobby, Front Counter, chairs	\$1,050
20	Flat Screen TVs, wall mounted (25%)	\$6,000	56	Lounge, flat screen TVs - (25%)	\$900
36	Artwork	\$5,300	66	FC - exercise bike, spin	\$2,050
95	Media Room, artwork	\$475	68	FC - rowing machine	\$1,100
117	Replace motor domestic pump, 75 hp	\$5,600	85	Lounge, flat screen TVs (50%)	\$1,200
136	Elevator cab interiors	\$102,000	94	Media Room, popcorn popper	\$1,000
			148	Spa white coat	\$3,230 \$4,250
			164	Dog Park, 3rd Floor, furniture	\$1,250
			']		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
			1		
Ì					
Ī			1		
1			1		
1					
Total S	Scheduled Replacements	\$342,815	Total S	Scheduled Replacements	\$11,780

	0000 1/5:5:5		.,	0007 11717	•
Item	2036 - YEAR 10	\$	Item	2037 - YEAR 11	\$
20	Flat Screen TVs, wall mounted (25%)	\$6,000	33	Wall Covering	\$2,100
45	Manager Office, furniture	\$8,000	43	Lobby, Front Counter, computers	\$3,600
60	Fitness Center, Rubber Flooring	\$15,000	56	Lounge, flat screen TVs - (25%)	\$900
61	Fitness Center, Rubber Flooring (top)	\$12,000	57	Lounge, video projector	\$1,400
114	Domestic water booster pump control	\$8,100	84	Lounge, computers	\$2,800
119	Domestic water booster pump control	\$8,100	92	Media Room, video projector	\$1,425
121	Domestic water pump, 20 hp rebuild	\$2,200	93	Media Room, projector screen	\$325
122	Domestic water pump, 20 hp motor	\$2,200	106	Replace condensor pump motor, 75 hp	\$5,600
123	Domestic water pump, 20 hp VFD	\$2,200	112	Replace water pump motor, 75 hp	\$17,000
135	Elevator cabs & doors, remodel	\$168,000	113	Domestic water booster pump VFDs	\$5,600
141	Key Trak system	\$31,500	118	Domestic water booster pump VFDs	\$17,000
152	Swimming pool pumps	\$5,200			
154	Spa, air pump	\$1,750			
157	Big Wicker Sofa	\$2,100			
158	Big Wicker Chairs	\$7,425			
162	Dog Park, 3rd Floor, carpet	\$1,208			
Total S	cheduled Replacements	\$280,983	Total S	Scheduled Replacements	\$57,750
		•			

Item	2038 - YEAR 12	\$	Item	2039 - YEAR 13	\$
20	Flat Screen TVs, wall mounted (25%)	\$6,000	1	Storefront Doors, 9th & 10th floors	\$8,400
32	Area Rugs	\$1,800	2	Sliding Glass Doors to Balconies (10%)	\$223,440
156	Recliner Lounge, outdoors, replace fabric	\$5,724	4	Hallway Carpet (20%)	\$44,736
159	Big Wicker, re-cushion	\$9,900	9	Mailroom, Carpet	\$2,724
			10	Tile Floor, tuckpoint, 5%	\$1,980
			12	Hallway Wall Covering, w/base & signs (20%)	\$105,893
			18	Hallway Lighting, 25%	\$36,000
			22	Wood Doors, with hardware, 25%	\$110,550
			31	Chain Link Fence Storage, repair	\$42,000
			37	Bathroom Renovation, 1st, Men	\$6,500
			38	Bathroom Renovation, 1st, Women	\$6,500
			40	Lounge, 9th Floor, Carpet	\$20,688
			46	Bathroom Renovation, 9th, Men	\$6,500
			47	Bathroom Renovation, 9th, Women	\$6,500
			48	Bathroom Renovation, fitness	\$6,500
			52	Lounge, furniture, soft goods	\$45,000
			56	Lounge, flat screen TVs - (25%)	\$900
			59	Fitness Center, Carpet	\$6,720
			77	Lounge, 10th floor, carpet	\$6
			78	Lounge, bathroom renovation	\$13,000
			82 85	Lounge, furniture, soft goods	\$4,400 \$1,200
			85	Lounge, flat screen TVs (50%)	\$1,200
			88 108	Media Room, 10th floor, carpet	\$6
			108	DHW tanks & heat exchangers Cooling Water treatment system	\$23,600 \$10,750
			110	Domestic water booster pumps, 75 hp	\$39,000
			111	Rebuild domestic water booster pump	\$12,800
			115	Domestic water booster pumps, 75 hp	\$39,000
			116	Rebuild domestic water booster pump	\$12,800
			117	Replace motor domestic pump, 75 hp	\$5,600
			126	1st Floor Lobby FCU HP	\$3,400
			127	1st Floor Maint. Shop FCU HP	\$2,975
			128	9th Floor FCU Heat Pumps	\$11,850
			129	10th Floor FCU Heat Pumps	\$8,900
			162	Dog Park, 3rd Floor, carpet	\$1,208
Total S	cheduled Replacements	\$23,424	Total S	Scheduled Replacements	\$872,025

Harr	2040 VEAD 44	•	ltar-	2044 VEAD 45	<u></u>
Item 5	2040 - YEAR 14 Hallway Carpet (20%)	\$ \$44,736	Item 6	2041 - YEAR 15 Hallway Carpet (20%)	\$ \$44,736
13	Hallway Wall Covering, w/base & signs (20%)	\$105,893	14	Hallway Wall Covering, w/base & signs (20%)	\$105,893
20	Flat Screen TVs, wall mounted (25%)	\$6,000	51	Lounge, pool table	\$5,500
42	Lobby Front Counter, millwork	\$1,750	56	Lounge, flat screen TVs - (25%)	\$900
53	Lounge, furniture, hard goods	\$20,000	76	FC Light fixtures	\$600
74	FC - Chairs, metal	\$600	89	Media Room, millwork	\$25
81	Lounge, millwork	\$1,275	91	Media Room, furniture, hard goods	\$825
83	Lounge, furniture, hard goods	\$9,875	134	Elevator controls and component replace	\$968,000
90	Media Room, furniture, soft goods	\$10,750	147	Swimming pool waterline tile	\$3,850
94	Media Room, popcorn popper	\$1,000	149	Spa waterline tile	\$792
143	Concrete, seal, around pool	\$1,590	152	Swimming pool pumps	\$5,200
144	Swimming pool finish, tuckpointing	\$6,390			
150	Swimming pool filter	\$3,200			
151	Swimming pool valves & plumbing	\$3,195			
160	Gas Barbeque Grills	\$2,325			
1					
1					
1					
1					
1					
1					
1					
1					
1					
1					
Total S	scheduled Replacements	\$218,579	Total	Scheduled Replacements	\$1,136,321
rotal S	oneduled Replacements	⊅∠18,579	rotal S	оспечией періасетіеніх	\$1,130,321

Item	2042 - YEAR 16	\$	Item	2043 - YEAR 17	\$
7	Hallway Carpet (20%)	\$44,736	8	Hallway Carpet (20%)	\$44,736
15	Hallway Wall Covering, w/base & signs (20%)	\$105,893	16	Hallway Wall Covering, w/base & signs (20%)	\$105,893
20	Flat Screen TVs, wall mounted (25%)	\$6,000	21	Hallway Artwork	\$16,500
122	Domestic water pump, 20 hp motor	\$2,200	35	Lounge, furniture, hard goods	\$13,600
146	Swimming white coat	\$24,140	43	Lobby, Front Counter, computers	\$3,600
154	Spa, air pump	\$1,750	55	Lounge, artwork	\$1,750
162	Dog Park, 3rd Floor, carpet	\$1,208	56	Lounge, flat screen TVs - (25%)	\$900
			62	FC - treadmills	\$29,600
			63	FC - ellipticals	\$8,400
			64	FC - exercise bike, upright	\$1,200 \$2,050
			65 67	FC - exercise bike, spin	\$2,050
			69	FC - stair stepper FC - exercise equipment, resistance	\$2,400 \$42,000
			70	FC - smith machine	\$6,800
			73	FC Mirrors	\$6,144
			79	Lounge, kitchen millwork	\$3,200
			80	Lounge, kitchen appliances	\$1,475
			84	Lounge, computers	\$2,800
			85	Lounge, flat screen TVs (50%)	\$1,200
			86	Lounge, artwork	\$1,600
			97	Cooling Towers, rebuild	\$118,700
			98	Cooling Towers, replacement	\$118,700
			99	Cooling Towers fan VFDs	\$16,200
			101	Rooftop AHU for Corridors, replace	\$81,000
			102	Heating system heat exchangers	\$46,000
			103	Heating water pump, 2 hp	\$11,800
			104	Condensor water pump, 75 hp	\$26,000
			105	Rebuild condensor water pump	\$12,800
			106	Replace condensor pump motor, 75 hp	\$5,600
			107	Condensor water pump VFDs	\$17,000
			112	Replace water pump motor, 75 hp	\$17,000
			125 133	Elevator Equipment HVAC, 4000 cfm Stairwell heates, electric, w/fan	\$23,750 \$5,850
			161	Fire Pit	\$5,000
			101	THETH	ψ3,000
T-4-1-0	shadulad Daylasaysayt-	6405.000	T-4 1 0	School and Double comparate	#004.04 2
i otai Sc	cheduled Replacements	\$185,926	i otai S	Scheduled Replacements	\$801,248

Serial S	l.	0044 VEAD 40			-0015 VEAD 10	
10	Item	2044 - YEAR 18 Sliding Glass Doors to Balconics (10%)	\$ \$	Item 56	2045 - YEAR 19	\$
20						
28					· · · · · · · · · · · · · · · · · · ·	
Mailboxes, 10 unit high, double wide						
Assistance						
30 Stair light features \$10,500 41 Lounge, millwork \$4,500 50 Lounge, paplances \$2,800 51 Lounge, Lighting \$7,950 75 FO Light Skips \$3,000 77 Replace motor demostic pump, 75 hp \$5,000 78 Replace motor demostic pump, 77 hp \$5,000 79 Replace motor demostic pump, 77 hp \$5,000 79 Replace motor demostic pump, 78 hp \$5,000 70 Replace motor demostic pump, 78 hp \$5,000 71 Replace motor demostic pump, 78 hp \$5,000 72 Replace motor demostic pump, 78 hp \$5,000 73 Replace motor demostic pump, 78 hp \$5,000 74 Replace motor demostic pump, 78 hp \$5,000 75 Replace motor demostic pump, 78 hp \$5,000 76 Replace motor demostic pump, 78 hp \$5,000 77 Replace motor demostic pump, 78 hp \$5,000 78 Replace motor demostic pump, 78 hp \$5,000 79 Replace motor demostic pump, 78 hp \$5,000 70 Replace motor demostic pump, 78 hp \$5,000 71 Replace motor demostic pump, 78 hp \$5,000 71 Replace motor demostic pump, 78 hp \$5,000 72 Replace motor demostic pump, 78 hp \$5,000 79 Replace motor demostic pump, 78 hp \$5,000 70 Replace motor demostic pump, 78 hp \$5,000 71 Replace motor					·	
Lounge, Wood Panel Wall \$4,050						. ,
49 Lounge, millwork \$4,500 50 Lounge, furniture, hard goods \$12,000 54 Lounge, Lighting \$7,950 75 FC Light Strips \$3,000 76 Replace motor domestic pump, 75 hp \$5,600 117 Replace motor domestic pump, 75 hp \$5,600 158 Recliner Lounge, outdoors, replace fabric \$5,724 159 Big Wicker, re-custion \$9,900		=				
Lourge, appliances	49					
S8 Lourge, Lighting \$7,950 75 FC Light Strips \$3,000 87 Lourge, lighting \$3,600 178 Replace motor demestic pump, 75 hp \$5,600 155 Recliner Lourge, outdoors \$7,290 156 Recliner Lourge, outdoors, replace fabric \$5,724 159 Big Wicker, re-sushion \$9,000	50					
75 FC Light Strips \$3,000 R2 Lounge lighting \$3,800 Replace motor domestic pump, 75 hp \$5,600 Replace motor domestic pump, 75 hp \$5,000 Replace motor Lounge, outdoors \$7,200 Recliner Lounge, outdoors, replace fabric \$5,724 Recliner Lounge, outdoors, replace fabric \$9,900 Recliner L	54	Lounge, furniture, hard goods	\$12,000			
87 Lounge, lighting \$3,600 117 Replace motor domestic pump, 75 hp \$5,600 115 Rediiner Lounge, outdoors \$7,280 115 Bediener Lounge, outdoors, replace fabric \$5,724 1159 Big Wricker, re-cushion \$9,900	58	Lounge, Lighting				
117 Replace motor domestic pump, 75 hp Ss.600 158 Redimer Lounge, datdoors, replace fabric SS.724 159 Big Wicker, re-cushion S9,900		FC Light Strips				
155 Redirer Lounge, outdoors, replace fabrio \$5,724 159 Big Wicker, re-cushion \$9,900						
156 Recliner Lounge, outdoors, replace fabric \$5,724 159 Big Wicker, re-cushion \$9,900						
159 Big Wicker, re-cushion \$9,900						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	159	Big Wicker, re-cushion	\$9,900			
Total Scheduled Replacements \$397.284						
Total Scheduled Replacements \$397.284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397.284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397.284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397.284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397.284						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397.284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888	1					
Total Scheduled Replacements \$397,284 Total Scheduled Replacements \$33,888						
	Total S	cheduled Replacements	\$397,284	Total S	Scheduled Replacements	\$33,888

20	Item	2046 - YEAR 20	\$	Item	2047 - YEAR 21	\$
32		Flat Screen TVs, wall mounted (25%)	\$6,000	44	Lobby, Front Counter, chairs	\$1,050
Media Room, lighting \$1,200 8		Area Rugs		56		\$900
Media Room. Ighthing						\$2,050
100 Rochtop AHU for Cornidors, repair \$60,000 144 Swimming pool finish, tuckpointing \$8 152 Swimming pool pumps \$5,200 164 Dog Park, 3rd Floor, furniture \$1 164 Dog Park, 3rd Floor, furniture \$1 165 Dog Park, 3rd Floor, furniture \$1 167 Dog Park, 3rd Floor, furniture \$1 167 Dog Park, 3rd Floor, furniture \$1 168 Dog Park, 3rd Floor, furniture \$1 1	95	Media Room, artwork		68	FC - rowing machine	\$1,100
Roeftep ArtIL for Carridors, repair \$58,000 144 Swimming pool finish, buckpointing \$58,000 145 Swimming pool pumps \$51 Swimming pool pumps \$51 Swimming pool pumps \$51 Swimming pool pumps \$52,000 \$64 Dog Park, 3rd Floor, turniture \$51 Swimming pool pumps \$52 Swimming pool pumps \$52 Swimming pool pumps \$52 Swimming pool pumps \$52 Swimming pool pumps \$53 Swimming pool pumps \$54 Swimming pool pumps \$55 Swimming pool pump	96	Media Room, lighting		85		\$1,200
	100	Rooftop AHU for Corridors, repair	\$59,000	144	Swimming pool finish, tuckpointing	\$6,390
	152			164		\$1,250
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$1						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements 578 975 Total Scheduled Replacements \$13						
Total Scheduled Replacements 578.975 Total Scheduled Replacements 513						
Total Scheduled Replacements 578.975 Total Scheduled Replacements 513						
Total Scheduled Replacements \$76.975 Total Scheduled Replacements 5:13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13.						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13.975 Total Scheduled Replacements						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13.975 Total Scheduled Replacements						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78.975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Total Scheduled Replacements \$78,975 Total Scheduled Replacements \$13						
Form Somewhat Control Wild Control I Foun Control (Control Control Con	Total S	cheduled Replacements	\$78 975	Total 9	Scheduled Replacements	\$13,940
	, otal O	ssa.sa nopiassimonio	ψ10,010	, otal C		Ψ10,940

Item	2048 - YEAR 22	\$	Item	2049 - YEAR 23	\$
20	Flat Screen TVs, wall mounted (25%)	\$6,000	2	Sliding Glass Doors to Balconies (10%)	\$223,440
45	Manager Office, furniture	\$8,000	4	Hallway Carpet (20%)	\$44,736
120	Domestic water pump, 20 hp	\$6,200	9	Mailroom, Carpet	\$2,724
121	Domestic water pump, 20 hp rebuild	\$2,200	10	Tile Floor, tuckpoint, 5%	\$1,980
122	Domestic water pump, 20 hp motor	\$2,200	11	Tile Floor, replace	\$216,767
123	Domestic water pump, 20 hp VFD	\$2,200	17	Hallway Suspended Ceiling	\$23,760
124	HW recirculation pump, 9th floor	\$3,500	18	Hallway Lighting, 25%	\$36,000
154	Spa, air pump	\$1,750	22	Wood Doors, with hardware, 25%	\$110,550
157	Big Wicker Sofa	\$2,100	23	HM Doors, single	\$99,325
158	Big Wicker Chairs	\$7,425	24	HM Doors, double	\$2,400
162	Dog Park, 3rd Floor, carpet	\$1,208	40	Lounge, 9th Floor, Carpet	\$20,688
			43	Lobby, Front Counter, computers	\$3,600
			52	Lounge, furniture, soft goods	\$45,000
			56	Lounge, flat screen TVs - (25%)	\$900
			59	Fitness Center, Carpet	\$6,720
			77	Lounge, 10th floor, carpet	\$6
			82	Lounge, furniture, soft goods	\$4,400
			84	Lounge, computers	\$2,800
			88	Media Room, 10th floor, carpet	\$6
			106	Replace condensor pump motor, 75 hp	\$5,600
			109	Cooling Water treatment system	\$10,750
			111	Rebuild domestic water booster pump	\$12,800
			112	Replace water pump motor, 75 hp	\$17,000
			113	Domestic water booster pump VFDs	\$5,600
			116	Rebuild domestic water booster pump	\$12,800
			117	Replace motor domestic pump, 75 hp	\$5,600
			118	Domestic water booster pump VFDs	\$17,000
			130	Exhaust Fan, 15hp, large	\$10,200
			131	Exhaust Fans, 10hp, medium	\$48,300
			132	Exhaust Fans, 7.5hp, small	\$10,200
			136	Elevator cab interiors	\$102,000
			138	Disrtibution Switchgear repairs	\$36,000
			139	Distrubution Transformer, 480v to 208v	\$395,250
			140	FCU, heat pump, for electrical rooms	\$43,350
Total	Scheduled Replacements	\$42,783	Total 9	Scheduled Replacements	\$1,578,252
, oral c	55.1525/04 Propiacomonio	ψ 7 Ζ,100	1 Otal C	50saaloa (topiasonionio	ψ1,010,202

Item	2050 - YEAR 24	\$	Item	2051 - YEAR 25	\$
5	Hallway Carpet (20%)	\$44,736	6	Hallway Carpet (20%)	\$44,736
20	Flat Screen TVs, wall mounted (25%)	\$6,000	56	Lounge, flat screen TVs - (25%)	\$900
29	Parcel collector, 9th floor	\$34,000	60	Fitness Center, Rubber Flooring	\$15,000
90	Media Room, furniture, soft goods	\$10,750	61	Fitness Center, Rubber Flooring (top)	\$12,000
94	Media Room, popcorn popper	\$1,000	71	FC - weight bench	\$2,000
143	Concrete, seal, around pool	\$1,590	72	FC - weights	\$4,500
150	Swimming pool filter	\$3,200	85	Lounge, flat screen TVs (50%)	\$1,200
153	Swimming pool heat exchanger	\$18,600	141	Key Trak system	\$31,500
156	Recliner Lounge, outdoors, replace fabric	\$5,724	147	Swimming pool waterline tile	\$3,850
159	Big Wicker, re-cushion	\$9,900	149	Spa waterline tile	\$792
160	Gas Barbeque Grills	\$2,325	152	Swimming pool pumps	\$5,200
100	Cas Barbeque Griiis	Ψ2,020	162	Dog Park, 3rd Floor, carpet	\$1,208
Total S	cheduled Replacements	\$137,825	Total S	Scheduled Replacements	\$122,886

Item	2052 - YEAR 26	\$	Item	2053 - YEAR 27	\$
7	Hallway Carpet (20%)	\$44,736	3	Balcony railing (25%)	\$184,500
20	Flat Screen TVs, wall mounted (25%)	\$6,000	8	Hallway Carpet (20%)	\$44,736
33	Wall Covering	\$2,100	56	Lounge, flat screen TVs - (25%)	\$900
34	Wall panels,mirror	\$1,000	57	Lounge, video projector	\$1,400
146		\$24,140	92		
146	Swimming white coat	\$24,140		Media Room, video projector	\$1,425
			93	Media Room, projector screen	\$325
Total	chadulad Panlacaments	¢77.076	Total	Scheduled Replacements	മറാവ വാഗ
างเลา S	cheduled Replacements	\$77,976	Total	оспечией періасетіенть	\$233,286

Item	2054 - YEAR 28	\$	Item 2055 - YEAR 29	\$
2	Sliding Glass Doors to Balconies (10%)	\$223,440	13 Hallway Wall Covering, w/base & signs (20%)	\$105,893
12	Hallway Wall Covering, w/base & signs (20%)	\$105,893	21 Hallway Artwork	\$16,500
20	Flat Screen TVs, wall mounted (25%)	\$6,000	43 Lobby, Front Counter, computers	\$3,600
32	Area Rugs	\$1,800	55 Lounge, artwork	\$1,750
117	Replace motor domestic pump, 75 hp	\$5,600	56 Lounge, flat screen TVs - (25%)	\$900
122	Domestic water pump, 20 hp motor	\$2,200	62 FC - treadmills	\$29,600
144	Swimming pool finish, tuckpointing	\$6,390	63 FC - ellipticals	\$8,400
154	Spa, air pump	\$1,750	64 FC - exercise bike, upright	\$1,200
162	Dog Park, 3rd Floor, carpet	\$1,208	65 FC - exercise bike, spin	\$2,050
			67 FC - stair stepper	\$2,400
			80 Lounge, kitchen appliances	\$1,475
			84 Lounge, computers	\$2,800
			85 Lounge, flat screen TVs (50%)	\$1,200
			86 Lounge, artwork	\$1,600
			94 Media Room, popcorn popper	\$1,000
			97 Cooling Towers, rebuild	\$118,700
			99 Cooling Towers fan VFDs	\$16,200
			105 Rebuild condensor water pump	\$12,800
			106 Replace condensor pump motor, 75 hp	\$5,600
			107 Condensor water pump VFDs	\$17,000
			112 Replace water pump motor, 75 hp 148 Spa white coat	\$17,000 \$3,230
			146 Spa write coat	\$3,230
Total S	cheduled Replacements	\$354,280	Total Scheduled Replacements	\$370,898
างเลาร	oneducu Nepiacements	φ304, ∠ 00	Total Sofieduled Inchiacements	φ <i>31</i> U,098

Item	2056 - YEAR 30	\$	Item	2057 - YEAR 31	\$
14	Hallway Wall Covering, w/base & signs (20%)	\$105,893	15	Hallway Wall Covering, w/base & signs (20%)	\$105,893
20	Flat Screen TVs, wall mounted (25%)	\$6,000	56	Lounge, flat screen TVs - (25%)	\$900
50	Lounge, appliances	\$2,800	162	Dog Park, 3rd Floor, carpet	\$1,208
114	Domestic water booster pump control	\$8,100			
119	Domestic water booster pump control	\$8,100			
135	Elevator cabs & doors, remodel	\$168,000			
152	Swimming pool pumps	\$5,200			
155	Recliner Lounge, outdoors	\$7,290			
156	Recliner Lounge, outdoors, replace fabric	\$5,724			
159	Big Wicker, re-cushion	\$9,900			
Total S	cheduled Replacements	\$327,007	Total S	Scheduled Replacements	\$108,000

Item	2058 - YEAR 32	\$	Item	2059 - YEAR 33	\$
16	Hallway Wall Covering, w/base & signs (20%)	\$105,893	1	Storefront Doors, 9th & 10th floors	\$8,400
20	Flat Screen TVs, wall mounted (25%)	\$6,000	2	Sliding Glass Doors to Balconies (10%)	\$223,440
36	Artwork	\$5,300	4	Hallway Carpet (20%)	\$44,736
95	Media Room, artwork	\$475	9	Mailroom, Carpet	\$2,724
163	Dog Park, 3rd Floor, glass surround	\$2,400	10	Tile Floor, tuckpoint, 5%	\$1,980
			18	Hallway Lighting, 25%	\$36,000
			22	Wood Doors, with hardware, 25%	\$110,550
			31	Chain Link Fence Storage, repair	\$42,000
			37	Bathroom Renovation, 1st, Men	\$6,500
			38	Bathroom Renovation, 1st, Women	\$6,500
			39	Lobby, 9th Floor, Tile	\$15,334
			40	Lounge, 9th Floor, Carpet	\$20,688
			44	Lobby, Front Counter, chairs	\$1,050
			46	Bathroom Renovation, 9th, Men	\$6,500
			47	Bathroom Renovation, 9th, Women	\$6,500
			48	Bathroom Renovation, fitness	\$6,500
			52	Lounge, furniture, soft goods	\$45,000
			56	Lounge, flat screen TVs - (25%)	\$900
			59	Fitness Center, Carpet	\$6,720
			66	FC - exercise bike, spin	\$2,050 \$1,100
			68 77	FC - rowing machine	\$1,100 \$6
			78	Lounge, 10th floor, carpet Lounge, bathroom renovation	\$6 \$13,000
			82	_	\$4,400
			85	Lounge, furniture, soft goods Lounge, flat screen TVs (50%)	\$4,400 \$1,200
			88	Media Room, 10th floor, carpet	\$1,200 \$6
			108	DHW tanks & heat exchangers	\$23,600
			108	Cooling Water treatment system	\$10,750
			110	Domestic water booster pumps, 75 hp	\$39,000
			111	Rebuild domestic water booster pump	\$12,800
			115	Domestic water booster pumps, 75 hp	\$39,000
			116	Rebuild domestic water booster pump	\$12,800
			117	Replace motor domestic pump, 75 hp	\$5,600
			126	1st Floor Lobby FCU HP	\$3,400
			127	1st Floor Maint. Shop FCU HP	\$2,975
			128	9th Floor FCU Heat Pumps	\$11,850
			129	10th Floor FCU Heat Pumps	\$8,900
			164	Dog Park, 3rd Floor, furniture	\$1,250
Total S	scheduled Replacements	\$120,068	Total S	Scheduled Replacements	\$785,709

Item	2060 - YEAR 34	\$	Item	2061 - YEAR 35	\$
5 20	Hallway Carpet (20%) Flat Screen TVs, wall mounted (25%)	\$44,736 \$6,000	6 42	Hallway Carpet (20%) Lobby Front Counter, millwork	\$44,736 \$1,750
45	Manager Office, furniture	\$8,000 \$8,000	42	Lobby, Front Counter, milwork Lobby, Front Counter, computers	\$3,600
90	Media Room, furniture, soft goods	\$10,750	53	Lounge, furniture, hard goods	\$20,000
94	Media Room, popcorn popper	\$1,000	56	Lounge, flat screen TVs - (25%)	\$900
121	Domestic water pump, 20 hp rebuild	\$2,200	57	Lounge, video projector	\$1,400
122	Domestic water pump, 20 hp motor	\$2,200	74	FC - Chairs, metal	\$600
123	Domestic water pump, 20 hp VFD	\$2,200	81	Lounge, millwork	\$1,275
143	Concrete, seal, around pool	\$1,590	83	Lounge, furniture, hard goods	\$9,875
150	Swimming pool filter	\$3,200	84	Lounge, computers	\$2,800
151	Swimming pool valves & plumbing	\$3,195	92	Media Room, video projector	\$1,425
154	Spa, air pump	\$1,750	100	Rooftop AHU for Corridors, repair	\$59,000
157	Big Wicker Sofa	\$2,100	106	Replace condensor pump motor, 75 hp	\$5,600
158	Big Wicker Chairs	\$7,425	112	Replace water pump motor, 75 hp	\$17,000
160	Gas Barbeque Grills	\$2,325	113	Domestic water booster pump VFDs	\$5,600
162	Dog Park, 3rd Floor, carpet	\$1,208	118	Domestic water booster pump VFDs	\$17,000
			144	Swimming pool finish, tuckpointing	\$6,390
			147	Swimming pool waterline tile	\$3,850
			149	Spa waterline tile	\$792
			152	Swimming pool pumps	\$5,200
Total S	cheduled Replacements	\$99,879	Total S	Scheduled Replacements	\$208,793
	•	,-		•	,

Item	2062 - YEAR 36	\$	Item	2063 - YEAR 37	\$
7	Hallway Carpet (20%)	\$44,736	8	Hallway Carpet (20%)	\$44,736
20	Flat Screen TVs, wall mounted (25%)	\$6,000	56	Lounge, flat screen TVs - (25%)	\$900
32	Area Rugs	\$1,800	85	Lounge, flat screen TVs (50%)	\$1,200
51	Lounge, pool table	\$5,500	161	Fire Pit	\$5,000
89	Media Room, millwork	\$25	162	Dog Park, 3rd Floor, carpet	\$1,208
91	Media Room, furniture, hard goods	\$825		•	
146	Swimming white coat	\$24,140			
156	Recliner Lounge, outdoors, replace fabric	\$5,724			
159	Big Wicker, re-cushion	\$9,900			
159	big Wicker, re-cushion	\$9,900			
1					
Total 9	cheduled Replacements	\$98,650	Total	Scheduled Replacements	\$53,044
, otal c	onoughou replacements	ψου,υου	i otal c	ronouanou rropiacionionto	ψυυ,υ 44

Item	2064 - YEAR 38	\$	Item	2065 - YEAR 39	\$
2	Sliding Glass Doors to Balconies (10%)	\$223,440	54	Lounge, furniture, hard goods	\$12,000
20	Flat Screen TVs, wall mounted (25%)	\$6,000	56	Lounge, flat screen TVs - (25%)	\$900
35	Lounge, furniture, hard goods	\$13,600	94	Media Room, popcorn popper	\$1,000
117	Replace motor domestic pump, 75 hp	\$5,600	148	Spa white coat	\$3,230
136	Elevator cab interiors	\$102,000			
Total S	cheduled Replacements	\$350,640	Total C	cheduled Replacements	\$17,130

INTENTIONALLY LEFT BLANK

SECTION D - CONDITION ASSESSMENT

General Comments. MillerDodson Associates conducted a Reserve Study at Sample High Rise - Residential Common Elements in December 2020. Sample High Rise - Residential Common Elements is in generally excellent condition for a residential condominium constructed in 2010. A review of the Replacement Reserve Inventory will show that we are anticipating most of the components achieving their normal economic lives.

Residential Common Element (RCE) - This area includes the 9th floor lobby, lounge, and fitness center, restrooms, and mailroom. Also the 10th floor lounge and media room. From the 9th floor to the 42nd floor all hallway finishes are included. Elevator lobbies for the 2nd thru 9th floors are included. On the exterior the sliding doors to balconies, glass exit doors from the 9th and 10th floors, and the pool, spa, fire pit, and charcoal grills on the 9th floor. The 4 elevators, penthouse mechanical equipment, and electrical equipment in electric rooms from the 9th through 43 floors are included.

The following comments pertain to the larger, more significant components in the Replacement Reserve Inventory and to those items that are unique or deserving of attention because of their condition or the manner in which they have been treated in the Replacement Reserve Analysis or Inventory.

IMPORTANT NOTE: This Condition Assessment is based upon visual and apparent conditions of the common elements of the community which were observed by the Reserve Analyst at the time of the site visit. This Condition Assessment does not constitute, nor is it a substitute for, a professional Structural Evaluation of the buildings, amenities, or systems. MillerDodson strongly recommends that the Association retain the services of a Structural Engineer to conduct thorough and periodic evaluations of the buildings, balconies, and any other structural components of the buildings and amenities of the Association.

General Condition Statements.

Excellent. 100% to 90% of Normal Economic Life expected, with no appreciable wear or defects.

Good. 90% to 60% of Normal Economic Life expected, minor wear or cosmetic defects found. Normal maintenance should be expected. If performed properly, normal maintenance may increase the useful life of a component. Otherwise, the component is wearing normally.

Fair. 60% to 30% of Normal Economic Life expected moderate wear with defects found. Repair actions should be taken to extend the life of the component or to correct repairable defects and distress. Otherwise, the component is wearing normally.

Marginal. 30% to 10% of Normal Economic Life expected, with moderate to significant wear or distress found. Repair actions are expected to be cost-effective for localized issues, but normal wear and use are evident. The component is reaching the end of the Normal Economic Life.

Poor. 10% to 0% of Normal Economic Life expected, with significant distress and wear. Left unattended, additional damage to underlying structures is likely to occur. Further maintenance is unlikely to be cost-effective.

(Continued on next page)

EXTERIOR ITEMS

Glass Sliding Glass Doors. The sliding glass doors have some of the same features and failure problems and the glass exterior, but they also fail at the track system which allows them to move and operate. The study assumes that ten percent of the sliding glass doors will fail and be replaced in 5-year intervals.



INTERIOR ITEMS

Carpet. The commercial carpet of this construction in this type of application has a typical service life of 7 to 10 years.

To extend the carpet's life, the Association must continue with a comprehensive maintenance program that includes regular vacuuming, spot and spill removal, interim cleaning of high-traffic areas, and regularly scheduled cleanings. It is also recommended that all entrances be fitted with walk-off mats to trap soil.

Ceramic Tile. The Association maintains ceramic tile in the lobby, elevator lobbies, corridors, entrances, and restrooms. The overall condition of the ceramic tile appears to be in good condition.

Regular cleaning is recommended to help maintain the ceramic tile's condition. The tile can further be protected by installing dirt-catching walk-off mats at all building entrances.

Fabric Wall Covering. All of the hallways have a fabric wall covering material. This material does last longer than paint on the same surface but will require replacement about every 15 years. This replacement will cost more than painting of the same area, so the association should decide when replacement is required if the material should be replaced with painting. This work has also been staggered over a 5 year period to coincide with the carpet replacement.

Furniture. The association has numerous furniture items in the lobbies, lounge areas, media room, and outside pool area. This furniture will require replacement, sometimes from wear and tear failure and sometimes simply for aesthetic reasons.

9th Floor







10th Floor















BUILDING SYSTEMS

HVAC Control System. A pneumatic, electronic, computerized HVAC control system controls the facility's central heating and cooling plant. Pneumatic systems of this type have a service life of 30 years. Electronic Computerized systems of this type have a service life of 15 to 20 years.

Rooftop AHU. There is a large rooftop air handling unit that heats and cools the building corridors. It utilizes?steam for heating and cools through air conditioning compressors and air cooled condensers. These large?units will last 20-25 years with a mid-life rebuild and then they are replaced. Because this unit is roof mounted, the same size and weight issues are found as for the cooling towers. The unit will be at the end of life when?the cooling section rusts to the point that the panels rust through. Instead of replacement, a major overhaul?of all metal panels can be accomplished in conjunction with a mechanical equipment rebuild to keep from?needing to remove the unit from the roof.





Heating Boiler. Heat to the building is supplied by 2, hot water low-pressure steam boilers located in the basement. The boilers appear to be in good condition.









Our assessment of the condition of the boiler is based on the boiler's age, the conditions seen during the site visit, the reported maintenance history of the boiler, and conversations with maintenance personnel. Boiler systems typically have a service life of 20 to 40 years.

When replacing the central boiler system is necessary, we recommend that the community consider installing a bank of modular boilers. Using multiple boilers will allow the operators to stage their use to match heating requirements in the building and increase the overall operating efficiency of the heating system.

For additional information about modular boiler systems, please see the link at http://mdareserves.com/resources/links/building-system.

Cooling Tower. The facility has a central cooling system generates and distributes chilled water to the individual units and other interior areas. The atmosphere rejects heat from the system through the cooling tower system. The cooling tower system appears to be in good condition.





Cooling towers have a very large impact on the operating efficiency of a central air conditioning system. Therefore, following a comprehensive maintenance program is important to keep the tower operating at peak efficiency. It is also a good practice to replace the cooling tower and chiller systems at the same time. Cooling towers have a typical service life of 20 to 25 years.

November 11, 2025

Air Handlers. The facility includes air handlers as part of the heating, ventilating, and air-conditioning system. The air handlers typically include a blower, heating or cooling coils, filter racks, operating controls, and dampers. Conditioned air from the air handler is distributed through the building through a ductwork system. We consider the ductwork a long-life item and have excluded it from the Reserve Analysis.


Individual components within the air handler will require periodic replacement. We have assumed these replacements are maintenance items and have excluded them from the Reserve Analysis. The air handler itself has a service life of 20 to 40 years. If fan, motor, and coil replacements are performed as needed, the casings of these systems can last significantly longer.

Water Source Heat Pumps. The Association maintains water-source heat pumps. We have assumed that these units will have a useful life of 15 to 20 years.

Pumps, Fans, and Motors. The Association maintains an assortment of fans, motors, pumps, and valves that are part of the central heating and cooling plant. Rather than inventorying and listing these separately, we have assumed an incremental approach to their replacement and provided a partial replacement allowance every five years.

Elevators. Since the elevators are being maintained by a "premium" elevator maintenance contract the majority of the major components are replaced under this contract. What remains are items that become obsolete or aesthetic components. The reserve study has left the controls along with the door mechanisms as these become obsolete. Also included are the cab and cab door remodels along with the interiors. These items will wear with use. If the "premium" contract is not continued then additional funding should be added back into the reserve study to cover the cost of the major components. The estimated cost of replacing the elevator components remaining in the study has been developed utilizing R.S. Means Construction Cost Data and through periodic repair quotes. These costs are included to reflect the obsolescence that occurs with elevator systems. Even though the systems may be functioning well at this time, parts for most mechanical control systems are becoming increasingly hard to find. Parts availability becomes a major consideration that forces a replacement decision.

When this work is ultimately accomplished, the elevators will have to be brought into compliance with the latest safety code requirements. This work typically entails upgrading door operating mechanisms, replacing elevator call systems, and installation of emergency phones. A prudent amount has been included in anticipation of these problems.





Electrical Switchgear. There is switchgear for distribution 480v power throughout the entire building on the1st floor and there are also power distribution panels for 120/208v power to the residential floors and for 480vpower in the penthouse for mechanical equipment. The switchgear has a long life but changes in equipment technology can result in the inability of obtaining replacement parts and subsequently to switchgear must be replaced. History in this area shows that in about 30 years the distribution breakers will require power panel replacements and the switchgear will require replacement in 50 years.

Electrical Transformers. Transformers are used to reduce the 480v power throughout the building to120/208v. These transformers experience the majority of failures due to overheating, so with electrical room cooling this failure timeframe should be extended. The study assumes the transformers will last for 30 years before replacement.






RECREATION ITEMS

Swimming Pool and Spa. The community operates an outdoor pool and spa of concrete construction and concrete deck. Listed below are the major components of the pool facilities:

- Pool Shell. The shell for the swimming pool is incorporated into the 9th floor structure and becomes the ceiling for the 8th floor of the garage. It is not expected the pool shell will require replacement but will see surface refinishing as covered below.
- Pool Deck. The pool has a concrete deck. The deck should have sealant applied similar to the garage floor surface to minimize the potential of cracking and spalling.
- Pool and Spa surface. The pool is coated with glass tiles. The spa was previously coated with glass tiles but the tiles were recently removed and what is commonly referred to as a "white coat" finish was applied, although the actual color is black. The glass tiles have a nice aesthetic appearance but are high maintenance. The study recommends maintaining to the end of their useful life but to replace the pool glass tiles with a quality white coat finish similar to the spa work that was performed. The pool color could be a white or a blue finish. The white coat can achieve a high-quality look but will require only minor tuck-pointing along with a recoating throughout its lifecycle.
- Waterline Tile. The waterline tile is in excellent condition. We have assumed that the waterline tile will be replaced or restored about every 10 years.
- Pump and Filter System. The filter system is in excellent operating condition. We have assumed a service life of 20 years for the filter systems and 10 years for the pumps.















Dog Park. 9th Floor Pool Table.

This Condition Assessment is based upon our visual survey of the property. The sole purpose of the visual survey was an evaluation of the common and limited common elements of the property to ascertain their remaining useful life and replacement cost. Our evaluation assumed that all components met building code requirements in force at the time of construction. Our visual survey was conducted with care by experienced persons, but no warranty or guarantee is expressed or implied.

End of Condition Assessment

INTENTIONALLY LEFT BLANK


SECTION A - FINANCIAL ANALYSIS

The Sample High Rise - Skyclub Replacement Reserve Analysis uses the Cash Flow Method (CFM) to calculate Replacement Reserve funding for the periodic replacement of the 21 Projected Replacements identified in the Replacement Reserve Inventory.

\$5,639 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR THE STUDY YEAR, 2026 \$0.95 Per unit (average), minimum monthly funding of Replacement Reserves

We recommend the Association adopt a Replacement Reserve Funding Plan based on the annual funding recommendation above. Inflation adjusted funding for subsequent years is shown on Page A3.5.

Sample High Rise - Skyclub reports a Starting Balance of \$27,787 and Annual Funding totaling \$4,452, which is inadequate to fund projected replacements starting in 2050. See Page A3.3 for a more detailed evaluation.



REPLACEMENT RESERVE ANALYSIS - GENERAL INFORMATION

The Sample High Rise - Skyclub Replacement Reserve Analysis calculations of recommended funding of Replacement Reserves by the Cash Flow Method (CFM) and the evaluation of the Current Funding are based upon the same Study Year, Study Period, Beginning Balance, Replacement Reserve Inventory and Level of Service.

2026 STUDY YEAR

The Association reports that their accounting year begins on January 1, and the Study Year, the first year evaluated by the Replacement Reserve Analysis, begins on January 1, 2026.

40 Years | STUDY PERIOD

The Replacement Reserve Analysis evaluates the funding of Replacement Reserves over a 40-year Study Period

\$27,787 | STARTING BALANCE


The Association reports Replacement Reserves on Deposit totaling \$27,787 at the start of the Study Year.

Level Two | LEVEL OF SERVICE

The Replacement Reserve Inventory has been developed in compliance with the National Reserve Study Standards for a Level Two Study, as defined by the Community Associations Institute (CAI).

\$242,186 | REPLACEMENT RESERVE INVENTORY - PROJECTED REPLACEMENTS

The Sample High Rise - Skyclub Replacement Reserve Inventory identifies 21 items that will require periodic replacement, that are to be funded from Replacement Reserves. We estimate the cost of these replacements will be \$242,186 over the 40-year Study Period. The Projected Replacements are divided into 1 major categories starting on Page B3.3. Pages B3.1-B3.2 provide detailed information on the Replacement Reserve Inventory.



November 11, 2025

UPDATING OF THE FUNDING PLAN

The Association has a responsibility to review the Funding Plan annually. The review should include a comparison and evaluation of actual reserve funding with recommended levels shown on Page A3.4 and A3.5. The Projected Replacements listed on Page C3.2 should be compared with any replacements accomplished and funded from Replacement Reserves. Discrepancies should be evaluated and if necessary, the Reserve Study should be updated or a new study commissioned. We recommend annual increases in replacement reserve funding to account for the impact of inflation. Inflation Adjusted Funding is discussed on Page A3.5.

UPDATING OF THE REPLACEMENT RESERVE STUDY

At a minimum, the Replacement Reserve Study should be professionally updated every three to five years or after completion of a major replacement project. Updating should also be considered if during the annual review of the Funding Plan, discrepancies are noted between projected and actual reserve funding or replacement costs. Updating may also be necessary if there is a meaningful discrepancy between the actual inflation rate and the inflation rate used for the Inflation Adjusted Funding of Replacement Reserves on Page A3.5.

ANNUAL EXPENDITURES AND CURRENT FUNDING

The annual expenditures that comprise the \$242,186 of Projected Expenditures over the 40-year Study Period and the impact of the Association continuing to fund Replacement Reserves at the current level are detailed in Table 3.

3 - Table of Annual Expenditures and Current Funding Data - Years 0 through 39										
Year	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035
Starting Balance	\$27,787									
Projected Replacements					(\$6,343)		(\$12,750)			(\$7,340
Annual Deposit	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452
End of Year Balance	\$32,239	\$36,691	\$41,143	\$45,595	\$43,705	\$48,157	\$39,859	\$44,311	\$48,763	\$45,875
Cumulative Expenditures					(\$6,343)	(\$6,343)	(\$19,093)	(\$19,093)	(\$19,093)	(\$26,433
Cumulative Receipts	\$32,239	\$36,691	\$41,143	\$45,595	\$50,047	\$54,499	\$58,951	\$63,403	\$67,855	\$72,307
Year	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045
Projected Replacements					(\$40,748)	(\$15,100)	(\$7,200)	(\$7,000)	(\$6,550)	(\$1,200
Annual Deposit	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452
End of Year Balance	\$50,327	\$54,779	\$59,231	\$63,683	\$27,387	\$16,739	\$13,991	\$11,443	\$9,345	\$12,597
Cumulative Expenditures	(\$26,433)	(\$26,433)	(\$26,433)	(\$26,433)	(\$67,180)	(\$82,280)	(\$89,480)	(\$96,480)	(\$103,030)	(\$104,230
Cumulative Receipts	\$76,759	\$81,211	\$85,663	\$90,115	\$94,567	\$99,019	\$103,471	\$107,923	\$112,375	\$116,827
Year	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055
Projected Replacements	(\$8,100)		(\$4,500)		(\$42,219)		(\$7,200)			
Annual Deposit	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452
End of Year Balance	\$8,949	\$13,401	\$13,353	\$17,805	(\$19,962)	(\$15,510)	(\$18,258)	(\$13,806)	(\$9,354)	(\$4,902
Cumulative Expenditures	(\$112,330)	(\$112,330)	(\$116,830)	(\$116,830)	(\$159,049)	(\$159,049)	(\$166,249)	(\$166,249)	(\$166,249)	(\$166,249
Cumulative Receipts	\$121,279	\$125,731	\$130,183	\$134,635	\$139,087	\$143,539	\$147,991	\$152,443	\$156,895	\$161,347
Year	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065
Projected Replacements	(\$5,550)				(\$36,248)		(\$22,300)		(\$4,500)	(\$7,340
Annual Deposit	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452	\$4,452
End of Year Balance	(\$6,000)	(\$1,548)	\$2,905	\$7,357	(\$24,439)	(\$19,987)	(\$37,835)	(\$33,383)	(\$33,431)	(\$36,319
Cumulative Expenditures	(\$171,799)	(\$171,799)	(\$171,799)	(\$171,799)	(\$208,046)	(\$208,046)	(\$230,346)	(\$230,346)	(\$234,846)	(\$242,186
Cumulative Receipts	\$165,799	\$170,251	\$174,703	\$179,155	\$183,607	\$188,059	\$192,511	\$196,963	\$201.415	\$205,867

EVALUATION OF CURRENT FUNDING

The evaluation of Current Funding (Starting Balance of \$27,787 & annual funding of \$4,452), is done in today's dollars with no adjustments for inflation or interest earned on Replacement Reserves. The evaluation assumes Replacement Reserves will only be used for the 21 Projected Replacements identified in the Replacement Reserve Inventory and that the Association will continue Annual Funding of \$4,452 throughout the 40-year Study Period.

Annual Funding of \$4,452 is approximately 79 percent of the \$5,639 recommended Annual Funding calculated by the Cash Flow Method for 2026, the Study Year.

See the Executive Summary for the Current Funding Statement.


CASH FLOW METHOD FUNDING

\$5,639 RECOMMENDED REPLACEMENT RESERVE FUNDING FOR 2026

\$0.95 Per unit (average), minimum monthly funding of Replacement Reserves

Recommended Replacement Reserve Funding has been calculated using the Cash Flow Method (also called the Straight Line or Threshold Method). This method calculates a constant annual funding between peaks in cumulative expenditures, while maintaining a Minimum Balance (threshold) in the Peak Years.

- **Peak Years.** The First Peak Year occurs in 2062 with Replacement Reserves on Deposit dropping to the Minimum Balance after the completion of \$230,346 of replacements from 2026 to 2062. Recommended funding is anticipated to decline in 2063. Peak Years are identified in Chart 4 and Table 5.
- Threshold (Minimum Balance). The calculations assume a Minimum Balance of \$6,100 will always be held in reserve, which is calculated by rounding the 12-month 40-year average annual expenditure of \$6,055 as shown on Graph #2.
- Cash Flow Method Study Period. Cash Flow Method calculates funding for \$242,186 of expenditures over the 40-year Study Period. It does not include funding for any projects beyond 2065 and in 2065, the end of year balance will always be the Minimum Balance.



INFLATION ADJUSTED FUNDING

The Cash Flow Method calculations on Page A4 have been done in today's dollars with no adjustment for inflation. At MillerDodson, we believe that long-term inflation forecasting is effective at demonstrating the power of compounding, not at calculating appropriate funding levels for Replacement Reserves. We have developed this proprietary model to estimate the short-term impact of inflation on Replacement Reserve funding.

\$5,639 2026 - CASH FLOW METHOD RECOMMENDED FUNDING

The 2026 Study Year calculations have been made using current replacement costs \$5,769 2027 - 2.3% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2027 funding based on three assumptions:

- Starting Balance totaling \$33,426 on January 1, 2027.
- No Expenditures from Replacement Reserves in 2027.

\$5,902 2028 - 2.3% INFLATION ADJUSTED FUNDING


A new analysis calculates the 2028 funding based on three assumptions:

- Starting balance of approximately \$39,196 = 2028 Starting Balance \$33,426, plus Inflation Adjusted Funding \$5,769 for 2027, minus \$0 2027 Inflation Adjusted Cost.
- No Expenditures from Replacement Reserves in 2028.

\$6,038 2029 - 2.3% INFLATION ADJUSTED FUNDING

A new analysis calculates the 2029 funding based on three assumptions:

- Starting balance of approximately \$45,097 = 2029 Starting Balance \$39,196, plus Inflation Adjusted Funding \$5,902 for 2028, minus \$0 2028 Inflation Adjusted Cost.
- No Expenditures from Replacement Reserves in 2029.



Year Four and Beyond

The inflation-adjusted funding calculations outlined above are not intended to be a substitute for periodic evaluation of common elements by an experienced Reserve Analyst. Industry Standards, lender requirements, and many state and local statutes require a Replacement Reserve Study to be professionally updated every 3 to 5 years.

Inflation Adjustment

Prior to approving a budget based upon the 2027, 2028 and 2029 inflation-adjusted funding calculations above, the 2.30 percent base rate of inflation used in our calculations should be compared to rates published by the Bureau of Labor Statistics. If there is a significant discrepancy (over 1 percentage point), contact MillerDodson Associates prior to using the Inflation Adjusted Funding.

Interest on Reserves

The recommended funding calculations do not account for interest earned on Replacement Reserves. In 2026, based on a 1.00 percent interest rate, we estimate the Association may earn \$306 on an average balance of \$30,607, \$363 on an average balance of \$36,311 in 2027, and \$421 on \$42,146 in 2028. The Association may elect to attribute 100 percent of the earned interest to Reserves, resulting in a reduction in the 2026 funding from \$5,639 to \$5,333 (a 5.42 percent reduction), \$5,769 to \$5,406 in 2027 (a 6.29 percent reduction), and \$5,902 to \$5,480 in 2028 (a 7.14 percent reduction).

November 11, 2025

REPLACEMENT RESERVE STUDY - SUPPLEMENTAL COMMENTS

Maryland's new Reserves and Reserve Study Law, HB-107, is intended to ensure that adequate Reserve Funding is available for capital repair and replacement projects when it is needed. This is done by funding the Reserve Fund annually. The law requires that the Recommended Annual Reserve Funding amount in the most recent Reserve Study be included in the Association's annual budgets. If this is an Association's "initial" (first) professionally conducted Reserve Study, HB-107 gives the Association up to three (3) fiscal years following the fiscal year in which the Reserve Study was completed, to attain the Annual Reserve Funding level recommended in the initial Reserve Study.

SECTION B - REPLACEMENT RESERVE INVENTORY

PROJECTED REPLACEMENTS. Sample High Rise - Skyclub - Replacement Reserve Inventory identifies 21 items
that are Projected Replacements and the periodic replacements of these items are scheduled for funding from
Replacement Reserves. The Projected Replacements have an estimated one-time replacement cost of
\$121,774. Cumulative Replacements totaling \$242,186 are scheduled in the Replacement Reserve Inventory over
the 40-year Study Period. Cumulative Replacements include those components that are replaced more than once
during the period of the study.

Projected Replacements are the replacement of commonly-owned physical assets that require periodic replacement and whose replacement is to be funded from Replacement Reserves.

- **TAX CODE.** The United States Tax Code grants favorable tax status to Replacement Reserves, conditioned on expenditures being made within certain guidelines. These guidelines typically exclude maintenance activities, minor repairs, and capital improvements.
- **EXCLUDED ITEMS.** Some of the items contained in the Replacement Reserve Inventory are 'Excluded Items'. Multiple categories of items are typically excluded from funding by Replacement Reserves, including but not limited to:

Value. Items with a replacement cost of less than \$1000 and/or a normal economic life of less than 3 years are typically excluded from funding from Replacement Reserves. This exclusion should reflect the Association policy on the administration of Replacement Reserves. If the Association has selected an alternative level, it will be noted in the Replacement Reserve Inventory - General Comments on Page B3.2.

Long-lived Items. Items are excluded from the Replacement Reserve Inventory when items are properly maintained and are assumed to have a life equal to the property.

Unit Improvements. Items owned by a single unit and where the items serve a single unit are generally assumed to be the responsibility of that unit, not the Association.

Other Non-Common Improvements. Items owned by the local government, public and private utility companies, the United States Postal Service, Master Associations, state and local highway authorities, etc., may be installed on property that is owned by the Association. These types of items are generally not the responsibility of the Association and are excluded from the Replacement Reserve Inventory.

- **CATEGORIES.** The 21 items included in the Sample High Rise Skyclub Replacement Reserve Inventory are divided into 1 major categories. Each category is printed on a separate page, beginning on page B3.3.
- **LEVEL OF SERVICE.** This Replacement Reserve Inventory has been developed in compliance with the standards established for a Level 2 Update, as defined by the National Reserve Study Standards, established in 1998 by the Community Associations Institute, which states:

This study has been performed as a Level 2 Update with Site Visit/On-Site Review as defined by the Community Associations Institute's, National Reserve Study Standards. As such, the component inventory is based on the study that was performed by . This inventory was adjusted to reflect changes provided by the Community Manager and/or the Board of Directors, or adjustments made based on the site visit and visual assessment performed by the Analyst. The analysis, including fund status and funding plan, is developed from the adjusted inventory.

REPLACEMENT RESERVE INVENTORY - GENERAL INFORMATION (CONT'D)

 INVENTORY DATA. Each of the 21 Projected Replacements listed in the Replacement Reserve Inventory includes the following data:

Item Number. The Item Number is assigned sequentially and is intended for identification purposes only.

Item Description. We have identified each item included in the Inventory. Additional information may be included in the Comments section at the bottom of each page of the Inventory.

Units. We have used standard abbreviations to identify the number of units including SF-square feet, LF-lineal feet, SY-square yard, LS-lump sum, EA-each, and PR-pair. Non-standard abbreviations are noted in the Comments section at the bottom of the page.

Number of Units. The methods used to develop the quantities are discussed in "Level of Service" above.

Unit Replacement Cost. We use four sources to develop the unit cost data shown in the Inventory; actual replacement cost data provided by the client, information provided by local contractors and suppliers, industry standard estimating manuals, and a cost database we have developed based upon our detailed interviews with contractors and service providers who are specialists in their respective lines of work.

Normal Economic Life (Years). The number of years that a new and properly installed item should be expected to remain in service.

Remaining Economic Life (Years). The estimated number of years before an item will need to be replaced. In "normal" conditions, this could be calculated by subtracting the age of the item from the Normal Economic Life of the item, but only rarely do physical assets age "normally". Some items may have longer or shorter lives depending on many factors such as environment, initial quality of the item, maintenance, etc.

Total Replacement Cost. This is calculated by multiplying the Unit Replacement Cost by the Number of Units.

- **PARTIAL FUNDING.** Items may have been included in the Replacement Reserve Inventory at less than 100 percent of their full quantity and/or replacement cost. This is done on items that will never be replaced in their entirety, but which may require periodic replacements over an extended period of time. The assumptions that provide the basis for any partial funding are noted in the Comments section.
- **REMAINING ECONOMIC LIFE GREATER THAN 40 YEARS.** The calculations do not include funding for initial replacements beyond 40 years. These replacements are included in this Study for tracking and evaluation. They should be included for funding in future Studies, when they enter the 40-year window.
- ACCURACY OF THE ANALYSIS. The accuracy of the Replacement Reserve Analysis is dependent upon expenditures from Replacement Reserves being made ONLY for the 21 Projected Replacements specifically listed in the Replacement Reserve Inventory. The inclusion/exclusion of items from the Replacement Reserve Inventory is discussed on Page B3.1.

November 11, 2025

	RIOR ITEMS CTED REPLACEMENTS						Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
1	Tile Floor, tuckpoint, 20%	sf	139	\$7.50	10	4	\$1,043
2	Tile Floor, replace	sf	696	\$41.00	30	24	\$28,536
	Flooring, wood						EXCLUDED
	Flooring, wood						EXCLUDED
3	Carpet	sf	1,200	\$6.00	10	6	\$7,200
4	Sliding Glass Doors, single	ea	2	\$3,500.00	25	17	\$7,000
5	Wood Panels, wall covering	sf	80	\$21.00	20	14	\$1,680
6	Wood Doors	ea	5	\$825.00	20	14	\$4,125
7	Throw rugs	sf	248	\$5.00	15	9	\$1,240
8	Bathroom Renovations	ea	2	\$6,500.00	20	14	\$13,000
9	Kitchen Renovation	ls	1	\$5,500.00	24	18	\$5,500
10	Kitchen Appliances	ls	1	\$1,050.00	12	6	\$1,050
11	Millwork	ls	1	\$1,500.00	21	15	\$1,500
12	Wine Storage Cabinets	ls	1	\$2,600.00	21	15	\$2,600
13	WIne Storage Cabinets (new)	ls	1	\$2,600.00	21	20	\$2,600
14	Window Coverings	ls	1	\$6,100.00	15	9	\$6,100
15	Furniture, soft goods	ls	1	\$5,300.00	10	4	\$5,300
16	Furniture, hard goods	ls	1	\$11,000.00	21	15	\$11,000
17	Pool Table	ea	1	\$5,500.00	21	20	\$5,500
			Ren	lacement Costs -	Page 9	Subtotal	\$104,974

COMMENTS

- Flooring, wood [01/21/2021] excluded per board
- Flooring, wood [01/21/2021] excluded per board
- Item #13: WIne Storage Cabinets (new) New Wine Storage Cabinets installed in 2017
- Item #15: Furniture, soft goods Furniture soft goods include (2) sectional sofas and (6) throw pillows
- Item #16: Furniture, hard goods Furniture hard goods include (8) swivel chairs, (14) bar stools, (1) wood bench, (3) coffee tables, (5) planters, and (1) wallhung mirror
- Item #17: Pool Table New game/meeting table installed in 2016.

November 11, 2025

	RIOR ITEMS - (cont.)						Economic Life (yrs) Economic Life (yrs)
ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
18	Flat panel TV - 80" screen	ea	1	\$4,500.00	8	6	\$4,500
19	Heat Pump, 60k BTU	ea	1	\$4,800.00	20	14	\$4,800
20	Exhaust Fan	ea	1	\$1,200.00	25	19	\$1,200
21	Recessed ceiling & track lights	ea	42	\$150.00	20	14	\$6,300

Replacement Costs - Page Subtotal \$16,800

COMMENTS

• Item #18: Flat panel TV - 80" screen - New big screen TV was installed in 2016

November 11, 2025

VALUATION EXCLUSIONS Excluded Items					
Excluded Items ITEM	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL REL	REPLACEMENT COST (S) EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED

VALUATION EXCLUSIONS

- Valuation Exclusions. For ease of administration of the Replacement Reserves and to reflect accurately how Replacement Reserves are administered, items with a dollar value less than \$1000 have not been scheduled for funding from Replacement Reserve. Examples of items excluded by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

LONG-LIFE EXCLUSIONS						
Excluded Items						
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
Building foundation(s)	SINIT	OF SIMILE	υσυ (ψ)	NEL	NEE	EXCLUDED
Concrete floor slabs (interior)						EXCLUDED
Wall, floor, and roof structure						EXCLUDED
Common element electrical services						EXCLUDED
Electrical wiring						EXCLUDED
Water piping at common facilities						EXCLUDED
Waste piping at common facilities						EXCLUDED
Gas services at common facilities						EXCLUDED
Trash chute						EXCLUDED
Stainless steel pool fixtures						EXCLUDED
·						

LONG-LIFE EXCLUSIONS

- Long Life Exclusions. Components that when properly maintained, can be assumed to have a life equal to the property as a whole, are normally excluded from the Replacement Reserve Inventory. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- Exterior masonry is generally assumed to have an unlimited economic life, but periodic repointing is required, and we have
 included this for funding in the Replacement Reserve Inventory.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

UNIT IMPROVEMENTS EXCLUSIONS Excluded Items						
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
Sanitary sewers serving one unit			(1)			EXCLUDED
Electrical wiring serving one unit						EXCLUDED
Cable TV service serving one unit						EXCLUDED
Telephone service serving one unit						EXCLUDED
Gas service serving one unit						EXCLUDED
Unit interior						EXCLUDED

UNIT IMPROVEMENTS EXCLUSIONS

- Unit improvement Exclusions. We understand that the elements of the project that relate to a single unit are the responsibility of that unit owner. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

UTILITY EXCLUSIONS Excluded Items					
UTILITY EXCLUSIONS Excluded Items ITEM	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$) NE	EL REL	REPLACEMENT COST (\$) EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED EXCLUDED

UTILITY EXCLUSIONS

- Utility Exclusions. Many improvements owned by utility companies are on property owned by the Association. We have assumed that repair, maintenance, and replacements of these components will be done at the expense of the appropriate utility company. Examples of items excluded from funding Replacement Reserves by this standard are listed above.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

MAINTENANCE AND REPAIR EXCLUSIONS						
Excluded Items			UNIT			
ITEM ITEM # DESCRIPTION	UNIT	NUMBER OF UNITS	REPLACEMENT COST (\$)	NEL	REL	REPLACEMENT COST (\$)
Striping of parking spaces			3331 (4)			EXCLUDED
Numbering of parking spaces						EXCLUDED
Interior painting						EXCLUDED
Janitorial service						EXCLUDED
Repair services						EXCLUDED
Partial replacements						EXCLUDED
Capital improvements						EXCLUDED

MAINTENANCE AND REPAIR EXCLUSIONS

- Maintenance activities, one-time-only repairs, and capital improvements. These activities are NOT appropriately funded from Replacement Reserves. The inclusion of such component in the Replacement Reserve Inventory could jeopardize the special tax status of ALL Replacement Reserves, exposing the Association to significant tax liabilities. We recommend that the Board of Directors discuss these exclusions and Revenue Ruling 75-370 with a Certified Public Accountant.
- Examples of items excluded from funding by Replacement Reserves are listed above. The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

November 11, 2025

Government, roadways and parking EXCLUDED	GOVE	RNMENT EXCLUSIONS					
Government, roadways and parking EXCLUDED	ITEM #	ITEM DESCRIPTION	UNIT	NUMBER OF UNITS	UNIT REPLACEMENT COST (\$)	NEL RI	REPLACEMENT EL COST (\$)
Government, sidewalks and curbs EXCLUDED		Government, roadways and parking					EXCLUDED
		Government, sidewalks and curbs					EXCLUDED

GOVERNMENT EXCLUSIONS

- Government Exclusions. We have assumed that some of the improvements installed on property owned by the Association will be maintained by the state, county, or local government, or other association or other responsible entity. Examples of items excluded from funding by Replacement Reserves by this standard are listed above.
- Excluded rights-of-way, including adjacent properties and adjacent roadways.
- The list above exemplifies exclusions by the cited standard(s) and is not intended to be comprehensive.

INTENTIONALLY LEFT BLANK

November 11, 2025

SECTION C - CALENDAR OF PROJECTED ANNUAL REPLACEMENTS

GENERAL STATEMENT. The 21 Projected Replacements in the Sample High Rise - Skyclub Replacement Reserve Inventory whose replacement is scheduled to be funded from Replacement Reserves are broken down on a year-by-year basis, beginning on Page C3.2.

REPLACEMENT RESERVE ANALYSIS AND INVENTORY POLICIES, PROCEDURES, AND ADMINISTRATION

- **REVIEW OF THE REPLACEMENT RESERVE STUDY.** For this study to be effective, it should be reviewed by the Board of Directors, those responsible for the management of the items included in the Replacement Reserve Inventory, and the accounting professionals employed by the Association.
- **REVISIONS.** Revisions will be made to the Replacement Reserve Analysis and Replacement Reserve Inventory in accordance with the written instructions of the Board of Directors. No additional charge is incurred for the <u>first</u> revision if requested in writing within three months of the date of the Replacement Reserve Study. It is our policy to provide revisions in electronic (Adobe PDF) format only. We acknowledge that there are instances in which multiple revisions are necessary. However, unnecessary multiple revisions drain our time and manpower resources. Therefore, MillerDodson will exercise its sole discretion as to whether additional charges are incurred.
- TAX CODE. The United States Tax Code grants favorable tax status to a common interest development (CID) meeting certain guidelines for their Replacement Reserve. If a CID files their taxes as a 'Corporation' on Form 1120 (IRC Section 277), these guidelines typically require maintenance activities, partial replacements, minor replacements, capital improvements, and one-time-only replacements to be excluded from Reserves. A CID cannot co-mingle planning for maintenance activities with capital replacement activities in the Reserves (Revenue Ruling 75-370). Funds for maintenance activities and capital replacement activities must be held in separate accounts. If a CID files taxes as an "Exempt Homeowners Association" using Form 1120H (IRC Section 528), the CID does not have to segregate these activities. However, because the CID may elect to change their method of filing from year to year within the Study Period, we advise using the more restrictive approach. We further recommend that the CID consult with their Accountant and consider creating separate and independent accounts and reserves for large maintenance items, such as painting.
- CONFLICT OF INTEREST. Neither MillerDodson Associates nor the Reserve Analyst has any prior or existing
 relationship with this Association which would represent a real or perceived conflict of interest.
- **RELIANCE ON DATA PROVIDED BY THE CLIENT.** Information provided by an official representative of the Association regarding financial, physical conditions, quality, or historical issues is deemed reliable.
- **INTENT.** This Replacement Reserve Study is a reflection of the information provided by the Association and the visual evaluations of the Analyst. It has been prepared for the sole use of the Association and is not for the purpose of performing an audit, quality/forensic analyses, or background checks of historical records.
- **PREVIOUS REPLACEMENTS.** Information provided to MillerDodson Associates regarding prior replacements is considered to be accurate and reliable. Our visual evaluation is not a project audit or quality inspection.
- EXPERIENCE WITH FUTURE REPLACEMENTS. The Calendar of Annual Projected Replacements, lists replacements we have projected to occur over the Study Period and begins on Page C2. Actual experience in replacing the items may differ significantly from the cost estimates and time frames shown because of conditions beyond our control. These differences may be caused by maintenance practices, inflation, variations in pricing and market conditions, future technological developments, regulatory actions, acts of God, and luck. Some items may function normally during our visual evaluation and then fail without notice.

November 11, 2025

Item 2027 - YEAR 1	\$
Item 2027 - YEAR 1	\$
No Scheduled Replacements	¢
	\$
	\$
No Scheduled Replacements	
Item 2033 - YEAR 7	\$
No Scheduled Replacements	
1tem 2035 - YEAR 9 7 Throw rugs 14 Window Coverings	\$ \$1,240 \$6,100 \$7,340
	Item 2029 - YEAR 3 No Scheduled Replacements Item 2031 - YEAR 5 No Scheduled Replacements Item 2033 - YEAR 7 No Scheduled Replacements

	PROJECTED RI	EPLACEMENTS	
Item 2036 - YEAR 10	\$	Item 2037 - YEAR 11	\$
No Scheduled Replacements		No Scheduled Replacements	
Item 2038 - YEAR 12 No Scheduled Replacements	\$	Item 2039 - YEAR 13	\$
No Scheduled Replacements		No Scheduled Replacements	
Item 2040 - YEAR 14 1 Tile Floor, tuckpoint, 20% 5 Wood Panels, wall covering 6 Wood Doors 8 Bathroom Renovations 15 Furniture, soft goods 18 Flat panel TV - 80" screen 19 Heat Pump, 60k BTU 21 Recessed ceiling & track lights	\$ \$1,043 \$1,680 \$4,125 \$13,000 \$5,300 \$4,500 \$4,800 \$6,300	Item 2041 - YEAR 15 11 Millwork 12 Wine Storage Cabinets 16 Furniture, hard goods	\$ \$1,500 \$2,600 \$11,000
Total Scheduled Replacements	\$40,748	Total Scheduled Replacements	\$15,100
Item 2042 - YEAR 16 3 Carpet	\$ \$7,200	Item 2043 - YEAR 17 4 Sliding Glass Doors, single	\$ \$7,000
Total Scheduled Replacements	\$7,200	Total Scheduled Replacements	\$7,000
Item 2044 - YEAR 18 9 Kitchen Renovation 10 Kitchen Appliances	\$ \$5,500 \$1,050	Item 2045 - YEAR 19 20 Exhaust Fan	\$ \$1,200
Total Scheduled Replacements	\$6,550	Total Scheduled Replacements	\$1,200

PR	OJECTED RI	EPLACEMENTS
Item 2046 - YEAR 20 13 Wine Storage Cabinets (new)	\$ \$2,600	Item 2047 - YEAR 21 \$
17 Pool Table	\$5,500	
Total Scheduled Replacements	\$8,100	No Scheduled Replacements
Item 2048 - YEAR 22 18 Flat panel TV - 80" screen	\$ \$4,500	Item 2049 - YEAR 23 \$
Total Scheduled Replacements	\$4,500	No Scheduled Replacements
Item 2050 - YEAR 24	\$	Item 2051 - YEAR 25 \$
1 Tile Floor, tuckpoint, 20% 2 Tile Floor, replace	\$1,043 \$28,536	
7 Throw rugs	\$1,240	
14 Window Coverings	\$6,100	
15 Furniture, soft goods	\$5,300	
Total Scheduled Replacements	\$42,219	No Scheduled Replacements
Item 2052 - YEAR 26 3 Carpet	\$ \$7,200	Item 2053 - YEAR 27 \$
Total Scheduled Replacements	\$7,200	No Scheduled Replacements
Item 2054 - YEAR 28	\$	Item 2055 - YEAR 29 \$
No Scheduled Replacements		No Scheduled Replacements

Total Scheduled Replacements

November 11, 2025

PROJECTED REPLACEMENTS			
	2056 - YEAR 30 chen Appliances t panel TV - 80" screen	\$ \$1,050 \$4,500	Item 2057 - YEAR 31 \$
Total Scheduled Replacements \$5,550		\$5,550	No Scheduled Replacements
Item	2058 - YEAR 32	\$	Item 2059 - YEAR 33 \$
No Scheduled Replacements			No Scheduled Replacements
5 Wo 6 Wo 8 Ba 15 Fu 19 He	2060 - YEAR 34 e Floor, tuckpoint, 20% ood Panels, wall covering ood Doors throom Renovations rniture, soft goods at Pump, 60k BTU cessed ceiling & track lights	\$ \$1,043 \$1,680 \$4,125 \$13,000 \$5,300 \$4,800 \$6,300	Item 2061 - YEAR 35 \$
Total Scheduled Replacements \$36,248		\$36,248	No Scheduled Replacements
11 Mil 12 Wi	2062 - YEAR 36 rpet lwork ne Storage Cabinets rniture, hard goods	\$ \$7,200 \$1,500 \$2,600 \$11,000	Item 2063 - YEAR 37 \$
Total Scheduled Replacements \$22,300		\$22,300	No Scheduled Replacements
Item 18 Fla	2064 - YEAR 38 t panel TV - 80" screen	\$ \$4,500	Item

\$4,500

Total Scheduled Replacements

\$7,340

INTENTIONALLY LEFT BLANK

Sample High Rise

November 11, 2025

SECTION D - CONDITION ASSESSMENT

General Comments. MillerDodson Associates conducted a Reserve Study at Sample High Rise - Skyclub in December 2020. Sample High Rise - Skyclub is in generally excellent condition for a residential condominium constructed in 2010. A review of the Replacement Reserve Inventory will show that we are anticipating most of the components achieving their normal economic lives.

SkyClub - For the SkyClub all interior finishes are included to include furniture, pool table, and a flat-screen TV. Sliding glass doors to balconies along with window coverings are included. Renovations to bathrooms and the kitchen area are included. Also included are the mechanical fan coil unit, exhaust fan, and lighting for the Skyclub.

The following comments pertain to the larger, more significant components in the Replacement Reserve Inventory and to those items that are unique or deserving of attention because of their condition or the manner in which they have been treated in the Replacement Reserve Analysis or Inventory.

IMPORTANT NOTE: This Condition Assessment is based upon visual and apparent conditions of the common elements of the community which were observed by the Reserve Analyst at the time of the site visit. This Condition Assessment does not constitute, nor is it a substitute for, a professional Structural Evaluation of the buildings, amenities, or systems. MillerDodson strongly recommends that the Association retain the services of a Structural Engineer to conduct thorough and periodic evaluations of the buildings, balconies, and any other structural components of the buildings and amenities of the Association.

General Condition Statements.

Excellent. 100% to 90% of Normal Economic Life expected, with no appreciable wear or defects.

Good. 90% to 60% of Normal Economic Life expected, minor wear or cosmetic defects found. Normal maintenance should be expected. If performed properly, normal maintenance may increase the useful life of a component. Otherwise, the component is wearing normally.

Fair. 60% to 30% of Normal Economic Life expected moderate wear with defects found. Repair actions should be taken to extend the life of the component or to correct repairable defects and distress. Otherwise, the component is wearing normally.

Marginal. 30% to 10% of Normal Economic Life expected, with moderate to significant wear or distress found. Repair actions are expected to be cost-effective for localized issues, but normal wear and use are evident. The component is reaching the end of the Normal Economic Life.

Poor. 10% to 0% of Normal Economic Life expected, with significant distress and wear. Left unattended, additional damage to underlying structures is likely to occur. Further maintenance is unlikely to be cost-effective.

(Continued on next page)

Sample High Rise November 11, 2025

INTERIOR ITEMS

Tile Floors. Tile floors are found in the 1st floor and 9th-floor lobbies and in the elevator lobbies on the 1stthrough 9th floors. Tile flooring and walls can also be found in the common restrooms. These floors walls have an extended life but may need occasional regrouting of joints. A full replacement has been included to allow for replacement due to failure or to allow for changes in the décor.

Carpet. Carpet in the common areas is found in the hallways, lounges, media room, and the fitness center. The carpet was installed as large carpet tiles. This does allow for easy replacement should an area be damaged or stained. The carpet will still have a useful life of about 10 years. Since it would be difficult to replace the hallway carpet on 33 floors all in one year this work has been broken into a 5 year period where either 6 or 7 floors would be done in a year and the work would coincide with the fabric wall covering for that floor.










Glass Sliding Glass Door. The sliding glass door has some of the same features and failure problems and the glass exterior, but they also fail at the track system which allows them to move and operate. The study assumes that ten percent of the sliding glass doors will fail and be replaced in 5 year intervals.

Sample High Rise November 11, 2025









Fan Coil Units. HVAC to the lounges, media center, fitness center, and electrical rooms is provided by multiple heat pump style FCUs. The FCUs are located above the ceiling of all common spaces except the electrical rooms. The FCUs use the condenser water from the cooling towers or flat-plate heat exchangers with an internal DX heating cooling compressor and coil to either heat or cool the space.

Sample High Rise November 11, 2025





Exhaust Fans. Numerous large fans provide exhaust from the hallways, elevator shafts, and other common areas. There are also exhaust fans for the public restrooms.

This Condition Assessment is based upon our visual survey of the property. The sole purpose of the visual survey was an evaluation of the common and limited common elements of the property to ascertain their remaining useful life and replacement cost. Our evaluation assumed that all components met building code requirements in force at the time of construction. Our visual survey was conducted with care by experienced persons, but no warranty or guarantee is expressed or implied.

End of Condition Assessment

INTENTIONALLY LEFT BLANK

1. COMMON INTEREST DEVELOPMENTS - AN OVERVIEW

Over the past 40 years, the responsibility for many services, facilities, and infrastructure around our homes has shifted from the local government to Community Associations. Thirty years ago, a typical new townhouse abutted a public street on the front and a public alley on the rear. Open space was provided by a nearby public park, and recreational facilities were purchased ala carte from privately owned country clubs, swim clubs, tennis clubs, and gymnasiums. Today, 60% of all new residential construction, i.e., townhouses, single-family homes, condominiums, and cooperatives, is in Common Interest Developments (CID). In a CID, a homeowner is bound to a Community Association that owns, maintains, and is responsible for periodic replacements of various components that may include the roads, curbs, sidewalks, playgrounds, streetlights, recreational facilities, and other community facilities and infrastructure.

The growth of Community Associations has been explosive. In 1965, there were only approximately 500 Community Associations in the United States. According to the 1990 U.S. Census, there were roughly 130,000 Community Associations. The Community Associations Institute (CAI), a national trade association, estimated in 2020 that there were more than 350,000 communities with over 75 million residents.

The shift of responsibility for billions of dollars of community facilities and infrastructure from the local government and private sector to Community Associations has generated new and unanticipated issues. Although Community Associations have succeeded in solving many short-term issues, many Associations still fail to properly plan for the significant expenses of replacing community facilities and infrastructure components. When inadequate Replacement Reserve funding results in less than timely replacements of failing components, homeowners are invariably exposed to the burden of special assessments, major increases in Association fees, and often a decline in property values.

2. REPLACEMENT RESERVE STUDY

The purpose of a Replacement Reserve Study is to provide the Association with an inventory of the common community facilities and infrastructure components that require periodic major repair or replacement, a general view of the physical condition of these components, and an effective financial plan to fund projected periodic replacements or major repairs. The Replacement Reserve Study consists of the following:

Replacement Reserve Study Introduction. The introduction provides a description of the property, an Executive Summary of the Funding Recommendations, Level of Reserve Study service, and a statement of the Purpose of the Replacement Reserve Study. It also lists documents and site evaluations upon which the Replacement Reserve Study is based and provides the Credentials of the Reserve Analyst.

Section A Replacement Reserve Analysis. Many components that are owned by the Association have a limited life and require periodic replacement. Therefore, it is essential that the Association have a financial plan that provides funding for the timely replacement of these components in order to protect the safety, appearance, and ultimately, the property value of the homes in the community. In conformance with National Reserve Study Standards, a Replacement Reserve Analysis evaluates the current funding of Replacement Reserves as reported by the Association and recommends annual funding of Replacement Reserves using the Threshold Cash Flow Method. See the definition below.

Section B Replacement Reserve Inventory. The Replacement Reserve Inventory lists the commonly owned components within the community that require periodic replacement using funding from Replacement Reserves. Replacement Reserve Inventory includes estimates of the Normal Economic Life (NEL) and the Remaining Economic Life (REL) for those components whose replacement is scheduled for funding from Replacement Reserves.

The Replacement Reserve Inventory also provides information about those components that are excluded from the Replacement Reserve Inventory and whose replacement is not scheduled for funding from Replacement Reserves.

Section C Projected Annual Replacements. The Calendar of Projected Annual Replacements provides a year-by-year listing of the Projected Replacements based on the data in the Replacement Reserve Inventory.

Section D Condition Assessment. The observed condition of the major items listed in the Replacement Reserve Inventory is discussed in more detail. The Condition Assessment includes a narrative and photographs that document conditions at the property observed at the time of our visual evaluation.

The Appendix is provided as an attachment to the Replacement Reserve Study. Additional attachments may include supplemental photographs to document conditions at the property and additional information specific to the property cited in the Conditions Assessment (i.e., Consumer Product Safety Commission, Handbook for Public Playground Safety, information on segmental retaining walls, manufacturer recommendations for asphalt shingles or siding, etc.).

3. METHODS OF ANALYSIS

The Replacement Reserve industry generally recognizes two different methods of accounting for Replacement Reserve Analysis, the Cash Flow Method. Due to the difference in accounting methodologies, these methods lead to different calculated values for the Recommended Annual Funding to the Reserves. A brief description is included below:

Cash Flow Threshold Method. This Reserve Study uses the Threshold Cash Flow Method, sometimes referred to as the "Pooling Method." It calculates the minimum constant annual funding to reserves (Minimum Annual Deposit) required to meet projected expenditures without allowing total reserves on hand to fall below the predetermined Minimum Balance, or Threshold, in any year.

4. REPLACEMENT RESERVE STUDY DATA

Identification of Reserve Components. The Reserve Analyst has only two methods of identifying Reserve Components; (1) information provided by the Association and (2) observations made at the site. The Reserve Analyst must be provided with all available information detailing the components owned by the Association. It is our policy to request such information prior to bidding on a project and to meet with the parties responsible for maintaining the community after acceptance of our proposal. Upon submission of the Initial Study, the Study should be reviewed by the Board of Directors and the individuals responsible for maintaining the community. We depend upon the Association for correct information, documentation, and drawings. We also look to the Association representative to help us fashion the Reserve Study so that it reflects what the community hopes to accomplish in the coming years.

Unit Costs. Unit costs are developed using nationally published standards and estimating guides and are adjusted by state or region. In some instances, recent data received in the course of our work is used to modify these figures. Contractor proposals or actual cost experience may be available as part of the Association records. This is useful information, which should be incorporated into your report. Please bring any such available data to our attention, preferably before the report is commenced.

Replacement vs. Repair and Maintenance. A Replacement Reserve Study addresses the required funding for Capital Replacement Expenditures. This should not be confused with operational costs or the cost of regular repairs or maintenance.

5. DEFINITIONS

Adjusted Cash Flow Analysis. Cash flow analysis adjusted to take into account annual cost increases due to inflation and interest earned on invested reserves. In this method, the annual contribution is assumed to grow annually at the inflation rate.

Cash Flow Analysis. See the Cash Flow Threshold Method, above.

Contingency. An allowance for unexpected requirements. The "Threshold" used in the Cash Flow Method is a predetermined minimum balance that serves the same purpose as a "contingency." However, IRS Guidelines do not allow for a "contingency" line item in the inventory. Therefore, it is built into the mathematical model as a "Threshold."

Cyclic Replacement Item. A component item that typically begins to fail after an initial period (Estimated Initial Replacement), but which will be replaced in increments over a number of years (the Estimated Replacement Cycle). The Reserve Analysis program divides the number of years in the Estimated Replacement Cycle into five equal increments. It then allocates the Estimated Replacement Cost equally over those five increments. (As distinguished from Normal Replacement Items, see below)

Estimated Normal Economic Life (NEL). Used in the Normal Replacement Schedules. This represents the industry average number of years that a new item should be expected to last until it has to be replaced. This figure is sometimes modified by climate, region, or original construction conditions.

Estimated Remaining Economic Life (REL). Used in the Normal Replacement Schedules. Number of years until the item is expected to need replacement. Normally, this number would be considered to be the difference between the Estimated Economic Life and the age of the item. However, this number must be modified to reflect maintenance practice, climate, original construction, quality, or other conditions. For the purpose of this report, this number is determined by the Reserve Analyst based on the present condition of the item relative to the actual age.

Minimum Annual Deposit. Shown on the Summary Sheet A1. The calculated requirement for annual contribution to reserves is calculated by the Cash Flow Method (see above).

Minimum Balance. Otherwise referred to as the Threshold, this amount is used in the Cash Flow Threshold Method only. Normally derived using the average annual expenditure over the study period, this is the minimum amount held in reserves in the Peak Year.

Overview, Standard Terms, and Definitions

National Reserve Study Standards. A set of Standards developed by the Community Associations Institute in 1995 (and updated in 2017) which establishes the accepted methods of Reserve Calculation and stipulates what data must be included in the Reserve Study for each component listed in the inventory. These Standards can be found at CAlonline.org.

Normal Replacement Item. A component of the property that, after an expected economic life, is replaced in its entirety. (As distinguished from Cyclic Replacement Items, see above.)

Number of Years of the Study. The number of years into the future for which expenditures are projected and reserve levels calculated. This number should be large enough to include the projected replacement of every item on the schedule, at least once. The Reserve Study must cover a minimum of 20 years to comply with the National Reserve Study Standards. However, your study covers a 40-year period.

Peak Year. In the Cash Flow Threshold Method, a year in which the reserves on hand are projected to fall to the established threshold level. See Minimum Balance, above.

Reserves Currently on Deposit. Shown on the Summary Sheet A1, this is the amount of accumulated reserves as reported by the Association in the current year.

Replacement Reserve Study. An analysis of all of the components of the common property of a Community Association for which replacement should be anticipated within the economic life of the property as a whole. The analysis involves estimation for each component of its Estimated Replacement Cost, Normal Economic Life, and Remaining Economic Life. The objective of the study is to calculate a Recommended Annual Funding for the Association's Replacement Reserve Fund.

Total Replacement Cost. Shown on the Summary Sheet A1, this is total of the Estimated Replacement Costs for all items on the schedule if they were to be replaced once.

Unit Replacement Cost. Estimated replacement cost for a single unit of a given item on the schedule.

Unit (of Measure). Non-standard abbreviations are defined on the page of the Replacement Reserve Inventory where the item appears. The following standard abbreviations are used in this report:

ea each Is lump sum sy square yard ft or If linear foot pr pair cy cubic yard sf square foot

What is a Reserve Study? Who are we?



https://youtu.be/m4BcOE6q3Aw

Who conducts a Reserve Study? Reserve Specialist (RS) what does this mean?



https://youtu.be/pYSMZO13VjQ

What's in a Reserve Study and what's out? Improvement/Component, what's the difference?



https://youtu.be/ZfBoAEhtf3E

What kind of property uses a Reserve Study?
Who are our clients?



https://youtu.be/40SodajTW1g

When should a Reserve Study be updated? What are the different types of Reserve Studies?



https://youtu.be/Qx8WHB9Cgnc

What is my role as a Community Manager? Will the report help me explain Reserves?



https://youtu.be/1J2h7FIU3gw

What is my role as a community Board Member? Will a Reserve Study meet my needs?



https://youtu.be/aARD1B1Oa3o

How do I read the report?
Will I have a say in what the report contains?



https://youtu.be/qCeVJhFf9ag

How are interest and inflation addressed? Inflation, what should we consider?




https://youtu.be/W8CDLwRIv68

Community dues, how can a Reserve Study help? Will a study keep my property competitive?



https://youtu.be/diZfM1IyJYU

Where do the numbers come from? Cumulative expenditures and funding, what?



https://youtu.be/SePdwVDvHWI

A community needs more help, where do we go? What is a strategic funding plan?



https://youtu.be/hlxV9X1tlcA